




__






.

Z




7


. .




ī




.






. . .

æ



CS-D/N 9 1/0 mother 9560 Beard 9560 8 bit both bus Muy Ewi ટરરકલ્ક 55518 2200(7715)



To: Merle McIntosh

From: Rich Leis/Jack Kelley

Subj: 2200 CPU Test Capacity

Date: 2/21/90

Our memo of 2/9/90 stressed the need for additional output of the CPU boards (212-7129-A/B/C/D). On the memo was a matrix of the needs of each board type. The total of all boards was 159 pcs with a demand window through 2/23/90. This is an update to that memo reflecting the output of those boards.

Of the 159 boards needed through 2/23 Ed Bradley and his people have output 128. The Hotlist has virtually been eliminated and we are nearly on schedule with kitting. This past weekends performance (resulting in a yield of 49 boards) took us out of the backlog/scrambling situation. A new matrix is attached to show the needs through 3/16 by board type.

The demand for these boards through 3/16 is as follows:

!	SPEC:	I AL	PRODUCTS	!		!	2200 KIT	PUERTO	RICO NEEDS	!		!	REVISED
!	LIST	<u>.</u>	SCHEDULE	<u>.</u>	_CE_	!	SHORTS	<u> </u>	SCHEDULE	<u>.</u>	TOTAL	. I'	TOTAL**
212-7129-A!	5	!	12	!	8	!	18	!!!	47	!	90	!	77
-B!	3	!	8	!	9	į	=	!	O	!	25	!	11
-C!	0	!	4	!	9	!	8	!	0	!	21	!	10
-D!	0	!	8	!	12	!	0	!	Q	!	20	ŧ	9
TOTAL	!	8	! 3:	2	!	38	} !	44	. 47		!	!	*
									GRAND TOT	AL	! 156	. !	107 **

** The 49 pc output of 2/20 has not been applied to specific kits or hot list needs as of this writing so it's merely netted out at the end.

cc: B. Dorazio

P. Martell

G. Terris

S. Nichols

F. Stec

E. Bradley

S. Anthony

$\frac{\texttt{TMD DISTRIBUTION FOR 2200 CS-386}}{\texttt{MODEL 210-9561 C-D}} \\ \frac{\texttt{MODEL 210-9561 C-D}}{\texttt{TMD\# 2415}}$

D.	Aldrich	018-28C
K.	Azar	018-27C
R.	Bator	018-211
K.	Bean	018-26F
P.	Doris	015-17B
R.	Downing	018-27C
D.	Eno	019-490
D.	Foley	018-28B
D.	Heiner	018-211
D.	Jarry	018-25A
J.	Manion	018-18D
D.	Monahan	018-27C
К.	Morman	018-17D
В.	O'Connor	018-G1F
J.	O'Hara	018-26C
	Pestana	018-25E
	Proulx	012-190
	Quigley	018-18A
	Seto	· 018-26F
	Spera	018-15A
	Sutton	018-27C
	Todd	018-G1C
	Tudisco	018-26C
	Tyler	024-290
T.	Zacher	018-G1B
SIGNEES:S.	Anthony	018-25D
	Hondras	018-27B
CC:T.	LaMonica	018-28G
	Prudencio	018-28F
_ •		



TEMPORARY MANUFACTURING DEVIATION

Originator	Date 3////C	M/S (*/\/->\)(Ext. Ref. TMD		
Part Number	Description	- 186	Mode 1 2200 CS:386		
ECO Pending?	If yes, ECO#	ECO REQ'D	Temporary Change Only		
SWO or CWO Number		SWO or CWO Quantity			
Effectivity Date	190	Expiration # //4	Pate 90		
Affected Areas					
Quantity					

Completely describe deviation including instructions for rework, assembly and test, etc. Include drawings and visual aids as necessary.

Restrict Vendor N.F.C CANCETSON 4518

From Locations LIC, LIB LIY, LRS LB) LOLLYZ

CND LYS

NEC+MC-40100A9B-10 Cause 100% Fail re

Add to Compension Restriction hist

at In Systems test come these parts

Quality Control

Date

Resident Comp. Eng.

Date

Material Control

Date

CATA

Date

Operations Manager

Date

Mfg. Engineering

Date

Mfg. Engineering

Date

Mfg. Engineering

Date

cc: T. La Monica R. Downing L. Prudencis Ken Blan

$\frac{\text{TMD DISTRIBUTION FOR 2200 CS-386}}{\text{MODEL 210-9561 A-D}} \\ \frac{\text{MODEL 210-9561 A-D}}{\text{TMD}\#^2~2414}$

K. R:	Aldrich Azar Bator Bean	018-28C 018-27C 018-21I 018-26F
		015-17B
	Downing	018-27C
	Eno	019-490
D.	Foley	018-28B
_ D.	Heiner	018-211
. D.	Jarry	018-25A
	Manion	018-18D
D.	Monahan	018-27C
к.	Morman	018-17D
	O'Connor	018-G1F
	O'Hara	018-26C
	Pestana	018-25E
	Proulx	012-190
	Quigley	018-18A
	Seto	018-26F
	Spera	018-15A
	Sutton	018-27C
	Todd	018-G1C
	Tudisco	018-26C
	Tyler	024-290
T.	Zacher	018-G1B
SIGNEES:S.	Anthony	018-25D
J.	Hondras	018-27B
	Hamel	018-28G
L.	Prudencio	018-28F

TEMPORARY-MANUFACTURING DEVIATION =

The state of the s

Originator: STEVE ANTHONY	S/1/90	M/S- 018-250	Ext. Ref. TMD.		
Past Number 210 - 9561 A=0	Description 2200 CS-		Mode l		
ECO: Pending?: //O	if≅yes; Eco#≢	ECO REQ'D	Temporary Change Only		
SW92 or CW9. Number		SWO or CWO			
Effectivity Dates 3/1/90		Expiration	0 ate		
Affected KITTING ROOM	EPIC				
Quantity					

Completely described deviation including instructions for rework, assembly and test, etc. Include drawings and visual aids as necessary.

DUE TO EXCESSIVE FAICURES IN THE IN-SUAMS TEST AREA, RESTRICT VENDOR MMI PAC WPN 377-3774 AND 377-3776 FROM PCB COCATIONS L 44 AND LGZ. ACC OTHER WICK WORK IN THESE LOCATIONS.

Quality Control Date Resident Comp. Eng. Date

Material Control Date CATA- Date

APPROVALS

Operations Manager Date

Mfg Engineering

Date 3/1/90

all and an armine and area

TEMPORARY MANUFACTURING DEVIATION

Originator STEVE ANTHONY	Pater 3/1/90	M/S: 018-250	64478	Ref. TMD	
Pant Number 210 - 9561 A-0	Description CS-386		Mode 1		
ECO Pending?. NO	If yes, Eco#	ECO: REQ'D			
SWO or CWO Number		SWOor- CWO			
Effectivity Date: 3/1/90		Expiration	Date- 4 /4/90		
Affected KITHUR ROOM	EPIC E				
Quantity					

Completely describe deviation including instructions for rework, assembly and test, etc. Include drawings and visual aids as necessary.

DUE TO EXCESSIVE FAICURES IN THE IN-SULANS TEST AREA, RESTRICT VENDOR MMI PAC WPN 377-3774 AND 377-3776 FROM PCB LOCATIONS LYY AND LGZ. ALL OTHER WILL WORK IN THESE LOCATIONS.

	AF	PROVALS	
Quality Control	Date	Resident Comp. Eng.	Date
Material Control	Date	CATA	Date
Operations Manager	Date ./1/95	Mfg, Engineering Inthon	Date 3/1/90

Diagnostic Program Documentation

Documentation Release:

Software Release:

69C1

Documentation Part Number: 760-1209D

Program Name:

2200 Multiple Disk Exerciser

Date:

December 18, 1989

. Table of Contents

1.0 Reference Documentation

2.0 Configuration Requirements

3.0 Program Description

4.0 Load Procedures

5.0 Operating Instructions

6.0 Miscellaneous

7.0 Program Revision History

Appendix A

Appendix B

Appendix C

Diagnostic Engineering Department WANG Laboratories, INC. One Industrial Ave. Lowell, Massachusetts 01851

1.0 REFERENCE DOCUMENTS

2200 Multiple Disk Exerciser

2.0 CONFIGURATION REQUIREMENTS

2.1 Hardware

Minimum required configuration

2200 with the minimum required configuration

Soft-sectored diskettes are not supported on 2270A controllers

2236DE/DW or equivalent terminal

If a printer is used, it must have a column width of at least 66 characters

2.2 Software

MVP CPU software must be rev. 1.8 or higher

VP CPU software must be rev. 2.1 or higher

Media containing the 2200 Multiple Disk Exerciser which is labeled: MULTIDSK

3.0 PROGRAM DESCRIPTION

The 2200 Multi-Disk Exerciser is a disk burn-in/exerciser with error logging capabilities. The exerciser tests eight sequential sectors for each random selection of; function, disk address and sector address.

4.0 LOAD PROCEDURES

4.1 Load directly from disk

- 1) Select the device address with a 'SELECT DISK ###' statement (see note 1)
- 2) Input command 'LOAD RUN "MULTIDSK"'

4.2 Load from 2200 Diagnostic Package

- 1) Select the device address with a 'SELECT DISK ###' statement (see note 1)
- 2) Input command 'LOAD RUN'
- 3) If 'MAGNETIC MEDIA' disk proceed with step 4
 Under '2200 DIAGNOSTIC PACKAGE' menu, select 'Magnetic Media'
- 4) Under 'MAGNETIC MEDIA' menu, select 'Disk Exercisers'
- 5) Under 'DISK EXERCISERS' menu, select 'Multiple Disk Exerciser'

Note 1: (### equals the device address where program resides)

5.0 OPERATING INSTRUCTIONS

5.1 Description of Operation

The first two screens of the exerciser require operator input to select the processes, the function, and amount of testing. The third screen displays the functions running, device being tested, number of errors, and the number of accesses that have been completed. When inputs are needed, it is indicated and all the options are listed at the bottom of the screen.

7.2 Screen Descriptions

On each screen, lines:

- a) 20 and 21 will describe any status or error information.
- b) 22 and 23, (in box), describe all input/command options for the current screen.

7.3 Procedures

- 1) For the exercisers set up procedure and screens see Appendix A.
- 2) For a description of the run time screen see Appendix B.
- 3) For a description of standard input and command options see Appendix C.

6.0 MISCELLANEOUS

6.1 Definitions

- <u>Hard error</u> A disk operation that failed during normal testing and would not successfully execute during ten retries.
- Soft error

 A disk operation that failed during normal testing and was successfully executed in less than eleven retries. Also a data compare error is considered a soft error.

· .**

7.0 PROGRAM REVISION HISTORY

Rev 69C1:

This Revision corrects the problem running multi disk diagnostics with the 386 Board.

The software has been patched to permenantly circumvent the error message "CPU SOFTWARE MUST BE UPGRADED TO RUN THIS PROGRAM".

Rev. 6735:

Added support for 2200DS and RAM Disk. Also fixed time out errors on long cabled mux.

Rev. 64A4:

Added a routine to zero the sector to R/A/W test so intermittent write problems would show up.

Removed the zero retries function.

Added the 30 MEG to the 2275.

Rev. 6441:

Corrected counter problem during init read and write.

Rev. 639C:

The 2275 option (Winchester and 5 1/4" floppy disk) have been added to the list of recognizable devices.

The screening has been made more user friendly. This will speed up the time it takes to initiate the test and also made it easier to understand.

Rev. 61B4:

The Quantum drives have been added to the list of recognizable devices. Since the Quantum Q2040 responds to two addresses it is treated as two separate devices.

Rev. 61A4:

Firmware retries on error are now suppressed on Disk Processing Unit's that have the ability.

Rev. 1.1:

Sector write backfill is now randomly selecting worst case data patterns.

APPENDIX A

THIS EXERCISOR WILL RENDER ALL RESIDENT DATA IN THE RANGE OF THE IMPORTANT: SELECTED SECTORS INVALID AND TOTALLY USELESS.

A.1 INITIAL INPUT and SCREEN

- The operator is instructed to mount platters in all the drives that are to be tested. For a device to be testable it must:
 - a) have a <u>scratch</u> platter mounted.
 - b) not be write protected.
 - c) be operable enough for the address to be recognized as available.
- Press 'RUN' or 'RETURN' and the program will scan all the possible disk addresses. The routine tries to ascertain what types of devices are at what addresses and reports this information on the Test and Parameter Select screen.
- NOTE: If desired the default parmeters can be altered by pressing SF'2 and then editing to the desired parmeters (as described by appendix A.2). These parmeters will then be inserted as the test parmeters. If a sector selected is out of range of a device then the parmeter used will be as close to the the altered default as possible.

TEST and PARAMETER SELECTION A.2

- A display of all devices available for testing is given with the following information:
 - a) test options
 - b) device address (see note 2)
 - c) model number
 - d) address of the first sector to be tested
 - e) address of the last sector to be tested
- Note 2: (If the address was recognized, but an error occurred, the error is printed to the left of the device address).
- 2 The user prompts are as follows:
 - A) "Are all the above parameters correct?"
 - 'N' (no), enters the edit mode, and 'CONT'/'CTNUE' will exit the edit mode. The option select menu may be edited using the following options:
 - a) Test 'yes' or 'no'

If no, then no functions will be run on that device. Format device?

'yes' or 'no' b) Frmt

A) (continued)

c)	Init '	yes' or 'no'	Initialize the device. Write a test pattern on every sector
d)	Ver '	yes' or 'no'	verify the device. Read the test pattern from every sector selected for test.
e)	Address	'xxx'	xxx=address of the device to be tested.
f)	Model	'xxxxxxx'	Model number. (not used in exerciser operation)
g)	Sec. Range	'xxxxx/yyyyy'	
h)	Accesses	'xxxxxxx'	Number of sectors to be read. Type infinite for infinite.

'Y' (yes) or 'CONT'/'CTNUE', then the system proceeds to the next prompt.

B) "To proceed type ENABLE WRITING "

instal led.

The operator <u>MUST</u> enter 'ENABLE WRITING' to proceed further. If the phrase has already been entered correctly, and the exerciser has not been returned to the first screen (A1), then the phrase will not be requested again and the exerciser will by-pass this prompt.

C) ""ARNING! All resident data will be DESTROYED by this exercise'"

This is the final step and warning before any WRITING is done.

Ensure that all devices to be tested have scratch media

Depressing CONT/CTNUE will start the exerciser.

A.3 Miscellaneous

- 1 No further operator commands are needed UNLESS:
 - a) An error occurs during format, at which time the exerciser will have to be restarted.
 - b) A format is requested on a device that can't be software formatted.
- 2 If an error occurs during Init, then the device is eliminated from the test and the exerciser continues.
- 3 The model descriptions of the drives are as follows;

```
850 DSDD
          - Double Sided Double Density floppy
1000
          - internal winchester
1002
          - internal winchester
1004
          - internal winchester
02040
          - internal winchester
          - internal winchester
Q2020
2200DS RAMD- 2200 Data Storage Cabinit ram disk
2200DS FLPk- 2200 Data Storage Cabinit 320/360k floppy
2200DS FLPm- 2200 Data Storage Cabinit 1.2 meg floppy
2200DS WINr- 2200 Data Storage Cabinit removable carterage winchester
2200DS WIN - 2200 Data Storage Cabinit winchester
          - external disk drive
2230-1
2260-1/2 - external disk drive
          - external disk drive
2260-1/4
2266
          - external disk drive
      WIN - 2275 winchester
2275
2275 FLPm- 2275 1.2 meg floppy
2275 FLPk- 2275 320/360k floppy
2270
          - external floppy drives
          - external floppy drives
2270a
          - external disk drive
2280
SYSTEM RAMD- System ram disk
```

APPENDIX B

The following screen/test descriptions are in the order in which they occur.

B.1 If no devices have been selected to test, then the following message will be displayed on line 20 and the exerciser will wait for a command.

"RECHECK PARAMETERS, NO DEVICES ARE SELECTED"

Pressing 'RETURN' or 'RUN' will cause the routine to return to the Test and Parameter Select Menu.

B.2 Format

- 1 If a device is selected for Test and Format, and:
 - a) It can be software formatted, then the following message will appear on line 22 and the format will begin.
 - " CHECK: to ensure that the device is formatting and the system isn't hung"
 - b) It can <u>not</u> be software formatted, then the exerciser will stop, print the following message on line 20, and will wait for a command.

"Press the format button for XXX" (where xxx is the device address to be formatted)

2 When all of the devices <u>requesting a format</u> are formatted, then the initialize and/or test routines will commence.

B.3 Run Screen

The run screen will be displayed with the following information of all the devices that are to being tested.

- a) the disk address
- b) the function (see note 3)
- c) the number of accessesd) the sector range being tested
- e) the number of hard errors (see note 4)
- f) the number of soft errors (see note 4)
- Note 3: The current function (if in process) or the last function (if not in process) processed. During init "w" or "r" is printed next to "init" to indicate whether reading or writing.
- Note 4: During init this column will stay blank. Init terminates testing of the device if an error is encountered.

The line containing the parameters of the device currently being processed is highlighted and the function updated, when applicable.

B.4 Initialization

A lower case 'w' appears to the right of the function name 1 Init (Init) while the media is being written.

> All disks sectors to be tested must be written, in the data field, with the current sector and disk addresses and then back-filled with a worst case data pattern.

- A lower case 'r' appears to the right of the function name 2 Ver (Init) while the media is being verified. Seek location is also checked whenever a read is performed.
 - A) If media verification was selected, all sectors to be tested are read. The sector and disk addresses written in the data field are compared with the current sector and disk addresses for equality (i.e., to see if the heads seek to the correct location).
 - B) If media verification was not selected, the first, middle and last sectors to be tested on the disks are verified.

B.5 Test

This is the exerciser portion of the "EXERCISER". The device, sector address, and function are reselected after eight sequential accesses.

- 1 All the devices selected for Test are assembled in a device list and the device to be tested is randomly selected.
- 2 The function is randomly selected from one of the following four:
 - a) VERIFY Verifies the sectors selected and reports controller detected errors.
 - b) READ Reads the selected sectors and checks that the correct data was read.
 - c) WRITE Writes the selected sectors with same information that Init does and will report controller detected errors.
 - d) R/A/W Writes the 8 sectors selected then immediately reads them and reports any errors.
- The sector address is randomly selected from within the range allowed by the test parameters. That address PLUS 7 are the eight sectors tested (the range of sectors allowed for test can vary up to eight greater than the maximum address selected in the test parameters but not more than the system allows).
- These parameters are combined, the test is run, and the above selection process is redone. Each device will be accessed (access = 1 sector R/A/W, READ, WRITE or VERIFY) as many times as was specified.

B.6 Error Recovery

- 1 Four types of errors can occur:
 - A) The first error is a hardware error. When a hardware error occurs the statement "CHECKING ERROR" appears at the top center of the screen. This statement remains while the program does up to ten retries of the current function on the failing sector and then reports the error.
 - B) The second type of error is a seek error (the disk and sector address read from the media, as written by Init, did not compare with the addresses requested). If this error is detected, the error is reported, counted as a soft error and the test continues.

- C) The third type of error is a data compare error (the data read from the disk didn't compare with the data that was expected from the disk, as written by Init). If this error is detected, the error is reported, counted as a soft error and the test continues.
- D) The fourth error is a format error. If an error occurred during a Format operation, then the exerciser will stop, report the error, and wait for another command.
- 2 Errors are reported with the device address, sector address, function that was being performed, and the type of error that occurred.
 - A) The last error that occurred is displayed on line 21 of the RUN SCREEN. If the screen has been changed (define an error or to change the page) then the error is not redisplayed, but new ones will be displayed when they occur.
 - B) Errors can be printed on either printer 204 or printer 215. If the printer is selected, 500 errors will be printed and then printing will cease, unless SF'14 (printer select key) is toggled or the exerciser screen is changed (to a different page or screen), but the screen error display will constantly update.

APPENDIX C

This is a description of the commonly used commands/inputs. All commands or inputs can be used when defined at the bottom of the screen (in the box).

SF'15/31 change the page. If there are more than 17 devices to

be listed, then at the top right corner of the screen "More" will be printed. This applies to the Parameter Select, Test and Run screens, if more than 17 devices

are available for testing.

<u>SF'O</u> "Define error l-xx" will be displayed. There is an

explanation of errors 1-90 through 1-99 in the "Exerciser". xx is the last error encountered or selected by the operator, if neither has occurred then default is 90. xx can be left or changed to select

90-99. When the explanation is displayed the

exerciser continues operation.

<u>RETURN</u> displays the explanation of the error selected.

SF'0 returns to the normal screen.

<u>SF'14</u> printer select. The currently selected printer option

is displayed in the upper left corner of each screen. To change selection press SF'14, the selected printer option will toggle between 204, 215, and off (no printer selected), until the desired option is

selected.

CLEAR/PREV SCRN Returns to the last functional screen or menu.

CONT/CTNUE These are general usage keys which cause a

RETURN or Y continuation to the next step.



REVIEW MEMORANDUM

Diagnostic Engineering Department

To:

Phil Doris, Darlene Ross, Henry Shinnagel, Mike Severin, Torry Hack

Date:

December 21, 1989

From:

Teri Emond

Doc:

DERLPRE93/VS6

Subject:

2200 Diagnostic Package, Rev. 2.00.00, Review

The 2200 Diagnostic Package, Rev. 2.00.00, is ready for review.

This review package p/n 195-2956-0/295-2956-0 includes the following:

Documentation:

2200 Diagnostic Package

760-0029E

2200 Multiple Disk Exerciser

760-1209D

Program Diskettes:

"ALL" 8" DSDD

2.00.00 732-0002J

Magnetic Media 8" SSSD Magnetic Media 5.25" DSDD

2.00.00 702-02920 2.00.00 732-8520A

This revision corrects the problem running Multi Disk diagnostics with the 386 board. The software has been patched to permanently circumvent the Error message "CPU SOFTWARE MUST BE UPGRADED TO RUN THIS PROGRAM"

There will be a meeting held on Monday, January 8, 1990 at 2:00 p.m. in the 6th floor conference room in Tower I, to determine the adequacy of this Diagnostic Package for release. If your review indicates a problem, please contact me immediately so that an attempt may be made to correct the problem prior to this meeting. At the time of the meeting, it will then be determined whether or not these problems can be or have been corrected to everyone's satisfaction. After this meeting, if the package is judged adequate for release, all further problems with it will be accepted only via Problem Reports.

cc: Paul Bencal Keith DeGiacomo Dan Horne Paul Phaneuf Debbie Querze Gail Stanwyck Al Woodruff Bill Zannini

Diagnostic Program Documentation

Software Releases:

Category	Disk Type	Part Number	Revision
AII	8" DSDD	732-0002J	2.00
Printers/Plotters/Terminals	8" SSSD	702-0295B	6591
	5-1/4" DSDD	732-0052B	6591
Magnetic Media	8" SSSD	702-0292C	2.00
	5-1/4" DSDD	732-8520A	2.00
Telecommunications	8" SSSD	702-0294	6436
, , , , , , , , , , , , , , , , , , , ,	5-1/4" DSDD	732-0051	6436
CPU/Memory test	8" SSSD	702-0293B	18A4
	5-1/4" DSDD	732-8521	18A4

NOTE

DSDD means Double-Sided Double-Density SSSD means Single-Sided Single-Density

Documentation Part Number: 760-00295

Package Part Number

19**5 2956**-0/295-2956-0D

ECO Number:

XXXXX

Program Name: 2200 Diagnostic Package

Date:

December 18, 1989

Table of Contents

- 1.0 Reference Documentation
- 2.0 Configuration Requirements
- 3.0 Program Description
- 4.0 Load Procedures
- 5.0 Operating Instructions
- 6.0 Miscellaneous

7.0 Program Revision History

Appendix A: Options for

Printers/Plotters/Terminals

Appendix B: Options for Magnetic Media Appendix C: Options for Telecommunications Appendix D: Options for CPU/Memory Test Appendix E: Explanation of Revision Numbers

Diagnostic Engineering Department WANG Laboratories, INC.
One Industrial Ave.
Lowell, Massachusetts 01851

1.0 REFERENCE DOCUMENTATION

Wang BASIC 2 Language Reference Manual.

2.0 CONFIGURATION REQUIREMENTS

2.1 Hardware

Minimum required configuration

2200 system

Check the configuration requirements for the program that is going to be run.

NOTE: Ensure that the partition size is large enough and the Device Table is properly configured.

2.2 Software

MVP CPU software must be rev. 1.8 or higher

VP CPU software must be rev. 2.1 or higher

Check the configuration requirements for the program that is going to be run:

3.0 PROGRAM DESCRIPTION

These are menu driven disks containing a combination of the diagnostics, utilities and exercisers for the 2200 MVP/LVP/SVP/VP systems. These programs are divided into four categories:

- 1. Printers/Plotters/Terminals
- 2. Magnetic Media
- 3. Telecommunications
- 4. CPU/Memory Test

The entire Diagnostic Package is contained on either one 8" Double-Sided Double-Density (DDDS) disk, four 8" Single-Sided Single-Density (SSSD) disks or four 5-1/4" Double-Sided Double-Density (DSDD) disks. The four disk set has the package divided into the four categories previously listed (one category per disk).

4.0 LOAD PROCEDURES

- 1. Select the device address with a 'SELECT DISK ###' statement (### equals the device address where program resides).
- 2. Input command 'LOAD RUN' to load if there is a "START" file. Input command 'LOAD RUN T"@MENU"', if there is no start file.

5.0 OPERATING INSTRUCTIONS

The menus in this package run the same as the system menus except the screening is revised. The Terminal number, Partition number and the size of the partition will be displayed in the lower right corner of the screen. Also the menus can be stepped backwards with 'PREV SCRN', CLEAR, or SF'31 keys.

Selection is made with the 'BACK SPACE', 'SPACE' bar, and the cursor arrows. When the desired selection is made (large dot before the name and the line is highlighted), press 'RUN' or 'RETURN' to initiate the selection. If the selection is another menu, then it will be displayed. If the selection is a program, then it will be loaded and run.

In order to support all of the 2200 LVP/SVP/MVP systems the diagnostic package needs to be available on 8" DSDD, 8" SSSD and 5-1/4" DSDD. The package is divided into four categories. Each category is small enough that it will fit on a SSSD 8" (or DSDD 5-1/4") disk. The entire package is on one 8" DSDD disk, four 8" SSSD or four 5-1/4 DSDD disks. The instructions for these disks are as follows:

Disk Type	Category refer	to Section
8" DSDD	All	7.1
8" SSSD & 5-1/4" DSDD	Printers/Plotters/Terminals	7.2
8" SSSD & 5-1/4" DSDD	Magnetic Media	7.3
8" SSSD & 5-1/4" DSDD	Telecommunications	7.4
8" SSSD & 5-1/4" DSDD	CPU/Memory test	7.5

5.1 2200 LVP/SVP Diagnostic Package

After the menu is loaded the following four selections will be displayed on the screen;

	Printers/Plotters/Terminals	Proceed to section 7.2	2
•	Magnetic Media	Proceed to section 7.3	3
	Telecommunications	Proceed to section 7.4	ŀ
	CPU/Memory test	Proceed to section 7.5	5

Select one of the above, using the normal menu selection procedure, and proceed with the corresponding instructions below.

5.2 Printers/Plotters/Terminals

When this menu is loaded the following options are available by the normal menu selection procedure:

- . Printers and Plotters
- . Terminals/Keyboards

The options for these selections are described in Appendix A.

5.3 Magnetic Media

When this menu is loaded, the following options are available by the normal menu selection procedure:

- . PLL/VCO Adjustments
- . Alignment Routines
- . Disk Utilities
- . Disk Exercisers
- . Mag Tape

The options for these selections are described in Appendix B.

5.4 Telecommunications

When this menu is loaded, the following options are available by the normal menu selection procedure:

- . 2228 D/E/F Power-Up Diagnostic Error Code Interpreter
- . 2228 D/E/F 7 Board Burn In
- . 2228 E/F Field Service Diagnostic
- . 2228 D Field Service Diagnostic Rev. 2
- . 2228 D Field Service Diagnostic Rev. 1
- . 2227B/2228B T/C Diagnostic

For these procedures, numbers and names see Appendix C.

5.5 CPU/Memory Test

When this menu is loaded, the following options are available by the normal menu selection procedure:

- . CPU Instruction Exerciser
- . CPU/Memory Diagnostic Procedure
- . Memory Error Chip Identifier

For these procedures, numbers and names see Appendix D.

6.0 MISCELLANEOUS

SSSD means Single-Sided Single-Density DSDD means Double-Sided Double-Density

Revision numbers are explained in Appendix E.

7.0 PROGRAM REVISION HISTORY

- 2.00.00 This Revision corrects the Problem running Multi Disk
 Diagnostics with the 386 Board.
 The software has been patched to permanently circumvent the
 Error message "CPU SOFTWARE MUST BE UPGRADED TO RUN THIS PROGRAM"
- 18A4 Changed the 'IF THEN ELSE' test in the CPU Instructions
 Exerciser to not error on old releases of BASIC. Replaced a
 damaged 'FTU' file on the 5-1/4 DSDD Magnetic Media disk (5-1/4
 revision is 68AO).
- Added test to the CPU Instructions to verify the VLSI CPU chip executes conditional branches correctly. Test was written after a bad shipment of chips was received. Rewrote the Data Memory Diagnostic for the VLSI-2 CPU. Added and enhanced many tests. Field Service menu labels changed.
- 6734 Added support for 2200DS and RAM Disk to MULTIDSK and FTU. Also fixed time out errors on long cabled mux.

 Added old style hashing routine to SUPERZAP.
- 6591 Internal change ECO update needed.
- 6534 Added 2220DW printer test to package.
- Multidsk has been modified to check for intermittent writing.

 STARTPLL was renamed to PLL and address selection was added.

 General Disk was converted to an FTU and named FTU.

 Phoenix Alignment was renamed to 2280ALGN and now has address selection.
- The package has been broken into four sections for use on Single-Sided Single-Density disks and the 5-1/4" disks.

 The programs have been updated to the latest revisions.

 MECI and FILZAP have been added.
- This package has been expanded to exercise the 2209A Tape Drive Unit.

APPENDIX A OPTIONS FOR PRINTERS/PLOTTERS/TERMINALS

Select the desired test and refer to the appropriate documentation for the procedures.

Documentation Menu selection F	Revision Program Name	Part Number	Soft	Doc.
. PRINTERS/PLOTTERS				
. 2201L . 2220DW . 2221W . 2231W-1 . 2231W-2	2201L 2220DW 2221W 2231W-1 2231W-2 2231W-3	760-1259 760-1327 (see note 1) (see note 1) (see note 1)	1.0 6534	9434 9534
. 2231W-3 . 2231W-6 . 2232 . 2235 . 2245 . 2251 . 2261W . 2263-1	2231W-6 2232 2235 2245 2251 2261W 2263-1	(see note 1) 760-1258 (see note 1) (see note 1) (see note 1) (see note 1) (see note 1)	61B0	9434
. 2263-2 . 2263-3 . 2273-1 . 2273-2 . 2281\(\)	2263-2 2263-3 2273-1 2273-2 2281\(\mathbb{W}\) 2282	(see note 1) 760-1276	414A	9434
. TERMINALS/KEYBOARDS				
 . 2200 Universal Keyboard Test . Burn-In Test . Local Printer Test . Character/Attributes Test . CRT Alignment Test . Partition Monitor 	uTextTst 36debin 36ptrloc 36chratb 36caling 36parton	760-1265 (see note 2) (see note 2) (see note 2) (see note 2)	1294	9434
Notes 1 - Part of General Printer Exe	orniser	760–1257	6441	9434
2 - Part of 2236DE/DW Field Ser		760–1270	11B1	9434

Revision numbers are explained in Appendix E.

APPENDIX B
OPTIONS FOR MAGNETIC MEDIA

Select the desired test and refer to the appropriate documentation for the procedures.

Documentation Menu selection	Revision Program Name	Part Number	Soft	Doc.
. PLL/VCO Adjustments				
. PLL Adj. (DSDD/Winchester) . VCO Adj. (DSDD/Win. w/o scope	PLL 2200 VCO	760-1250B 760-1263	84A5 81B4	94A5 9434
. Alignment Routines				
. DSDD Drive (850/851) . Phoenix	850ALIGN 2280ALGN	760-1223B 760-1264A	8448 84A4	9545 94A4
. Disk Utilities				
. Field Test Unit . Volume Zap . Alternate Sector Test	FTU Superzap PLL	760-1261D 760-1260A 760-1250B	68A0 8734 84A5	98A0 9734 94A5
. Disk Exerciser				
. Multiple Disk Exerciser . LVP DPU Burn in	MULTIDSK DPU BI	760-1209D 760-1262	69C1 41B4	99C1 9434
. Mag Tape				
. 2209A Tape Drive . Kennedy Archiving Tape Drive	109A010A TAP 29M	760-1269 760-1103A	2.0 7320	9434 9434

Revision numbers are explained in Appendix E.

APPENDIX C OPTIONS FOR TELECOMMUNICATIONS Select the desired test and refer to the appropriate documentation for the procedures.

		Documentation	Revi	sion
Menu selection	Program Name	Part Number	Soft	Doc.
. 2228 D/E/F Power-Up Diag.				
Error Code Interpreter	28DEFE I	760-1121A	3370	9434
. 2228 D/E/F 7 Board Burn In	7BDEFB1	760-1124B	4370	9434
. 2228 E/F F.S. Diag.	28EFSR2	760-1122A	1370	9434
. 2228 D F.S. Diag. Rev. 2	28DFSR2	760-1267	1158	9434
. 2228 D F.S. Diag. Rev. 1	28DFSR1	760-1268	1121	9434
. 2227B/2228B T/C Diagnostic	STARTTC	760-1275	13B1	9434

Revision numbers are explained in Appendix E.

APPENDIX D OPTIONS FOR CPU/MEMORY TEST Select the desired test and refer to the appropriate documentation for the procedures.

		Documentation	Revi	sion
Menu selection	Program Name	Part Number	Soft	Doc.
. CPU Instruction Exerciser . CPU/Memory Diagnostic Procedu . Memory Error Chip Identifier		•	1.0 179E 8434	9434 979E 9434

Notes:

- 1. The CPU/Memory Diagnostic Procedure explains how to load (boot) the CPU/Memory diagnostic. The documentation number and revision numbers are for the CPU/Memory diagnostic.
- 2. This test contains many files on the media. The file names are listed in the documention for the program.

Revision numbers are explained in Appendix E.

APPENDIX E EXPLANATION OF REVISION NUMBERS

			Rev.		
<u>1st</u>	Position	= Kind of Diagn	ostic	!!!!	- -
		Not Supported Diagnostic Prog Monitor Package Monitor Program Burn In Power Up Exerciser Board Repair Utility Document only Reserved		- 2 - 3 - 4 - 5 - 6 - 7	
<u>2nd</u>	Position	= Last Digit of	Year	!	
•		Self-explan	atory	0-	9 ! !
<u>3rd</u>	Position	= Month of Revi	sion		!!!
	·	Febru March April May _ June July Augus	t mber er ber		2 ! 3 ! 4 ! 5 ! 6 ! 7 !
<u>4th</u>	Position	= Type of Chang	e		
			Brand New Software F Test Added Enhancemen Hardware (l	0 1 2 4 8

These numbers can be added together (in hex) to include more than one type of change.

WANG MANU O664S TEST	PART NO. 212-7129A-D SHEET 1 OF 6 DATE 09/14/89	
TITLE CS386	PART NUMBER 210-9561A-D 210-9562 212-7129A-D	TYPE OF TEST RUN-IN TEST
APPROVAL	APPROVAL	APPROVAL
TECHNICAL WRITER 9-12-89 Juganne M. Clark	PRODUCT SUPTIENGR. E. Dargresult 9/12/89	
Station 9/14/25	PILOT ENGR. Normy 9/12/8	9
	REVISION HISTOR	Y

DESCRIPTION	SHT.	MPC/ECO	DATE	CHANGED BY
	n/a	n/a		S. CLARK
Distr. VS Board Area				
	PRELIMINARY DRAFT CHANGES PER ENGINEERING SMALL CHANGES	PRELIMINARY DRAFT CHANGES PER ENGINEERING SMALL CHANGES n/a	PRELIMINARY DRAFT CHANGES PER ENGINEERING SMALL CHANGES n/a n/a	PRELIMINARY DRAFT CHANGES PER ENGINEERING SMALL CHANGES n/a n/a 09/12/89 09/12/89

ø

WANG)

MANUFACTURING TEST PROCEDURE

PART NO.

212-7129 A-D

SHEET 2 OF 6

DATE 09-14-89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

1. PURPOSE

1.1 To detail the steps necessary when performing a RUN-IN test on the CS386 CPU assembly (212-7129A-D).

NOTE:

THERE ARE TWO METHODS THAT CAN BE USED TO RUN-IN THE CPU ASSEMBLY. THIS PROCEDURE COVERS RUNNING THE ASSEMBLY WITHIN THE CS386 SYSTEM. SEE APPENDIX 7.1 FOR A PROCEDURE ON HOW TO RUN THE ASSEMBLY USING THE BUILT IN TEST (BIT).

- 2. REFERENCES
 - 2.1 None required.
- 3. RESPONSIBILITIES
 - 3.1 Refer to <u>GUIDELINES FOR WRITING TEST PROCEDURES</u> (PROC-0009), section 4., for a detailed listing of responsibilities.
- 4. EQUIPMENT REQUIREMENTS

DESCRIPTION	PART NUMBER QTY
2436 Workstation	187-3249 or equiv1
Tark Sinkung ubich includes:	
20MP Hinchoster	
DOLL DOR	
- Triple Controller	212-30121

5. SETUP PROCEDURE

5.1 Verify that the jumper (J5), located on the 210-9561X board, is positioned as shown below:



- 5.2 Connect the battery (from the test fixture) to location J2 of the 210-9562 board.
- 5.4 Insert the assembly under test (212-7129A-D) into the CPU position of the test bed motherboard.

WANG)

MANUFACTURING TEST PROCEDURE

PART NO.

212-7129A-D

SHEET 3 OF 6

DATE

09-14-89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

- 6. ACTUAL TEST
 - 6.1 Power UP the test bed. The following screen will appear:

COPYRIGHT, WANG LABORATORIES, INC., 1989 REV 5930

SRAM 256KB DRAM XXXXKB LOOP COUNT: XX

- 6.2 Verify that the amount of "D RAM" tested is equal to that expected for the assembly under test (see above). If the amount is less than expected, the assembly has failed.
- 6.3 The following message will appear:

Mount system platter Press Reset

- 6.4 After the LED on the floppy drive has extinguished, press the SHIFT and RESET keys simultaneously (SHIFT/RESET).
- 6.5 The following prompt will appear on the monitor screen:

Key SF?

WANG) MANUFACTURING TEST PROCEDURE

PART NO. 212-7129A-D SHEET DATE

9-14-89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

6. ACTUAL TEST (cont'd)

6.6 Press the SFO key. The following screen will appear:

**** SYSTEM SOFTWARE ****

Select item with SPACE & BACKSPACE. MEMORY 1024 K Key RUN to execute, CLEAR or PREV for previous screen TERMINAL 1

Multiuser BASIC-2

. Diagnostics

- 6.7 Select "DIAGNOSTICS". Press the RUN key. The "Customer Diagnostic" screen will appear.
- 6.8 Allow the test to run for a specified period.
- 6.9 When complete, press the SHIFT and RESET keys at the same time (SHIFT/RESET). Disconnect the battery and remove the assembly from the test fixture.
- 6.10 If the assembly has run error free, fill out the appropriate paperwork and submit the assembly for FINAL ACCEPTANCE TESTING.
- 6.11 If a failure was detected, fill out the appropriate paperwork, noting the discrepancy, and send the assembly to the REPAIR AREA.

WANG)

MANUFACTURING TEST PROCEDURE

PART NO.

212-7129A-D

SHEET 5 OF 6

DATE 09/14/89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

- 7. <u>APPENDIX</u> ALTERNATE TEST
 - 7.1 RUN-IN TEST (BIT):
 - 7.1.1 EQUIPMENT REQUIREMENTS
 - One 2436 Workstation (187-3249 or equivalent)
 - One Cabinet Assembly CS-D/N (279-0873)
 - One Triple Controller (212-3012)

7.1.2 SETUP PROCEDURE

7.1.2.1 Verify that the jumper (J5), located on the 210-9561X board, is positioned as shown below:



- 7.1.2.2 Connect the battery (from the test fixture) to location J2 of the 210-9562 board.
- 7.1.2.3 Attach jumper to location J7 of the 210-9561 board.
- 7.1.2.4 Insert the 212-3012 Triple Controller into any available slot.
- 7.1.2.5 Attach a workstation cable to the terminal position of the 212-3012 Triple Controller.
- 7.1.2.6 Insert the assembly under test (212-7129A-D) into the CPU position of the motherboard.

WANG) MANUFACTURING TEST PROCEDURE

PART NO. 212-7129A-D SHEET 6 DATE 09/14/89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

- APPENDIX ALTERNATE TEST (cont'd) 7.
 - 7.1 RUN-IN TEST (BIT): (cont'd)

7.1.3 ACTUAL TEST

Power $\underline{\mathsf{ON}}$ the test bed. The following screen 7.1.3.1 will appear:

COPYRIGHT, WANG LABORATORIES, INC., 1989 REV 5930

SRAM 256KB DRAM XXXXKB LOOP COUNT: XX

- Verify that the amount of "D RAM" tested is 7.1.3.2 equal to that expected for the assembly under test (see above). If the amount is less than expected, the assembly has failed.
- The assembly under test will continue to 7.1.3.3 cycle for a specified run-in period (or until an error is detected).
- Run the diagnostic for a specified period. 7.1.3.4
- When complete, press the SHIFT and RESET 7.1.3.5 keys at the same time (SHIFT/RESET). down the test bed. Disconnect the battery and remove the assembly from the test fixture.
- If the assembly has run error free, fill out 7.1.3.6 the appropriate paperwork and submit the assembly for FINAL ACCEPTANCE TESTING.
- If a failure was detected, fill out the 7.1.3.7 appropriate paperwork, noting the discrepancy, and send the assembly to the REPAIR AREA.

WANG MANU	PART NO. 212-7129A-D SHEET 1 OF 6 DATE	
TITLE CS386	PART NUMBER 210-9561A-D 210-9562 212-7129A-D	09/14/89 TYPE OF TEST RUN-IN TEST
APPROVAL	APPROVAL	APPROVAL
TECHNICAL WRITER 9-12-09 Juganne M. Clark	PRODUCT SUPTIENCE. E. Jargreaut 9/12/89	
Both G/14/25	FILOT ENGR.	9
	REVISION HISTOR	Υ

REV. DESCRIPTION SHT. MPC/ECO DATE CHANGED BY

1167.	DESCRIPTION	SH 1.		5716	
A B C	PRELIMINARY DRAFT CHANGES PER ENGINEERING SMALL CHANGES	n/a	n/a		S. CLARK S. CLARK
RGW (Distr. VS Board Area			COMPA	NY CONFIDENTIA

WANG MANUFACTURING TEST PROCEDURE

PART NO.

212-7129 A-D

SHEET

DATE 09-14-89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

- 1. **PURPOSE**
 - 1.1 To detail the steps necessary when performing a RUN-IN test on the CS386 CPU assembly (212-7129A-D).

NOTE:

THERE ARE TWO METHODS THAT CAN BE USED TO RUN-IN THE CPU ASSEMBLY. THIS PROCEDURE COVERS RUNNING THE ASSEMBLY WITHIN THE CS386 SYSTEM. SEE APPENDIX 7.1 FOR A PROCEDURE ON HOW TO RUN THE ASSEMBLY USING THE BUILT IN TEST (BIT).

- REFERENCES 2.
 - 2.1 None required.
- RESPONSIBILITIES 3.
 - 3.1 Refer to <u>GUIDELINES FOR WRITING TEST PROCEDURES</u> (PROC-0009), section 4., for a detailed listing of responsibilities.
- EQUIPMENT REQUIREMENTS 4.

DESCRIPTION	PART NUMBER	QTY
2436 Workstation	187-3249 or equi	v1
Test fixture which includes: - 360K Floppy	289-0846	1
_ 20MR Winchester		
- DPIL PCR		
- Triple Controller	212-3012	<u> </u>

SETUP PROCEDURE 5.

5.1 Verify that the jumper (J5), located on the 210-9561X board, is positioned as shown below:





- 5.2 Connect the battery (from the test fixture) to location J2 of the 210-9562 board.
- 5.4 Insert the assembly under test (212-7129A-D) into the CPU position of the test bed motherboard.

WANG) MANUFACTURING TEST PROCEDURE

PART NO. 212-7129A-D SHEET DATE 09-14-89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

- ACTUAL TEST 6.
 - 6.1 Power UP the test bed. The following screen will appear:

COPYRIGHT, WANG LABORATORIES, INC., 1989 REV 5930

SRAM 256KB DRAM XXXXKB LOOP COUNT: XX

- 6.2 Verify that the amount of "D RAM" tested is equal to that expected for the assembly under test (see above). If the amount is less than expected, the assembly has failed.
- 6.3 The following message will appear:

Mount system platter Press Reset

- 6.4 After the LED on the floppy drive has extinguished, press the SHIFT and RESET keys simultaneously (SHIFT/RESET).
- 6.5 The following prompt will appear on the monitor screen:

Key SF?

WANG MANUFACTURING TEST PROCEDURE

PART NO. 212-7129A-D SHEET

DATE 9-14-89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

ACTUAL TEST (cont'd) 6.

6.6 Press the SFO key. The following screen will appear:

**** SYSTEM SOFTWARE ****

MEMORY 1024 K Select item with SPACE & BACKSPACE. Key RUN to execute, CLEAR or PREV for previous screen TERMINAL 1

Multiuser BASIC-2

. Diagnostics

- 6.7 Select "DIAGNOSTICS". Press the RUN key. The "Customer Diagnostic" screen will appear.
- 6.8 Allow the test to run for a specified period.
- 6.9 When complete, press the SHIFT and RESET keys at the same time (SHIFT/RESET). Disconnect the battery and remove the assembly from the test fixture.
- 6.10 If the assembly has run error free, fill out the appropriate paperwork and submit the assembly for FINAL ACCEPTANCE TESTING.
- 6.11 If a failure was detected, fill out the appropriate paperwork, noting the discrepancy, and send the assembly to the REPAIR AREA.

WANG MANUFACTURING TEST PROCEDURE

PART NO. 212-7129A-D SHEET DATE

TITLE

CS386 (212-7129A-D) RUN-IN TEST

- APPENDIX ALTERNATE TEST 7.
 - 7.1 RUN-IN TEST (BIT):
 - 7.1.1 EQUIPMENT REQUIREMENTS
 - One 2436 Workstation (187-3249 or equivalent)
 - One Cabinet Assembly CS-D/N (279-0873)
 - One Triple Controller (212-3012)

7.1.2 SETUP PROCEDURE

Verify that the jumper (J5), located on the 7.1.2.1 210-9561X board, is positioned as shown below:



- Connect the battery (from the test fixture) 7.1.2.2 to location J2 of the 210-9562 board.
- Attach jumper to location J7 of the 210-9561 7.1.2.3 board.
- Insert the 212-3012 Triple Controller into 7.1.2.4 any available slot.
- Attach a workstation cable to the terminal 7.1.2.5 position of the 212-3012 Triple Controller.
- Insert the assembly under test (212-7129A-D) 7.1.2.6 into the CPU position of the motherboard.

WANG) MANUFACTURING TEST PROCEDURE

PART NO. 212-7129A-D SHEET 6 6 DATE

TITLE

CS386 (212-7129A-D) RUN-IN TEST

APPENDIX - ALTERNATE TEST (cont'd) 7.

RUN-IN TEST (BIT): (cont'd)

7.1.3 ACTUAL TEST

Power $\underline{\text{ON}}$ the test bed. The following screen 7.1.3.1 will appear:

COPYRIGHT, WANG LABORATORIES, INC., 1989 REV 5930

SRAM 256KB DRAM XXXXKB LOOP COUNT: XX

- Verify that the amount of "D RAM" tested is 7.1.3.2 equal to that expected for the assembly under test (see above). If the amount is less than expected, the assembly has failed.
- The assembly under test will continue to 7.1.3.3 cycle for a specified run-in period (or until an error is detected).
- Run the diagnostic for a specified period. 7.1.3.4
- When complete, press the SHIFT and RESET 7.1.3.5 keys at the same time (SHIFT/RESET). down the test bed. Disconnect the battery and remove the assembly from the test fixture.
- If the assembly has run error free, fill out 7.1.3.6 the appropriate paperwork and submit the assembly for FINAL ACCEPTANCE TESTING.
- If a failure was detected, fill out the 7.1.3.7 appropriate paperwork, noting the discrepancy, and send the assembly to the REPAIR AREA.

VS OFFICE ELECTRONIC MAIL FRIDAY 12/15/89 03:52 PM PAGE: RICHARD SUTTON MS018-26C/PB CC: ELIACIM CORTES FROM: SUBJECT: SURPLUS 2200 EQUIPMENT DATE: 12/15/89 DISTRIBUTION: NOT REQUESTED TO: ED DAIGNEAULT CC. RICK SUTTON 212-3032 TERM CONT. 210-7342 DISTIPRENTER CONT. FROM: ELIACIM CORTES 12-15-89 DATE: SUBJECT: 2200 EQUIPMENT WPR CURRENTLY HAS THE FOLLOWING EQUIPMENT AVAILABLE: .3.GOOD DISKS.2275-10 AND 3 BAD ONES. 2. 1 MICRO VP WHICH ONLY HAS CHASSIS, POWER SURPLY AND MOTHERBOARD (NO BOARDS) 3. 2 BAD TRIPLE CONTROLLERS (NEED REPAIRS). -4. 4 KEYBOARDS PN 279-2030 (WILL THESE FIT YOUR APPLICATION?) 5. I HAVE NO DATA AT THIS MOMENT ON AVAILABILITY OF THE WORKSTATION CABLES. PLEASE ADVISE IF YOU WANT US TO SHIP THESE. REGARDS: ELIACIM. P.O. MADE FOR THIS EQUIPMENT NEED NEW P.O. #

> DEP

, TO:

KHALIL AZAR

FROM:

STEVEN J. ANTHONY / MICHAEL DICK

SUBJECT

CS 386 (2200 /386) Outstanding Run-In Equipment

DATE:

14 DEC 89

On 20 Sept 89, Ed Daignault generated a C.A.R. for support of the CS 386 product, a 2200 80386 microprocessor based product. In this C.A.R., is equipment designated for use in the PB PCB Run-In area. The list of equipment required to perform PCB Run-In, per projected build quantities, is as follows:

QUANTITY	<u>ITEM</u>	<u>P/N</u>
5	TERMÎNAL	187-3249
5	VLSI CHASIS	270-1018
5	TRIPLE CONTROLLER	212-3012
5	DISK SYSTEM	187-3505
5 .	DISK CABLE	220-0365
5	TERMINAL CABLE	220-0447

To date the following equipment is still required to perform PCB level Run-In:

QUANTITY	<u>ITEM</u>	<u>P/N</u>
2	VLSI CHASIS	270-1018
2	TRIPLE CONTROLLER	212-3012
4	DISK SYSTEM	187-3505
5	DISK CABLE	220-0365

In an effort to attain the required equipment to begin PCB level Run-In, the following will occur:

- 1) Wang Re-Manufacturing, athough previous checked twice for available required equipment, will be checked again. This will be complete 14 DEC 89.
- 2) Product Support Engineering and Finance will be requested to expedite any remaining equipment shortages from Wang Labs Puerto Rico and/ or Wang stock. Additionally, expected ship times and delivery dates will be requested.

TO:

KHALIL AZAR

FROM:

STEVEN J. ANTHONY / MICHAEL DICK

SUBJECT

CS 386 (2200 /386) Outstanding Run-In Equipment

DATE:

14 DEC 89

On 20 Sept 89, Ed Daignault generated a C.A.R. for support of the CS 386 product, a 2200 80386 microprocessor based product. In this C.A.R., is equipment designated for use in the PB PCB Run-In area. The list of equipment required to perform PCB Run-In, per projected build quantities, is as follows:

QUANTITY	ITEM	P/N
5	TERMÌNAL	187-3249
5	VLSI CHASIS	270-1018
5	TRIPLE CONTROLLER	212-3012
5	DISK SYSTEM	187-3505
5	DISK CABLE	220-0365
5	TERMINAL CABLE	220-0447

To date the following equipment is still required to perform PCB level Run-In:

QUANTITY	<u>ITEM</u>	<u>P/N</u>
2 .	VLSI CHASIS	270-1018
2	TRIPLE CONTROLLER	212-3012
4	DISK SYSTEM	187-3505
5	DISK CABLE	220-0365

In an effort to attain the required equipment to begin PCB level Run-In, the following will occur:

- 1) Wang Re-Manufacturing, athough previous checked twice for available required equipment, will be checked again. This will be complete 14 DEC 89.
- 2) Product Support Engineering and Finance will be requested to expedite any remaining equipment shortages from Wang Labs Puerto Rico and/ or Wang stock. Additionally, expected ship times and delivery dates will be requested.

WE 1) 1:30

ī

TROS:

SUBJECT: KHALIL AZAR

STEVEN J. ANTHONY 212-7129 PB TEST INFO

MS013-27C/PB

DATE: 12/21/89

DISTRIBUTION:

NOT REQUESTED

JUAN,

I HAVE RECEIVED THESE TESTS ARE THE 8 212-7129 PCB'S AND TESTED THEM IN PR. THE RESULTS OF AS FOLLWOS:

		PASS		!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!	04273450	212-7129-A
(LOAD DIAGS)	(101	FAIL	*	!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!	04208203	212-7129-A
		PASS		4	04208206	212-7129-В
		S S 4 A		2084	04241459	212-7129-A
(BOOT TEST)	(B)	FAIL	*	5351	8441424C	212-7129-A
		PASS		ው	04273420	212-7129-A
		PASS		DOA	04273459	212-7129-A
		PASS		<u></u>	04204683	212-7129-A
JLT	RESULT	TEST	מי	WPR FAIL AT LOOP	SESIAL #	BOARD #

THE IN-SYSTEMS TEST IN PS CONSISTS OF RUNNING DIAGNOSTICS FOR 100 PASSES. THESE POB'S WILL NOT BE SHIPPED UNTIL PB HAS FULL RUN-IN CAPABILITIES AND IS ABLE TO PERFORM ALL RUN-IN TESTS. IF THERE ARE ANY QUESTIONS, PLEASE CALL AT TELEPHONE NUMBER (508) 656-4478.

REGARDS

ANCHINE BABLS

SUBJECT: 00: VS OFFICE ELECTRONIC MAIL FROM: STEVEN J. ANTHONY 212-7129 PB TEST INFO KHALIL AZAR THURSDAY DATE: 12/21/89 MS015-270/PB 12/21/89 12:37 FM PAGE:

DISTRIBUTION:

NOT REQUESTED

JUAN, I HAVE RECEIVED THESE TESTS ARE THE 8 212-7129 PCB'S AND TESTED THEM IN PR. THE RESULTS OF AS FOLLWOS:

((CAD DIAGS)	* V A O F O C	: :	04273450	212-7129-A
•	(V)	r	20820	2-7129
	ľÞ	is is	24145	2-7129-
. (BOOT TEST)	منا 1-4	533.7	24144	2-712
	D U:	o	27342	2-7129-
	(D)		27345	2-7129-
	PASO		20465	2-7129-
PESULT	\$ 7 E 8 T	SPR FAIL AT 1002	SESIAL	BOARD #

THE IN-SYSTEMS TEST IN PS CONSISTS OF PUNNING DIAGNOSTICS FOR 100 PASSES. THESE POE'S WILL NOT BE SHIPPED UNTIL PHEAS FULL RUN-IN CAPABILITIES AND IS ABLE TO PERFORM ALL PUN-IN TESTS. IF THERE ARE ANY QUESTIONS, PLEASE CALL ME AT TELEPHONE NUMBER (508) 555-4478.

8504308V

ANGHLRV BARLS



WANG

TO:	JUAN PENA
COMPANY:	WANG LABS PR
LOCATION:	PUERTO RICO
FAX #:	(809) 734-8775
FROM:	STEVEN J. ANTHONY
	18 DEC 89
DATE:	7
# of PAGES	(Including Cover):

TO:

JUAN PENA

FROM:

STEVEN J. ANTHONY

SUBJECT:

2200/386 SYSTEM RUN-IN OF 212-7129A-D PCB SET

DATE:

18 DEC 89

In October of 1989, the Pawtucket Boulevard Manufacturing facility began production of the the 2200/386 pcb card set, 212-7129A-D (PCB 210-9561A-D and PCB 210-9562). Due to the reschedule of site sourcing at this time, PCB Run-In test equipment was not available. Therefore Functional Run-In of these PCB's is not available in Pawtucket Boulevard. In lieu of the complete run-in capabilities, the PB maufacturing site has been performing a limited Built In Test for 24 hours as a prerequisit to final shipment.

Due to the lack of Run-In equipment, which is currently on order, and until this Run-In equipment becomes operational in Pawtucket Boulevard, it is recommended by the PB PCB Test Engineering group that a 24 HR System Run-In Test be performed in Wang Labs Puerto Rico. If there are any questions, please contact me at Tel. (508) 656-4478.

Steven J. Anthony

CAPITAL APPROPRIATION REQUEST (SEE SCHEDULE "A" FOR SUPPARY)

PROJECT TITLE: CS-386 CPU	PROJECT MUMBER:	
TETAL T BELLETHER THE STATE	DATE	
Foursing: Edmond Daigneault	TEL. Da.: 09/28/89	
EPARTICULT 6:-	COST CENTER:	
ACILITY: 007	CC HANAGER: 6022/ Don Monahan	
•	Joh Mohanah	
ECTION II - EXPENDITURE SUMMARY: (Attach Se	chedule B)	
APITAL EQUIPMENT: IXTURES: COOLING: INSTALLATION: \$ 11,985.00 28,200.00	ARE THERE RELATED REQUESTS? (Y/N)	
IXTURES: N	00011 000000000000000000000000000000000	
COLING: 28,200.00	TOTAL PREVIOUS REQUEST: (B) \$ BOOK VALUE OF TRANSFER: (C) \$ RELATED EXPENSES: (D) \$ (Schedule E - Part 4) TOTAL RELATED EXPENSES: (E) \$	
FREIGHT:	ELITED EADINESS: (C) 9	
DUTY:	(Schedule E - Part A)	
~	TOTAL RELATED EXPENSES: (E) \$	
OTAL REQUEST: (A) \$ 40,185.	(Add B. C. & D)	
MOUNT BUDGETED: \$ 40,185.	OCTOTAL PROJECT SCOPE (A + E) 8	1
	,	40,135.0
EDCTION III - PROJECT CATEGORY: (Check Only	One)	
CAPACITY: TACT	CICAL: STRATEGIC:	
PRODUCTION (STD POUTP) A PRODUCT	VITY: COST 6. NEW PRODUCT/	
P. OFFICE FUR & FIXTURES REDUCTION B. WANG BUILT EQUIPMENT S. REGULATION CONTROL OF AUTOMATION	CN/ REPLACEMENT PRODUCT TRANSF	ER T
B. WANG BUILT EQUIPMENT S. REGULATI	CON/SAFETY 7. NEW PLANT F11-	₩
e. orrice acrossion	e. Illinuui	
b. Business systems	DEVELOPMENT	
SECTION IV - SUPPORTING SCHEDULES		
IF YOU CHECKED 1,3,4, or 6 ABOVE; WHAT IS	PAYBACK: NPV: IER:	
(SCHEDULE C)	**************************************	一,
F TOU CHECKED 6. 7 OR 8 ATTACH SUPPARY OF	F STRATEGIC/COST ADVANTAGES. (SCHEDULE D)	
IP YOU CHECKED 1 OR 6 ATTACH PRODUCTION PA		1
IF YOU CHECKED 4 OR 8, COMPLETE GILY PART		
is equipment on plant "Standards" list (Y/	/N)? IF NO, PLEASE ATTACH EQUIPMENT	
CECK-OFF LIST. (SCEDULE F)	•	
IF TOOLING IS PART OF REQUEST ATTACH SCHOOL		
IF YOU CHECKED 3A OR 3B ATTACH DAFORMATICS		
IF YOU CHECKED 6 (PRODUCT TRANSFER) ATTAC	h equiphent transfer checklist. (schedule 1	9
ECTION V - SIGNATURES:		
review Date	APPROVAL DATE	
DESTRAL CAPITAL FURCHASING	DIRECTOR	
LITE EXGINEERING	FINANCE (PER AUTHORIZATION POLICY)	
570	AREA VF (UNDER 100K)	1
CUE-CORMITTEE CHAIRPERSON	CAPITAL COMMITTEE (FINANCE VP)	
DTHERS	EXECUTIVE VP (OVER \$250,000)	
COTE: IP REVIEWER DOES NOT CONTUR WITH	VICE CHAIRMAN®	
FROMOSAL FLEASE FUT AN ASTEMISK (*) ESSIDE		t
LIGILATURE AND ATTACH SUPPARTY OF CONTERNS		· · · · · ·
LID LIBERVATIONS, CTHERHISE, SIGNATURE	EQUIPMENT OVER \$1,000,000, ALL EVILDING	1
EPPLEDITS AGREEMENT WITH PROPOSAL.	IMPROVEMENTS, LAND & EVILORES OVER \$ 250	

Capital Appropriation Request Package Executive Summary Sheet

Project Title: CS-386 CPU

Project Number:	Date: 09/28/89
Department Name: New Product Introdu	Department 007
Requestors Name: Edmond Daigneault	Telephone Ext. 78635
Executive Summary: (The objective of The CS-386 CPU board is intended to 1. Improve CS CPU performance by 0. Create CS/2200 look alike system technology. 3. Enable the CS system to handle 1 performance level currently available.	o : up to 300%. m that uses modern 16 users at the same
Capital Spending Request Summary:	
A.) Outside Vendor Purchases:	(exc.Tooling costs)
B.) Wang Serialized Equipment:	\$ 11985.00 (at WLI MFG. COST)
C.) Tooling Expenditures:	\$
D.) Other:	\$
E.) ATE:	\$ 28,200.00
F.) CTE:	\$
G.) Total Cash Outflow(A+B+C+D+E+F):	\$40,185.00
H.) Domestic Mfg. Transfers In:	
I.) International Mfg. Transfers In:	\$Exchange Rate
J.) Total Related Previous Requests:	
K.) Total Project Scope: (G+H+I+J)	\$ 40,185.00
Finance Methods in Evaluating Capita Capital Budget Amount \$	l Projects:
NPV IRR	PAYBACK
TOTAL CASH OUTFLOW BY QUARTER: Q1 \$	Q2 \$ Q3 \$ Q4 \$



TECHNICAL SUMMARY/NEEDS ANALYSIS

Most of the cost in this request is for two In Circuit Test fixtures. One fixture will test the 210-9561 PCB. The other will test the 210-9562 PCB. These boards make up the 212-7129A-D assemblies. These assemblies will be the CPU board set for CS386 lMB thru 8MB systems.

These fixtures will be used to detect process related and other defects before they are passed on to the test technicians. It is anticipated that this will increase the first pass yield at Pretest by at least 25%. This will decrease the amount of technician repair time required.

Also included is the cost of remanufactured 2200 equipment to be used as test stations for board run-in. Five systems have been requested to cover CSO spares, and upgrade kits which will ship out of Pawtucket Boulevard. This amount of stations should also allow run-in of system boards if P.B. desires.



EXPENDITURE DETAIL LIST (ATTACH PURCHASE, CONSIGNMENT, ATE FIXTURE, CTE, REQS. HERE)

	DART/	INIT		. E)		57	
rem description	MODEL +	COST	OTY	VENDOR	CONSIGN MFG COST	OTHER WANG BUILT	G.L. • *
In Circuit Test Fixture 210-9561	F89-0	7 14	100	1		14100	1410
In Circuit Test Fixture 210-9562	F89-0	8 14	100		•	14100	1410
VLSI Chassis	270-1	18	24	5	2620		262
Terminal	187-33 25361	49 5 W	97	5	2985		298
Triple Controller	212-30	12	91	5	955		95
Disk System .	187-3 2275-	05 10 0	19	5	5095	·	509
Disk Cable	220-0	65	38	5	190	·	19
Terminal Cable	220-0	47	10	5	50		5
٠		_				•	•
•		٠					•
	•					·	
							•
70	TAL FOU	IPME	IT.		11 985.00	28.200 -	24 0 156
	Fixture 210-9561 In Circuit Test Fixture 210-9562 VLSI Chassis Terminal Triple Controller Disk System Disk Cable Terminal Cable	In Circuit Test Fixture 210-9561 In Circuit Test Fixture 210-9562 VLSI Chassis 270-1 Terminal 187-3 2536 Triple Controller Disk System 187-3 2275- Disk Cable 220-0 Terminal Cable 220-0	In Circuit Test F89-0 7 14 Fixture 210-9561 F89-0 8 14 Fixture 210-9562 F89-0 8 14 Fixture 210-9562 VLSI Chassis 270-1 18 5 Terminal 187-3 49 5 2536 W Triple Controller 212-3 12 Disk System 187-3 05 10 2275- 0 Disk Cable 220-0 65 Terminal Cable 220-0 47	In Circuit Test F89-0 7 14100 The Circuit Test F89-0 8 14100 VLSI Chassis 270-1 18 24 Terminal 187-3 49 2536 W 97 Triple Controller 212-3 12 191 Disk System 187-3 05 1019 2275- 0 1 19 Disk Cable 220-0 65 38	In Circuit Test Fixture 210-9561 F89-0 7 1 100 1	In Circuit Test Fixture 210-9561 F89-0 8 14 100 1	In Circuit Test Fixture 210-9561 F89-0 7 1 100 1 141000 141000 141000 141000 141000 141000 141000 141000 141000 141000 141000 141000 141000 1410



STRATEGIC/COST ADVANTAGE ANALYSIS

(Describe Below As Appropriate)

STRATEGIC: locational advantages, grants, second builder of product, closeness

to markets, etc.

COST FACTORS: economic/cost advantages of approach versus alternatives considered (used in place of payback when relationship to cash

inflow is not direct).

The use of the requested In Circuit test fixtures will increase the first pass yield at the Pretest station by an estimated 25%. This increase will result in lower costs. This will come from using less costly labor to detect the bulk of the defects.

Since the bulk of the defects detected will be manufacturing problems, detecting these problems early will facilitate information feedback to correct repetitive problems. This will further reduce labor costs.

The run—in stations will enable Wang to detect latent process defects that would otherwise be detected at the customers site. $\,$.

REQUEST FOR A.T.E. FIXTURES AND PROGRAMS

FINANCIAL ENGINEERING
PROJECT # REQUEST #
REQUESTOR SUPPLIED INFORMATION:
BRD/ASSY PART # 210-9561 FOR SUPPORT OF: CS-386
BRD/ASSY DESCRIPTION: <u>C5-386 CPU</u> DATE REQ'D JUNE 89
REASON FOR REQUEST: NEW PRODUCT: MPP REV.
VOLUME: 450 Q1 FY.90: 450 Q2 FY.90: 450 Q3 FY.90: 450 Q4 FY.90
REQUEST FOR: PROGRAM V FIXTURE V NEW V DUPLICATE UPGRADE
TYPE OF TEST: BARE BOARD IN-CIRCUIT \(\nu \) LOADED BOARD EMULATION
FUNCTIONAL OTHER
EQUIPMENT TYPE: FAIRCHILD STD V ECL SMD ESTIMATED COST: \$14,100
FIX. SIZE: S_ M L XL O_ BOARD DIMENSIONS:
COMMENTS:
REQUESTOR: E.DAIGNEAULT EXT: 78635 M/S: 015-118 DATE: 4/12/89 TEST ENGINEERING SUPPLIED INFORMATION:
JUSTIFICATION OF SELECTION OR REJECTION:
SPECIAL PROGRAMMING CONSIDERATIONS:
RDB RECEIVING EQUIPMENT:
APPROVAL:
PRODUCT ENG. MGR. W. M. L. L. TEST STRATEGY TOOK ST. B. SR. BUSINESS
SR. BUSINESS /_/ FINANCE /// DIRECTOR //

A.T.E. SUPPLIED INFORMATION: DATE REC'D: _/_/_
S/N FIM-1606 PROJECT TRACKING NO F89-057

REQUEST FOR A.T.E. FIXTURES AND PROGRAMS

FINANCIAL ENGINEERING
PROJECT # REQUEST # ***********************************
REQUESTOR SUPPLIED INFORMATION:
BRD/ASSY PART # 210-9562 FOR SUPPORT OF:
BRD/ASSY DESCRIPTION: CPU DAUGHTER BOARD DATE REQ'D JUNE 89
REASON FOR REQUEST: NEW P2000C7 MPP REV.
VOLUME: 450 0/ FY'90: 450 02 FY'90: 450 03 FY'90: 450 04 FY'90
REQUEST FOR: PROGRAM 1 FIXTURE NEW DUFLICATE UPGRADE
TYPE OF TEST: BARE BOARD IN-CIRCUIT LOADED BOARD EMULATION
FUNCTIONAL OTHER
EQUIPMENT TYPE: FARCHILO STD V ECL SMD ESTIMATED COST: \$ /4,100,00
FIX. SIZE: $S \times M \sqrt{L} \times L = 0$ BOARD DIMENSIONS: 3.50×11.25
COMMENTS:
REQUESTOR: <u>FD. OA/6NEAUL7</u> EXT: <u>78635</u> M/S: <u>615-118</u> DATE: <u>4//2/89</u>
TEST ENGINEERING SUPPLIED INFORMATION:
JUSTIFICATION OF SELECTION OR REJECTION:
SPECIAL PROGRAMMING CONSIDERATIONS:

RDB RECEIVING EQUIPMENT:
APPROVAL:
PRODUCT ENG. MGR. W.D. College Test STRATEGY Juke Green 5, 1, 8, A.T.E. OPERATION WILL THE STATEST A.T.E. OPERATION
SR. BUSINESS
SR. BUSINESS
A.T.E. SUPPLIED INFORMATION: DATE REC'D: _/_/_
S/N <u>FZIS-1607</u> PROJECT TRACKING NO <u>F89-058</u>



Schedule D

STRATEGIC/COST ADVANTAGE ANALYSIS

(Describe Below As Appropriate)

STRATEGIC: locational advantages, grants, second builder of product, closeness

to markets, etc.

COST FACTORS: economic/cost advantages of approach versus alternatives

considered (used in place of payback when relationship to cash

inflow is not direct).

The use of the requested In Circuit test fixtures will increase the first pass yield at the Pretest station by an estimated 25%. This increase will result in lower costs. This will come from using less costly labor to detect the bulk of the defects.

Since the bulk of the defects detected will be manufacturing problems, detecting these problems early will facilitate information feedback to correct repetitive problems. This will further reduce labor costs.



PRODUCTION FACT SHEET (ATTACH SUPPORTING DOCUMENTATION HERE AS NECESSARY)

	RODUCTION SCHE	DULE		•		MPP	EV #:	
	. MPP (6 months):	400	400	400	400	400	400	-
B	. Factory Plan:	400	400	400	400	400	400	
	(MPP + Assembly a ± Other) % passi				D - OV	O – Sou	rcing –	OEN
	Explain Other:	y Imo	agn a qu	ipilient				
C	. Date Equipment R	equired	9-9 07	8 9			•	•
	URRENT PLANT CA	_					•	
_	•	TRACII						
	. + Machines:							
			•		•			
C	. Available Hours: _		an Bata i	h # ~ & 11 =			•	
•	(40 * # Shifts * U	LIIIZ B LIC	on Hate.	- - Or On				
. <u>N</u>	IEW CAPACITY	•			•			
A	. # Machines: _	· 						
B	. # of Shifts: _						•	•
C	. Available Hours: _						•	
	(40 * # Shifts * U	tilizatio	on Rate	# # of U	nits)			
. <u> </u>	DDITIONAL OPERA	ATING	FACTO	RS				
A	. Additional Manpo BUDGE: + DL:		NOT	BUDGETE	ED.			
	+ IL:				_	~		
R	. Training Costs (ye	erly).						
	. Operating Costs ();					
	. Is Space Availabl	_						
_	. Maintenance Cost		_					
•	Describe Maintena							
	Dooning maintent	FI	4 11,					
		••		·				
	·							

CAPITAL EQUIPMENT APPROVALS

SAFETY CHECKLIST

EQU	IPMENT ATE FIXTURES MANUFACTURER · WANG
VENI	DOR CONTACT PHONE #
1.	Any chemicals used in the machine/process? MSDS's? Any waste stream?
2.	Excessive noise generated?
3.	Is equipment UL-Listed / FM-Approved for the intended purpose?
4.	Is electr. wiring/grounding equivalent to that req'd for UL listing?
5.	Is equipment movable?
6.	Does equipment plug in, or is it hard-wired?
7.	Any exposed electrics / removable panels for service / self-enclosed?
8.	Any safety interlocks or guards required?
9.	Any pers. prot. eqt. required line., safety glasses, gloves, etc.)?
10.	Any hot surfaces / sharp objects/edges / pinch points?
11.	Material hendling involved with the process? Special eqt./concerns?
12.	Is weight a concern for building structure?
13.	Any special HVAC / venting concerns?
44.	Ja Jacation compatible with adjoining equipment / operations? Any special clearances required?
15.	Does eqt. need to be attended constantly?
16.	Any special training / maint. required? Provided by vendor?
17.	Any special restrictions?
NOI	<u>ES:</u>
	·
	·

.....

---COMPANY CONFIDENTIAL---

TO:

Distribution

FROM

Edmond Daigneault

Production Support/Pilot Engineering

DATE:

September 27, 1989

SUBJECT:

CS386 CPU Revised Test Plan

Attached is a copy of revision B of the Manufacturing Test Plan for the CS386 CPU board. This plan is intended to provide an overview of the proposed test, and repair processes for CS386 project. Originally issued as part of the Manufacturing Engineering Plan, the test plan is being issued as a separate document. Changes were needed as a result of the decision to build and test the boards at Pawtucket Boulevard, and the final systems at Puerto Rico. Your input to this document is requested as this plan will be modified and reissued as details become available.

Please review this plan for the impact of this product on your operation. Direct questions and comments to the Production Support Engineer shown below.

PRODUCT: CS386 CPU

PRODUCTION SUPPORT ENGINEER:

Edmond Daigneault

78635 015-11B

Distribution:

S. Anthony 018-26C K. Azar 018-27C J. Lynch 015-11B T. Mahoney 015-11B M. Negron 015-17B J. O'Hara 018-26C E. Schulz 014-A3A S. Stevenson 015-130

R. Sutton 018-27C D.P. Wilson 018-21F

sod Wns

TEST PLAN CS-386 CPU BOARD

This revised Test Plan will only be concerned with testing after A.T.E. testing has been completed. Full in circuit test fixtures have been provided for both the 210-9561, and the 210-9562 boards, as outlined in Rev A of the M.E.P., distributed on April 11, 1989.

PWA TEST

All boards that pass in circuit test will be tested in the PWA test area. A known good board will be mated with the board under test. Tests used in this area will include the following:

BIT 379-3513R1 or greater. 379-3514R1 or greater. CS386 O.S. Rev. 1.0 or greater. CS386 Customer Diagnostics

Note; CS386 OS and Customer Diagnostics are on the system diskette.

The following is a list of equipment needed for one functional test station, either Pre Test or Final Acceptance.

Test Equipment List

_	Description	QLY	MEI/Model#	<u>Available</u>	_Needed	Cost
	Terminal	1	2436DW		ذ	597.27
	CS-D/N Chassis	1	279-0873			680.59
	Triple Cont.	1	212-3012	•		191.70
	DS. DPU Board	1	212-7113			592.92
	20MB Winch.	1	289-0849			204.95
	360K Floppy	1	289-0846		Total	<u>74.49</u> 2341.92

Substitution of the chassis and disk drives depending on availability would be acceptable as follows:

VLSI Chassis	1	270-1018	524.27
2275-10 Disk	1	187-3505	1019.14
CS System	1	187-3316	962.24
2275-10 Disk	1	187-3505	1019.14

Note: CS system would include cost of 210-8937A CPU board (543.45). CS chassis is not structured separately.

Run-In:

If PCB level run-in of this assembly is required, the following equipment will be needed. Two methods are outlined. Either method will require one setup for each assembly to be run-in. Board level run-in will be required for CSO spares, and system upgrade kits. The board level run-in periods will be as follows.

System boards Spares/Upgrac	_	rnight)	
віт			12
<u>Part Number</u>	Description	Qty.	131
Var i ous	CS, CS-D/N, VLSI chassis	1	20
212-3012	Triple Controller	1	, 2/2/40
187-3249	Workstation	1	
220-0447	Workstation cable	1	(13)
Customer Diag	gnostics		70 3
279-0873	CS-D chassis	1	V
212-3012	Triple Controller	1	$ \{0\}$
187-3249	Workstation	1	60×100 (8)
220-0447	Workstation cable	1	(907)

Run-In Equipment Needs Analysis

289-0849

MP&BM's proposed forecast for the CS386 CPU boards indicates that the average quarterly demand over the next year will average 273 system boards, and 191 spares and upgrades. The following analysis is based on this demand, and the run-in times previously proposed.

20MB Winchester

System	273/Qtr. 21/Week	10 / 17 / 13_	6 5451 EN
Spares/Upgrd	4.2/Day (use 5) 191/Qtr.	210	d' ni
spares/opgi u	14.7/Week 2.9/Day (use 3)	70	SUSTEMS
	Z.7/Day luse 3/	(9)	9 " 07

If 5 run-in systems are made available, a maximum of 10 boards could be run-in per day. This would also provide a cushion, to the availability vs. demand problem.

The prefferred run-in mode is to use the Customer Diagnostics, which are not prom resident. This would mean an increase in the cost of any run-in stations. PSE has calculated that the average cost of a run-in station will be \$2300.40. Remanufactured equipment should be used if possible.

Run-In Equipment List

	<u>Description</u>	QŁY	MEI/Model#	<u>Available</u>	<u>Needed</u>	<u>Cost</u>
	Terminal	1	2436DW			597.27
(1)	CS-D/N Chassis	1	279-0873			680.59
	Triple Cont.	1	212-3012			191.70
(2)	DS. DPU Board	1	212-7113			592.92
(2)	20MB Winch.	1	289-0849			204.95
(2)	360K Floppy	1	289-0846			<u>74.49</u>
					Total	2341.92
Alte	rnate Equipment					
(1)	VLSI chassis	1	270-1018	•		524.27
		1	187-3316	~		418.79
(1)	CS chassis	T				
(2)	2275-10 Disk	1	187-3505			1019.14

Note; Cost of CS chassis was calculated by subtracting cost of 210-8937X CPU board, which is not needed.

Fault Analysis and Repair

All boards that fail pre test, functional test or run-in will be sent to the fault analysis and repair area. Completed units will be routed back to pre test.

Fault Analysis/Repair Station;

<u>Part Number</u>	<u>Description</u>	<u>G</u> F⊼•
None	Modified CS/D chassis	1
212-7113	DPU PCB	1
212-3012	Triple Controller	1
289-0846	360K Floppy	1
289-0849	20MB Winchester	1
289-0905	Tape Cassette Drive	1
187-3249	Workstation	1
220-0447	Workstation cable	1
666-1016	3.5V Lithium battery	1

System Test


System test will follow the same procedure as the present CS-2 or CS-5D/N systems. The only difference will be the Operating System program, and the Customer Diagnostic program.

System Run-In

System Run-In will follow the procedure as outlined in Manufacturing Test Procedure 167/187-3539-3542 (CS386-10N/20N/40N/80N), Run-In/Final Test..

Final Test

If system to be shipped is a CS-N, the final test procedure is as outlined in the System Run-In step. If the system to be shipped is a CS-D, Test Procedure 167/197-3543-3546 (Final Acceptance Test) must also be performed.



WANG LOWELL MASS. U.S.A.		BY	DATE	APPROVED BY	D.
		DWN EVO	948/89	E ENGR	
		CHK		M ENGR	П
MATERIAL	MODEL NO.			MFG ENGR	
	CS386 SEE ENGAG. SPECIFICATIONS	BOARD 7	EST F	LOW (212-712	9X)

WANG MANUFACTURING O657S TEST PROCEDURE				1	12-7129 OF 14/89	9A-D 14
CS386		PART NUMBER 210-9561A-D 210-9562 212-7129A-D		TYPE OF TEST PRETEST/ACCEPTANCE TEST		
APPROVAL	APPROVAL		Al	PPROV	AL	
TECHNICAL WRITER 9-12-89 JUJUNE M. Clark		grant 9/12/89				
9/19/89 PILOT ENGR.						
U	REVI	SION HISTORY	/			-

REVISION HISTORY

1	REV.	DESCRIPTION	SHT.	MPC/ECO	DATE	CHANGED BY
	В	PRELIMINARY DRAFT CHANGES PER ENGINEERING SMALL CHANGE	n/a	n/a		S. CLARK S. CLARK
		Distr. VS Board Area				
	RGW (D3252 10/88	<u></u>	<u> </u>	COMPA	NY CONFIDENTIA

WANG)

MANUFACTURING TEST PROCEDURE

PART NO).				
SHEET	2	OF	14		
DATE	09	09/14/89			

TITLE

CS386 (212-7129A-D)
PRETEST/ACCEPTANCE TEST


1. <u>PURPOSE</u>

- 1.1 To detail the steps necessary when performing a PRETEST/ACCEPTANCE test on the CS386 (212-7129A-D)
- 1.2 This procedure can be used for testing either the 210-9561A-D, or the 210-9562. When testing a 9561 board, a known good 9562 must be used. When testing a 9562 board, a known good 9561 must be used. When assembled, these boards make up the 212-7129A-D assembly.
- 2. REFERENCES
 - 2.1 None required.
- 3. RESPONSIBILITIES
 - 3.1 Refer to <u>GUIDELINES FOR WRITING TEST PROCEDURES</u> (PROC-0009), section 4., for a detailed listing of responsibilities.
- 4. EQUIPMENT REQUIREMENTS

DESCRIPTION	PART NUMBER	QTY.
2436 Workstation	187-3249 or equending on board under te	iv1 st)1
- 360K Flongy	289-0846	
- 20MB Winchester	289–0849	
- DPU PCB	212-7113	<u>1</u>

5. SETUP PROCEDURE

- 5.1 Connect a known good board (210-9562 or 9561) to the board under test (we are now testing a 212-7129A-D).
- 5.2 Verify that the jumper (J5), located on the 210-9561X board, is positioned as shown below:



WANG)

MANUFACTURING TEST PROCEDURE

PART NO.

SHEET 3 OF 14

DATE 09/14/89

TITLE

CS386 (212-7129A-D)
PRETEST/ACCEPTANCE TEST

- 5. <u>SETUP PROCEDURE</u> (cont'd)
 - 5.3 Connect the battery (from test fixture) to location J2 of the 210-9562 board.
 - 5.4 Insert the assembly under test (212-7129A-D) into the CPU position of the test bed motherboard.
- 6. ACTUAL TEST
 - 6.1 Power UP the test bed. The following screen will appear:

COPYRIGHT, WANG LABORATORIES, INC., 1989 REV 5930

SRAM 256KB DRAM XXXXKB LOOP COUNT: XX

- 6.2 Verify that the amount of "D RAM" tested is equal to that expected for the assembly under test (see above). If the amount is less than expected, the assembly has failed.
- 6.3 The following message will appear:

Mount system platter Press Reset

- 6.4 After the LED on the floppy drive has extinguished, press the SHIFT and RESET keys simultaneously (SHIFT/RESET).
- 6.5 The following prompt will appear on the monitor screen:

Key SF?

PART NO. SHEET DATE 09/14/89

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

- ACTUAL TEST (cont'd) 6.
 - 6.6 Press the SFO key. The following screen will appear:

**** SYSTEM SOFTWARE ****

MEMORY 1024 K Select item with SPACE & BACKSPACE. Key RUN to execute, CLEAR or PREV for previous screen TERMINAL 1

Multiuser BASIC-2

. Diagnostics

- 6.7 Select "DIAGNOSTICS". Press the RUN key. The "Customer Diagnostic" screen will appear:
- 6.8 Complete five (5) passes of the test program. When complete, press the SHIFT/RESET keys.
- 6.9 The following message will appear:

Mount system platter Press Reset

6.10 Press the RESET key. The following prompt will appear on the monitor screen:

Key SF?

PART NO.

SHEET

DATE

09/14/89

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

ACTUAL TEST (cont'd) 6.

6.11 Press the SFO key. The following screen will appear:

**** SYSTEM SOFTWARE *****

MEMORY 1024 K Select item with SPACE & BACKSPACE. Key RUN to execute, CLEAR or PREV for previous screen TERMINAL 1

Multiuser BASIC-2

. Diagnostics

WANG:)

MANUFACTURING TEST PROCEDURE

PART NO. SHEET 6 DATE

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

ACTUAL TEST (cont'd) 6.

> 6.12 Select "MULTIUSER BASIC 2". Press the RUN key. The following screen will appear:

> > ***** Multiuser BASIC-2 Partition Generation Program ***** (c) Copr. Wang Laboratories, Inc. 1986, 1987, 1989

0.K. Configuration (#Partitions) (CPU number) current (4) (01)

List of options: '00 - clear partitions

'01 - clear device table

'02 - divide memory evenly '04 - edit partitions

'05 - edit device table

'06 - edit \$MS& '07 - select printer driver

'08 - load configuration

'09 - save configuration

'10 - delete configuration

'11 - edit CPU number

Press FN/TAB to exit

Configuration 'current' loaded. Name of configuration to load?

PART NO).			
SHEET	7	OF	7	
DATE	09	1141	29	

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

ACTUAL TEST (cont'd) 6.

6.13 Press the SF15 key. The following screen will appear:

***** Multiuser BASIC-2 Partition Generation Program ***** (c) Copr. Wang Laboratories, Inc. 1986, 1987, 1989

Available No. of ter PARTITION	rainals	16	CPU number 1 PROGRAMMABLE PROGRAM	'00 -	List of options: clear partitions clear device table
1	150.00	1	Y		
2	150.00	2	Y	'02 -	divide memory evenly
3	150.00	3	Y	'04 -	edit partitions
4	150.00	0	Y	'05 -	edit device table
				'06 -	edit \$MS6
				'07 -	select printer driver
				'08 -	load configuration
				'09 -	save configuration
				'10 -	delete configuration
				'11 -	edit CPU number
				'15 -	execute
		•		Press	FN/TAB to exit

Check configuration. OK to execute (Y or N)?

PART N	0.	
SHEET	8	OF ,4
DATE	0	9/14/89

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

ACTUAL TEST (cont'd) 6.

> 6.14 Press the "Y" key. Press the RETURN key and the following screen will appear:

> > ***** Multiuser BASIC-2 Partition Generation Program ***** (c) Copr. Wang Laboratories, Inc. 1986, 1987, 1989

Available	memory:	1,024 K		List of options:
No. of te		•	CPU nueber 1	'00 - clear partitions
PARTITION	SIZE (K)	TERMINAL	PROGRAMMABLE PROGRAM	'01 - clear device table
i	150.00	1	Y	
2	150.00	2	γ	'02 - divide memory evenly
3	150.00	3	γ	'04 - edit partitions
4	150.00	0	Y	'05 - edit device table
·				'06 - edit \$MSB
				'07 - select printer driver
				'08 - load configuration
				'09 - save configuration
•				'10 - delete configuration
				'11 - edit CPU number
				'15 - execute
				Press FN/TAB to exit

RECONFIGURATION PASSWORD ? SYSTEM

6.15 Press the RETURN key again. The following message will appear: Ready (Basic 2) Partition 01

WANG:

MANUFACTURING TEST PROCEDURE

PART NO).			•
SHEET	9	OF	14	
DATE	09	1.41	189	

TITLE

CS386 (212-7129A-D)
PRETEST/ACCEPTANCE TEST

6. ACTUAL TEST (cont'd)

6.16 Press the LOAD, RUN, and RETURN keys. The following screen will appear:

System Utilities - (c) Copr. Wang Laboratories, Inc. 1989

Select an item and press RUN/EXEC:

Partition 1, 150 K Terminal 1

- # Partition Generator
- # Partition Status
- # Format Disk Platter
- # Move File
- # Backup Platter
- # Recover from Backup
- # System Install
- # Make a Reference List of File Names
- # Initialize Date & Time
- # Vertical Format Control
- # DS Utilities
- # Game

PART NO	ο.		
SHEET	10	OF	14
DATE	0	9/14	1/89

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

ACTUAL TEST (cont'd) 6.

> 6.17 Select "DS UTILITIES". Press the RUN key and the following screen will appear:

> > DS Data Storage Cabinet Utilities (Release 2.0)

Select an item and press RUN/EXEC or press CANCEL/EDIT for previous menu:

Partition 1, 150 K Terminal 1

- # DS Configuration
- # Protect/Unprotect DS Surfaces
- # RAM Disk Allocation
- # Cache Usage
- # Backup Disk Platters to Tape Cassette
- # Restore Disk Platters from Tape Cassette
- # Field Test Unit
- # File Repair
- # Multi-Disk Utility
- # Printer Test

6.18 Select "FIELD TEST UNIT". Press the RUN key. The following message will appear on the monitor screen:

Load all devices to be tested

PART N	0.			
SHEET	//	OF	14	
DATE	0	9/14	1/00	

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

ACTUAL TEST (cont'd) 6.

6.19 Press the RETURN key. The following screen will appear:

2200 FTU (Field Test Unit) Rev. 873E*

					- .	
	Available Addresses		Disk Model		Ending Sector	
>-	340	-< >-	2270a	-< >-	1231	-<
}-	D10	-()-	2200DS FLPm	-(}-	4159	-<
)-	D11	-< >-	2200DS WIN	-< >-	38911	-<
) <u>-</u>	012	-< >-	2200DS WIN	-< >-	38911	-<

Select the address of the device to be tested.

Press: ANY KEY to input parameters CLEAR/PREV SCRN - to exit

SF'O define err RETURN/RUN to cont.

PART NO.

SHEET /2

DATE

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

ACTUAL TEST (cont'd) 6.

6.20 Enter "340" as the address. Press the RETURN key and the following screen will appear:

TEST SELECTION MENU Rev. 873E*

SF 08 - Write Enable SF 01 - Compare Sector(s) SF 09 - Write Lock SF 02 - Compare File SF 10 - Scratch Disk SF 03 - Display a Sector WRITE LOCKED SF 11 - Format Disk SF 04 - Verify SF 05 - Read SF 12 - Write SF 13 - Read After Write SF 06 - Position Head(s) SF 14 - Instruction Test SF 07 - DPU Prom Rev.

Device 340

Start Sector 0 Track 0 Track 76 End Sector 1231 Maximum = 1231 Printer OFF (204, 215, OFF) Loop N (N=No, T=on Test, E=on Error or test) Mode I (I = sequential step In, A = Alternate step) (O = seguential step Out, R = Random step)

Press: ANY KEY to input parameters SF' key listed above SF'O define err CLEAR/PREV SCRN - to exit

- 6.21 Press the SF8 key to "release" WRITE LOCK (WRITE ENABLE). Press the RETURN key.
- 6.22 Using the RETURN key, tab over to "LOOP" and change to "T". Press the RETURN key.
- 6.23 Using the RETURN key, tab over to "MODE" and set to "RANDOM". Press the RETURN key.
- 6.24 Set "RANDOM OPERATIONS" to "1000". Press the RETURN key.

PART NO.					
SHEET /3	OF	14			

09/14/89

DATE

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

- ACTUAL TEST (cont'd) 6.
 - 6.25 Press the SF13 key. Press the RETURN key.
 - 6.26 The RANDOM READ AFTER WRITE TESTS will now run. Allow the test to complete one (1) pass. When complete, press the SHIFT/RESET keys and the following message will appear:

Ready (Basic 2) Partition 01"

6.27 Press the LOAD, RUN, and RETURN keys. The following screen will appear:

System Utilities - (c) Copr. Wang Laboratories, Inc. 1989

Select an item and press RUN/EXEC:

Partition 1, 150 K Terminal 1

- # Partition Generator
- # Partition Status
- # Format Disk Platter
- # Nove File
- # Backup Platter
- # Recover from Backup
- # System Install
- # Make a Reference List of File Names
- # Initialize Date & Time
- # Vertical Format Control
- # DS Utilities
- # Gage
- 6.28 Select "INITIALIZE DATE AND TIME". Press the RUN key.
- 6.29 A clock will appear. Enter the correct DATE and press the RETURN key. Enter the correct TIME and press the RETURN key.
- 6.30 Verify that the clock is running.

WANG:

MANUFACTURING TEST PROCEDURE

PART NO.

SHEET /4 OF /4

DATE 09/14/89

TITLE

CS386 (212-7129A-D)
PRETEST/ACCEPTANCE TEST

- ACTUAL TEST (cont'd)
 - 6.31 Press the SHIFT/RESET keys and power down the test bed.
 - .6.32 Remove the 212-7129A-D assembly. If the board/assembly has passed PRETEST, fill out the appropriate paperwork and send the assembly to the RUN-IN AREA. If the board/assembly has just passed FINAL ACCEPTANCE, send the assembly to STOCK.
 - 6.33 If the board/assembly did not pass, fill out the appropriate paperwork, noting the discrepancy, and send the board/assembly to the REPAIR AREA.

TMD DISTRIBUTION FOR CS 386 CPU BD. MODEL CS 386 TMD# 2380

K. P. R. D. J. V. D. R. T. D. W. B. C. R.	Azar Bean Doris Downing Eno Flynn Foley Gaskell Gibeau Gliksberg Heiner Hondras Iosilevich Jarry LeFebvre Morin Morman Noonan O'Hara Pestana Proulx Quigley Rowlette Seto Scribner Tudisco Tyler	018-27C 018-26F 018-21H 018-27C 019-490 018-27C 018-28B 015-350 025-210 014-B30 018-21I 018-27B 018-21H 018-27B 018-21E 015-130 018-12I 018-26C 018-26C 018-26F 013-490 018-26C 024-290
R. T.	Anthony Dorval Keenan LaMonica Sutton	018-26C 018-28I 018-27B 018-28G 018-27C
CC:E.	Daigneault	015-11B



TEMPORARY MANUFACTURING DEVIATION

Originator E. DAIGNEAULT	Date 9/25/89	M/S 015-11B	Ext. Ref. TMD 78635			
Part Number 209-9561	Description CS 386 Cf	OU BD.	Model CS 386			
ECO Pending?	If yes, ECO#	ECO REQ'D	Temporary Change Only			
SWO or CWO Number SWO or CWO Quantity						
Effectivity Date 9/25/89 Expiration Date 10/25/89						
Affected EPK						
Quantity						

Completely describe deviation including instructions for rework, assembly and test, etc. Include drawings and visual aids as necessary.

CHANGE RESISTOR VALUES AS FOLLOWS;

R12 FROM -330-4021 - RES, 20K5, 14W, 5%. TO -330-2025-RES, 240 14W, 5%

R14 <u>FROM</u> - 330-2025 - RES 24050, 1/4W, 5 % <u>TO</u> - 330-4021 - RES 20KD, 1/4W, 5 %

SEE ATTACHED ECO FOR REASON.

Change E Rev. from 2 to 3 FOR ALL VERSIONS (210 M-B-C-D)

	APPRO	VALS	
Quality Control	Date	Resident Comp. Eng.	Date
R. Leenan	9/36/89		
Material Control	Date	CATA	Date
		·	
Operations Manager	Date	Mfg Engineering	Date
Shuley Doro	al 9/26/89	Kas Juffer	9-25-89
7	1 /01	Jan Canto	9/25/8
V		In Some	als ()

TMD 2380 MODEL NO DWG NO. PART NO. WRITTEN BY ORIGINATOR LEAmond Daigneault Edmond Daigneault 209-9561 Dept007 PER/0213C DESCRIPTION <u>Dept007</u> PCA CS-386 CPU Board M/S N/S 015-11B 115-11B EXT. EXT. ARTWORK HISTORY SHT. 210 HISTORY SHT. 510 DOCUMENTS 78635 ECO NO. DATE DATE SHEET FROM REVISIONS 09/22/89 유

$oldsymbol{\circ}$
M
S
Ô
Ħ
≘
Ų
\overline{c}
ž
0
Ť
_
\mathbf{L}
두
≥
Z
Ō
S

SCHEM DWG.

DRILL DWG. ASSY DWG E-REV.

S.P.I.

SPECIFICATION

CBL DWG.

AREA

CONFORMING

CE

REMFG

DIST.

FINAL ASSY. AREA SUB ASSY. AREA

NEXT ORDER

CLASS

 Ξ

CS-386

Change 209-9561 Parts List and schematics as follows:

Change resistor values as follows:

	WLI #	Description	tion			1	Ref. Des.
ige:	330-2025	Res 240 ohms	ohms	1/4W	%	From To	R14 R12
ige:	330-4021	Res 20K	ohms	1/4W	₩	From To	R12 R14

Chan

Chan

APPROVALS

CONFORMANCE DATE

DATE

	_	
_	T	_
		ECO CHAIRPERSON
2	ı	9
	l	ΣR
•	l	Ĕ
)		SON
ž		
)		
_	I	

MTO DES. ENGRG PP&M MFG. **CUST. ENGRG** J. M. Chrisy

REASON/SYMPTOM FOR CHANGE

Correct problem in operation of LED1 circuit.

PROD. SAFETY


F.C.C.

SECURE SYS.

ORIGINATORE", Jacque and


- RI 33-0912-350-0203-330-4021-330-2025-330-3023-330-4011-330-1048-21-1041-2.20KN 2 CONT 47000N 32.0000 PCA CS-386 CPU BD RES 2200 OHM NETWORK SIP 10 PIN 9 RES BUSS TYPE CONN HDR 2 POS . 100 1 ROW STR PIN RES 10K OHM 1/4W 5% METAL FILM 200 PPM RES 20K OHM 1/4W 5% METAL FILM 200 PPM 2.2K OHM 1/4W 5% METAL FILM 200 PPM ETAL FILM 200 PPM 10/05/88 12:53 07/24/89 08:49 SHEET OF RUN DATE: 07/24/89 08:50 ECO 547520 ECO 547520 BY: JMD · PAGE 1

7MD 2380 7 5. 8



9

SHFFT 6 OF 7 PART NUMBER SIZE DRAWING NUMBER



212-7129A-D PCB Test

Equipment Requirements

Functional Test:

Functional Test/Repair Station;

Description	Qty.	Misc.
Modified CS/D chassis	1	
DPU PCB	1	
Triple Controller	1	
360K Floppy	1	
20MB Winchester	1	
Tape Cassette Drive	1	
Workstation	1	
Workstation cable	1	
3.5V Lithium battery	1	
	Modified CS/D chassis DPU PCB Triple Controller 360K Floppy 20MB Winchester Tape Cassette Drive Workstation Workstation cable	Modified CS/D chassis 1 DPU PCB 1 Triple Controller 1 360K Floppy 1 20MB Winchester 1 Tape Cassette Drive 1 Workstation 1 Workstation cable 1

Run-In:

If PCB level run-in of this assembly is required, the following equipment will be needed. Two methods are reflected here and in the test procedures. Either method will require one setup for each assembly to be run-in.

BIT

Various	CS, CS-D/N, VLSI chassis	1		
212-3012	Triple Controller	1	or	212-3032
187-3249	Workstation	1		
220-0447	Workstation cable	1		
Customer I	Diagnostics			1
279-0873	CS-D chassis	1		
212-3012	Triple Controller	1	or	212-3032
187-3249	Workstation	1		
220-0447	Workstation cable	1		
289-0849	20MB Winchester	1		

Acceptance Test:

Acceptance test will use the same type of equipment as is used in the functional test/ or as is used in the Customer Diagnostic testing at run-in.

CAPITAL APPROPRIATION REQUEST (SEE SCHEDULE "A" FOR SURPLARY)

CS=386 CPU					
PROJECT TITLE:CS-386 CPU	PROJECT NUMBER:				
SECTION 1 - DEFARIMENT DETAIL:	DATE: 09/28/89				
Edmond Daigneault	TEL. Dat.: 78635				
PARTICUTE: 007 PARTICUTE: Parkwood	COST CENTER:6022/6023				
Parkwood	CC MANAGER: Don Monahan				
•	J.O'Hara				
ECTION II - EXPENDITURE SUMPARY: (Attach Sch					
	ARE THERE RELATED REQUESTS? (Y/M) N				
:X10/42:					
	TOTAL PREVIOUS REQUEST: (B) 8				
THEIGHT:	BOOK VALUE OF TRANSFER: (C) 8 REATED EXPENSES: (D) 8				
	(Schedule E - Part 4)				
	TOTAL DELATED EXPENSES. (F) \$				
OTAL REQUEST: (A) \$ 42,285.00	(Add B. C. & D) · 42,285.00				
HOURT BUDGETED:	TOTAL PROJECT SCOPE (A + E) 8				
EDITION III - PROJECT CATEGORY: (Check Only Or	ne)				
	717 a amusaces.				
CAPACITY: TACTION (STD EQUIP) 4. PRODUCTIVE	STRATEGIC:				
L PRODUCTION (SID EQUIF) 1. PRODUCTIVE					
2. OFFICE FUR & FIXTURES REDUCTION B. WANG BUILT EQUIPMENT S. REGULATION	REPLACEMENT PRODUCT TRANSFER				
a. OFFICE AUTOMATION	N/SAFETY 7. NEW PLANT FIT-UP 8. TECHNOLOGY				
b. Business system	DEVELOPMENT				
B. Business stores	UEVELO PRESI				
EDCTION IV - SUPPORTING SCHEDULES					
IF YOU CHECKED 1.3.4. or 6 ABOVE: HEAT IS P.	AYBACK: NPV: IRR:?				
(SCHEDULE C)					
F TOU CIDCOD 6. 7 OR 8 ATTACH SUPPORT OF	STRATEGIC/COST ADVANTAGES. (SCHEDULE D)				
P IP YOU CHECKED 1 OR 6 ATTACH PROXICTION FACT SHEET. (SCHEDULE E)					
IF YOU CHECKED 4 OR 8, COMPLETE GILY PART 4					
IS EQUIPMENT ON PLANT "STANDARDS" LIST (Y/N)? IF NO. PLEASE ATTACH EQUIPMENT				
CHECK-OFF LIST. (SCHEDULE F)					
IF TOOLDES IS PART OF REQUEST ATTACK SCHEDU	— •				
	TECHNOLOGY JUSTIFICATION ANALYSIS. (SCHEDULE H)				
IF YOU CHECKED 6 (PRODUCT TRANSFER) ATTACH	EQUIPMENT TRANSFER CHECKLIST. (SCHEDULE I)				
ECTION V - SIGNATURES:					
	_ • •				
REVIEW DATE	APPROVAL DATE				
DETELL CAPITAL FURCHASING	DIRECTOR				
THE EXIMERING	FINANCE (PER AUTHORIZATION POLICY)				
	AREA VP (UNDER 100K)				
570					
CUB-CORNITIEE CHAIRPERSON	CAPITAL COMMITTEE (FINANCE VP)				
THERS	EXECUTIVE VP (OVER \$250.000)				
COTE: IP REVIEWER DOES KOT CONTUR WITH COPOSAL FLEASE FUT AM ASTERISK (*) EESIDE	VICE CHAIRMAN				
HOWATHE AND ATTACH SUPPRINT OF CONTERNS					
LID RESERVATIONS. CTHERRISE, SIGNAURE	PEQUIPMENT OVER \$1.000.000. ALL EVILDING				
EPPERITS AGREEMEN WITH PROPOSAL.	IMPROVEMENTS. LAND & EVILDING OVER \$ 250,000.				
	1				

Capital Appropriation Request Package Executive Summary Sheet

Project Title: CS-386 CPU

Project Number:			Date:	09/28/89	
Department Name:	New Product Int	roduction	Department	007	
Requestors Name:	Edmond Daigneau	lt	Telephone E	xt.	78635
Executive Summary:	(The objective o	f the P	rogram or Pr	oject)	
The CS-386 CPU h 1. Improve CS (2. Create CS/220 technology. 3. Enable the CS performance leve	CPU performance 00 look alike sy 3 system to hand	by up to stem tha le 16 us	sers at the		
Capital Spending Requ	uest Summary:				
A.) Outside Vendor Pr	urchases:	\$		(exc.Too	ling costs)
B.) Wang Serialized	Equipment:	\$	14,085.00	(at WLI	MFG. COST)
C.) Tooling Expendit	ures:	\$			
D.) Other:		\$			
E.) ATE:		\$	28,200.00		
F.) CTE:		\$			
G.) Total Cash Outfle	ow(A+B+C+D+E+F):	\$	42,285.00	Exchange	Rate
H.) Domestic Mfg. Tr	ansfers In:	\$			
I.) International Mfc	g. Transfers In:	\$		Exchange R	ate
J.) Total Related Pro	evious Requests:	\$			
K.) Total Project Sc	ope: (G+H+I+J)	\$	42,285.00		
Finance Methods in E	valuating Capita	ıl Proje	cts:		
Capital Budget Amoun	t \$	•			
NPV	/ IRR		PAYBACK		
TOTAL CASH OUTSLOW R	V OHARTER: O1 \$	(O2 \$	03.5	04 \$



TECHNICAL SUMMARY/NEEDS ANALYSIS

Most of the cost in this request is for two In Circuit Test fixtures. One fixture will test the 210-9561 PCB. The other will test the 210-9562 PCB. These toards make up the 212-7129A-D assemblies. These assemblies will be the CPU board set for CS386 1MB thru 8MB systems.

These fixtures will be used to detect process related and other defects before they are passed on to the test technicians. It is anticipated that this will increase the first pass yield at Pretest by at least 25%. This will decrease the amount of technician repair time required.

Also included is the cost of remanufactured 2200 equipment to be used as test stations for board run-in. Five systems have been requested to cover CSO spares, and upgrade kits which will ship out of Pawtucket Boulevard. This amount of stations should also allow run-in of system boards if P.B. desires.



EXPENDITURE DETAIL LIST (ATTACH PURCHASE, CONSIGNMENT, ATE FIXTURE, CTE, REQS. HERE)

		PART/	me		. EXTENDED COST		_	
	ITEM DESCRIPTION	MODEL +	COST	QTY	VENDOR	CONSIGN MFG COST	OTHER WANG BULLT	G.L. • *
1-	In Circuit Test Fixture 210-9561 In Gircuit Test	F89-057	1410	1			14100	14100
2.	Fixture 210-9562					•	14100	14100
3.	CS2 System	187-3315	962	5	•	4810		4810
4.	Terminal	187-3249 2536DW	597	5		2985		2985
5.	Triple Controller	212-3012	191	· 5		955		955
6.	Disk System .	187-3505 2275-10	1019	5		5095	·	5095
7.	Disk Cable .	220-0365	38	5		190 .	·	190
8.	Terminal Cable	220-0447	10	5		• 50		50
9.	·	·					•	
10.	·		·	,				•
11.							٠	
12.								
13.								
14.								
15.						·		
16.								
17.								
18.				·				•
	τ	OTAL EQU	IIPMEI	VT:		14,085	28,200	\$ 42,285
					(VENDOR)	CONSIGN	(OTHER)	



STRATEGIC/COST ADVANTAGE ANALYSIS

(Describe Below As Appropriate)

STRATEGIC: locational advantages, grants, second builder of product, closeness

to markets, etc.

COST FACTORS: economic/cost advantages of approach versus alternatives

considered (used in place of payback when relationship to cash

inflow is not direct).

The use of the requested In Circuit test fixtures will increase the first pass yield at the Pretest station by an estimated 25%. This increase will result in lower costs. This will come from using less costly labor to detect the bulk of the defects.

Since the bulk of the defects detected will be manufacturing problems, detecting these problems early will facilitate information feedback to correct repetitive problems. This will further reduce labor costs.

The run-in stations will enable Wang to detect latent process defects that would otherwise be detected at the customers site.

Cost Analysis:

PP&M has predicted sales of 1800 CS386 cpu boards per year. This will be 1000 boards for new systems, and 800 boards for system upgrades. Since there is a minimum of 4 system types, and 4 upgrade types available, the costs were averaged.

Systems:	Average Cost	Average Sale Price
	2507.00	9250.00
GPM	73%	6743.00
Upgrade	1656.00	5375.00
GPM ·	69%	3719.00
Payback (Systems)	= Cost of test equ = 42,285/6743 = 6.	ipment/GPM. 27 Systems
Payback (upgrade)	= Cost of test equip = 42,285/3719 = 11	pment/ GPM .36 upgrades

REQUEST FOR A.T.E. FIXTURES AND PROGRAMS

	eering
PROJECT \$REQUE	ST #
REQUESTOR SUPPLIED INFORMATION:	
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
22 4 5 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	09-30/
BRD/ASSY PART # 210-9561 FOR SUP	PORT OF: C3 366
BRD/ASSY DESCRIPTION: <u>C5-386 CPU</u>	DATE REQ'D JUNE 89
REASON FOR REQUEST: NEW PRODUCT:	MPP REV.
VOLUME: 450 01 FY 90: 450 02 FY 90: 46	50 03 FY'90: 450 04 FY' 90
REQUEST FOR: PROGRAM V FIXTURE V NEW V	DUPLICATE UPGRADE
TYPE OF TEST: BARE BOARD IN-CIRCUIT \( \bullet \)	LOADED BOARD EMULATION
FUNCTIONAL OTHER	· · · · · · · · · · · · · · · · · · ·
EQUIPMENT TYPE: FAIRCHILD STD V ECL _ S	MD _ ESTIMATED COST: \$ 4 100
FIX. SIZE: S_ M L XL O_ BOARD DIM	ensions:x
COMMENTS:	
	, ,
REQUESTOR: E.DAIGNEAULT EXT: 7863	5 M/S: 015-118 DATE: 4/12/89
***********	*****
TEST ENGINEERING SUPPLIED INFORMATION:	
JUSTIFICATION OF SELECTION OR REJECTION:	
SPECIAL PROGRAMMING CONSIDERATIONS:	
· · · · · · · · · · · · · · · · · · ·	<del></del>
**********	*****
RDB RECEIVING EQUIPMEN	T:
	~
APPROVAL:	
PRODUCT ENG. MGR. W.D. Collins TEST  A.T.E	STRATEGY THE TOPE STRATEGY THE
SR. BUSINESS/ DIRECT	
FINANCE // DIRECT	TOR / /
***********	********
A.T.E. SUPPLIED INFORMATION:	DATE REC'D:/
,	
S/N FIM - 1606 PROJE	CT TRACKING NO <u>F-89-057</u>

### REQUEST FOR A.T.E. FIXTURES AND PROGRAMS

FINANCIAL	ENGINEERING
PROJECT :	REQUEST #
REQUESTOR SUPPLIED INFORMATION:	
BRD/ASSY PART # 210-9562 FO	R SUPPORT OF: <u>CS-386</u>
BRD/ASSY DESCRIPTION: CPU DAUGHTER	
REASON FOR REQUEST: NEW P2000C	7 MPP REV.
VOLUME: 450 0/ FY.90: 450 02 FY.90	): 450 03 fy'90: 450 04 fy'90
REQUEST FOR. PROGRAM 1 FIXTURE.	IEW — DUTLICATE OPGRADE
TYPE OF TEST: SARE BOARD IN-CIRCUIT	LOADED BOARD EMULATION
FUNCTIONAL OTHER	
EQUIPMENT TYPE: FARCHILD STD V ECL	_ SMD _ ESTIMATED COST: S /H, 100,60
FIX. SIZE: S M V L XL O BOA	RD DIMENSIONS: $3.50 \times 11.25$
COMMENTS:	
REQUESTOR: <u>FD. DAIGNEAU-1</u> EXT: <u>78</u>	635 M/S:015-118 DATE: 4/12/89
TEST ENGINEERING SUPPLIED INFORMATION:	
JUSTIFICATION OF SELECTION OR REJECTION:	
SPECIAL PROGRAMMING CONSIDERATIONS:	
RDB RECEIVING EC	paakaanaakaanaanaanaanaanaanaanaanaanaana
APPROVAL:	
PRODUCT ENG. MGR. W.D. Collen	TEST STRATEGY SINK GICKY 5,1,69 A.T.E. OPERATION WWW.711,571/89
SR. BUSINESS// FINANCE/	DIRECTOR//_
A.T.E. SUPPLIED INFORMATION:	DATE REC'D://
s/n <u>FIB-1607</u>	PROJECT TRACKING NO <u>F89-058</u>



# PRODUCTION FACT SHEET (ATTACH SUPPORTING DOCUMENTATION HERE AS NECESSARY)

1.	PR	ODUCTION SCHE	DULE		•		MPP R	EV +:
	A.	MPP (6 months):	400	400	400	400	400	400
		Factory Plan:	400	400	400	400	400	400
		(MPP + Assembly / ± Other) % passin				D - OV	O — Soul	rcing — OEI
		Explain Other:	LAFOL	- An Adai	P.III E III E			
		Date Equipment R	e quire d	<b>9</b> 07	<b>4</b> 9			•
2.		RRENT PLANT CA			<del></del>			•
-•		+ Machines:		<del>-</del>				
		+ of Shifts:						
		Available Hours: _	<del></del>			•		
	_,	(40 * + Shifts * U	tilizatio	n Rate 4	+ of Un	its)		•
3.	NE	W CAPACITY		-		<b>-</b>		
_•	ئے۔ ھ	+ Machines:	,			•		
	B.	+ of Shifts:						•
		Available Hours: _						
	~ <del>-</del>	(40 * + Shifts * U	tilizatio	n Rate!	+ of Un	ilts)		-
4.	AD	DDITIONAL OPERA	ATING	FACTO	RS	•		
	A.	Additional Manpo	wer					
		BUDGE		NOT E	BUDGETE	:D		
		+ DL:		•		_	-	
		+ IL:	· · ·	-		_		
	B.	Training Costs (ye	arly):	<b>s</b> _				
	C.	Operating Costs (	yearly).	: \$_				
	D.	Is Space Availabl	e? [Y/	N): _		·		
	E.	Maintenance Cost	s (year	ly): \$_				
	-	Describe Maintena	ince Pla	9n:	_			

### CAPITAL EQUIF MENT APPROVALS

### SAFETY CHECKLIST

EQUI	MUIPMENT ATE FIXTURES MANUF	ACTURER · WANG
VEND	ENDOR CONTACT PHONE	#
1.	Any chemicals used in the machine/pro	cess? MSDS's? Any waste stream?
2.	Excessive noise generated?	
3.	Is equipment UL-Listed / FM-Approved	for the intended purpose?
4.	Is electr. wiring/grounding equivalen	t to that req'd for UL listing?
5.	Is equipment movable?	
٥.	Does equipment plug in, or is it hard	-wired?
7.	Any exposed electrics / removable pan	els for service / self-enclosed?
8.	Any safety interlocks or guards requi	red?
9.	Any pers. prot. eqt. required lime.,	safety glasses, gloves, etc.)?
10.	). Any flot surfaces / sharp objects/ed	ges / pinch points?
11.	l. Heterial hendling involved-with the p	rocess? Special est./concerns?
12.	2. Is weight a concern for building stru	cture?
13.	3. Any special HVAC / venting concerns?	
44	<b>L le location compatible with adjoi</b> special clearances required?	ning <u>equipme</u> nt / operations? Any
15.	5. Does eqt. n <b>eed to be attended const</b> ar	tly?
16.	<ol><li>Any special training / maint. require</li></ol>	d? Provided by vendor?
17.	7. Any special restrictions?	

NOTES:



# TECHNICAL SUMMARY/NEEDS ANALYSIS

Most of the cost in this request is for two In Circuit Test fixtures. One fixture will test the 210-9561 PCB. The other will test the 210-9562 PCB. These boards make up the 212-7129A-D assemblies. These assemblies will be the CPU board set for CS386 LMB thru 8MB systems.

These fixtures will be used to detect process related and other defects before they are passed on to the test technicians. It is anticipated that this will increase the first pass yield at Pretest by at least 25%. This will decrease the amount of technician repair time required.

Also included is the cost of remanufactured 2200 equipment to be used as test stations for board run-in. Five systems have been requested to cover CSO spares, and upgrade kits which will ship out of Pawtucket Boulevard. This amount of stations should also allow run-in of system boards if P.B. desires.

Capacity Analysis:

Average total 212-7129 per quarter = 464

Total run-in hours available per quarter; 13 weeks x 5 days x 24 hours = 1560 hours

Capacity of one station = Available hrs./Run-in period. Capacity = 1560/12 = 130 boards per quarter.

Test stations needed = 464 boards/130 boards = 3.56 stations Four (4) test stations is the minimum needed.

The fifth test station is being requested to provide a cushion to the availability vs demand problem in both the run-in and functional test area.



# CAPITAL EQUIPMENT CHECK-OFF LIST

				Fairchild	based In C	ircuit fixt	tures.	
					s and suppo			
MAN	UFA	CTURER: _W	ANG		PART NO./M	odel no:	See Sched	ule B
RES	PON	SIBLE ENGI	NEER <u>ed Da</u>	igneault -	DSF / Stav	e Anthony	- Site	
NOTE	R		ER FOR SIGI		TE ENGINEE! MS III, IY AN			
	D	ATE:	SIGNATU	RE:	NT SAFETY EN	CINCER	_ (SEC. 亚)	
	n	ATE.	SIGNATU				_ (SEC. IX)	•
•			_		MAINTENANCE			•
	D	ATE:	SIGNATU	RE: ELECTRON	IIC MAINTENAI	NCE ENGINE	(SEC. Y)	
			•					
L	ACC	CEPTANC	E OF EQL	JIPMENT		•	YES	NO
	A.	is equipme	ent accepta	ance require	d?			
	•	•	•	required?		•		
			•		ition establi	shad?		
			•	= .			<del></del>	
	D.	is there are (if "yes", h	"in-Plant" : ow long? _	time trial pr	ior to final e	icceptance )	7	
	E.	-	al payment of u	•	sted to be (	compatible		
		(if "yes",	explain:					
			<del></del>		<del> </del>	)		
IL.	VE	NDOR SE	RVICE OF	EQUIPME	NT		/	' A ·
	A.	is vendor	warranty ac	cceptable?			<u> </u>	<u>/</u>
•		If "no", do	_	ave an altei	native warra	inty that		
		Explain: _	•		<del></del>			
		•	· · · · · · ·		••			
	8.	_	require ven		of operato	ers or	•	

## CAPITAL EQUIPMENT CHECK-OFF LIST - Page 3

VI.	PROCUREMENT DEPARTMENT.					
	A.	WIII terms and conditions of P.O. be accepted?	•			
	B.	Does vendor supply other Wang facilities?				
	C.	Is vendor planning or in process of revising current model?				
	D.	Are quotes on file for this equipment?				
	E.	Has a D & B report been done?				
	F.	is vendor survey required?				
	G.	Does requisitioner request special shipment of materials?				
	H.	Are special shipping instructions required from Traffic Department?				
		If "yes", explain:				

# CAPITAL EQUIPMENT CHECK-OFF LIST - Page 2

			YES	NO
	C.	Will vendor supply all manuals required, including spare parts list?	N	A
		(How many copies?)		
Ш.	PL/	ANT SAFETY ENGINEERING		
	A.	Will this equipment be guaranteed to meet applicable OSHA standa::ds?		
	B.	Are either UL or FM approvals required?		
	Ċ.	Would use, or installation, of this equipment conflict with safety or health practices established for Local Area Operations?		
V.	PL	ANT MAINTENANCE ENGINEERING		
	A.	Will vendor install equipment?		
•	B.	Will equipment require plumbing, wiring, air system, etc.?		
		if "yes", are these "expense type" items on order?		
	Ċ.	Are all specifications for installation available?		
	D.	Will equipment require riggers?		
	E.	Electrical specifications of equipment.  Voltage CY PH		
V.	ELE	CTRONIC MAINTENANCE AND CALIBRATION		•
	<b>A.</b>	Does equipment cost exceed \$10,000 and does this equipment contain electronics?		
•		(If "yes", continue)		4
		1. Will equipment require scheduled calibration?		<u>~</u>
		2. Has cost of electronic spare parts been budgeted?  (If "yes", how much? \$		
		3. How long is this equipment under warranty?		
		4. Vill equipment require a maintenance agreement after warranty?		V
	•	Of "yes", has the requirement been budgeted?)	<del></del>	



TO:

DISTRIBUTION

FROM:

JOHN R. LYNCH - NEW PROD ENG. MGR. - M/S 015-11B - (508) 967-8160

RE:

NEW PRODUCT TRANSFER

DATE:

OCTOBER 3, 1989

******************

ATTACHED IS A COPY OF THE MANUFACTURING ENGINEERING TRANSFER PACKAGE FOR THE CS-386 COMPUTER SYSTEM (210-9561/9562), WHICH HAS COMPLETED THE PILOT PHASE AND IS TRANSFERRING TO MAINSTREAM MANUFACTURING. PLEASE HAVE THE RESPONSIBLE ENGINEERS WITHIN YOUR GROUP REVIEW THE CONTENTS, SIGN THEIR APPROVAL, AND RETURN A COPY OF SIGNED COVER SHEET TO ME WITHIN 30 DAYS FROM RECEIPT. CALL ME OR SEND WANG OFFICE, TO ADD ADDITIONAL OUTSTANDING ISSUES IF NECESSARY. ANY OUTSTANDING ISSUES WILL BE MONITORED AND DATED WHEN COMPLETE.

THE NEW PRODUCT ENGINEER FROM PARKWOOD WILL PROVIDE IMMEDIATE SUPPORT FOR THIS PRODUCT IF REQUIRED FOR THE NEXT 30 DAYS. BEYOND THAT POINT, THE PRODUCTION SUPPORT ENGINEER WILL PROVIDE SUPPORT WHEN REQUIRED.

### DISTRIBUTION:

BILL QUIGLEY - PB FA&T ENG SR.MGR CLAUDE PIOTTE - PB PCB ASSEMBLY & TEST REP PHIL DORIS - PRODUCTION SUPPORT ENG. MGR.

CC: (COVER MEMO AND CONTENTS LIST ONLY)

RICHARD DOWNING SCOTT STEVENSON SIGNATORIES



# MANUFACTURING ENGINEERING TRANSFER PACKAGE

PRODUCT: <u>CS 386</u>	TRANSFERRING TO: P.B. 10/3/8
I HEREBY CONFIRM THAT MY ARE EXCEPTIONS ARE NOTED ON ATTACE	EA OF RESPONSIBILITY IS COMPLETE AND ACCURATE. ANY ED OUTSTANDING ISSUES LIST:
SENDING SITE FUNCTION	NAME/PRINT SIGNATURE DATE
MFG. PROGRAM MANAGER:	MAINY NECTON Mampallegn 9/13/8
TEST MFG. ENGINEER:	ED DANGHEAULT D Jacquet 9/2489
MECH/ASS'Y MFG. ENGINEER:	Tom MAHONEY ( for Mahoney 9/25/89
PCB PROCESS ENGINEER:	"
QUALITY CONTROL ENGINEER:	
PCB DOC. COORDINATOR:	JOYCE LANGAN JULI JANGAN 4
ASS'Y/TEST DOC. COORDINATOR:	SUE CLARK Jul Clark 9-14-8
ATE/CTE COORDINATOR:	MARIA DERY Maria Dery 9/13/89
WANG/VENDOR EQUIPMENT COORD.:	DOTRI ALBERT PROPOULAS
I HAVE REVIEWED THE TRANSFER EXCEPTIONS NOTED ON ATTACHED	PACKAGE AND HEREBY ACCEPT ITS CONTENTS WITH OUTSTANDING ISSUES LIST:
RECEIVING SITE FUNCTION	NAME/PRINT SIGNATURE DATE
PRODUCTION SUPPORT ENG.	
ASSEMBLY TEST ENGINEER:	
ASSEMBLY MFG ENGINEER:	
PCB PROCESS ENGINEER:	
PCB TEST ENGINEER:	
PCB QUALITY ENGINEER:	
FINAL QUALITY ENGINBER:	
PCB DOC. COORDINATOR:	



### TRANSFER PACKAGE CONTENTS

I.

ASCEMBLY WINO'S	PROCESS SHEETS/	TEST PROCEDURES	RUN-IN FIME
210-95-61)	CAM DATA	PRE-MISS MURO	Bur-
210-9561 210-9562	SENT 9/15/89	Run-In	
212-7129-ABC,I			
167/187-3543-3546		FINAL ACCUSA	WCB_
167/187-3539-3542	2 YES	FINAL ACCESSA	_6HR
		, 	
1 12			
	1 11		
			-
	• • •		

WANG

### TRANSFER PACKAGE CONTENTS

II.	TRANSFER FILE	<u>Y</u> ES	NO	COMMENTS
<u>i</u> )	UL APPROVAL MEMO:		K	M/A
2)	CSA APPROVAL MEMO:			NA
3)	IEC APPROVAL MEMO:			N/A
4)	FCC PT. 15 (A OR B) APPROVAL MEMO:			CLASS A 8/24/89 (WHINDOW)
5)	FCC PT. 68 APPROVAL MEMO:		V	N/A
6)	VDE APPROVAL MEMO:		<u> </u>	NA
7)	ESD TEST RESULTS:		<u> </u>	SEE ISSUES LIST
8)	CS-03 APPROVAL MEMO:		<u> </u>	<u> </u>
9)	ENVIRONMEMTAL TEST RESULTS:			SEE ISSUES LIST
10)	ACCOUSTICAL TEST RESULTS:			N/A
11)	PACKAGING DATA ANNOUNCEMENT:	<u>/</u>		9/5/89 (Mrs Tan)
12)	THEORY OF OPERATION:		<u> </u>	Plantin
13)	TEST STRATEGY:	_/		4/11/89 (DAICHAGUIT) 9/27/89
14)	ENG. REVIEW BULLETIN REV 2:			
15)	P.R.S. REPORTS:			
16)	PCB MANUFACTURABILITY REVIEW	i: <u>/</u>		5/2/89 (T. mAHENTY)
17)	ITEM STATUS ECO:	_/		9/11/89 (T. m Antoniby)
18)	QUALITY AUDIT REPORT:	• ••		
19)	YIELD REPORTS:			
20)	QVL REPORT:			
21)	100% 1st PIECE INSP. REPORT:	:	_ <u> </u>	N/A
22)	UNIQUE PARTS REVIEW LIST:			NA
23)	DEVIATION NOTICES:			~/A
24)	DIAGNOSTIC SOFTWARE:			
25)	OPER SYS SOFTWARE:			RMASSED



### TRANSFER PACKAGE CONTENTS

III. ATE STATUS:

PCB #	SYSTEM COVERAGE	BMK YIELDS	RELEASE DATE TO MFG. SITE	COMMENTS	
	Fairchied	85 %	9/15/89 8/24/89	Waiting for tach Re	rsult
IV. CTE STAT	us:  DESCRIPTION  N/A		RELEASE DATE TO MFG. SITE	COMMENTS	
DESCRIPTION  VS U	OR EQUIPMENT S	QUANTITY	RELEASE DATE TO MPG. SITE  9 18 89	COMMENTS	
	il cars	1 10	9/18/89		
VI. WAVE SOL	DER FIXTURES/S	MT STENCILS S	RELEASE DATE TO MFG. SITE	COMMENTS	

WANG

### TRANSFER PACKAGE CONTENTS

VII. OUTSTANDING ISSUES LIST:

1) P.B. FAST WILL USE 21 CS-N SYSTEM
TO DO RUY -IN OF BOARDS SHIPPED AS
UPCRADES - UNTIL P.R. COMBS BACK ON
LINE ED DAIGNEAUT
2.) CS-386 HAS NOT COMPLETED ESD AND
ENVIRONMENTIAL TESTING AS OF 10/3/89.
3.) 2 PARTS NOT ON QUL - JOHN TIGHTE

4.77

trans rev 5

PART NO. WANG) MANUFACTURING 212-7129A-D SHEET OF 1 14 TEST PROCEDURE 06575 DATE 09/14/89 TITLE PART NUMBER TYPE OF TEST PRETEST/ACCEPTANCE TEST CS386 210-9561A-D 210-9562 212-7129A-D APPROVAL **APPROVAL APPROVAL** TECHNIGAL WRITER 9-12-89 PRODUCT SUPT. ENGR. BEVIEW PILOT ENGR.

## REVISION HISTORY

REV.	DESCRIPTION	SHT.	MPC/ECO	DATE	CHANGED BY
В	PRELIMINARY DRAFT CHANGES PER ENGINEERING SMALL CHANGE	ņ/a	n/a		S. CLARK S. CLARK
				-	-
867	Distr. VS Board Area				NY CONFIDENTIA

RGW 03252 10/88

COMPANY CONFIDENTIAL

PART NO.						
SHEET	2	OF	14			
DATE	09	7/14/	189			

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

### 1. **PURPOSE**

- 1.1 To detail the steps necessary when performing a PRETEST/ACCEPTANCE test on the CS386 (212-7129A-D)
- 1.2 This procedure can be used for testing either the 210-9561A-D, or the 210-9562. When testing a 9561 board, a known good 9562 must be used. When testing a 9562 board, a known good 9561 must be used. When assembled, these boards make up the 212-7129A-D assembly.

### 2. **REFERENCES**

2.1 None required.

### 3. RESPONSIBILITIES

3.1 Refer to <u>GUIDELINES FOR WRITING TEST PROCEDURES</u> (PROC-0009), section 4., for a detailed listing of responsibilities.

### **EQUIPMENT REQUIREMENTS** 4.

DESCRIPTION	PART NUMBER	QTY.
2436 Workstation	nding on board under tes	St)1
- 360K Flonny	289-0846	1
_ 20MR Winchester	289-0849	1
- DPU PCB	212-7113	1
- MXE Controller	212-3032	<u>1</u>

### 5. SETUP PROCEDURE

- 5.1 Connect a known good board (210-9562 or 9561) to the board under test (we are now testing a 212-7129A-D).
- 5.2 Verify that the jumper (J5), located on the 210-9561X board, is positioned as shown below:





TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

- 5. SETUP PROCEDURE (cont'd)
  - 5.3 Connect the battery (from test fixture) to location J2 of the 210-9562 board.
  - 5.4 Insert the assembly under test (212-7129A-D) into the CPU position of the test bed motherboard.
- ACTUAL TEST 6.
  - 6.1 Power UP the test bed. The following screen will appear:

COPYRIGHT, WANG LABORATORIES, INC., 1989 REV 5930

SRAM 256KB DRAM XXXXKB LOOP COUNT: XX

- 6.2 Verify that the amount of "D RAM" tested is equal to that expected for the assembly under test (see above). If the amount is less than expected, the assembly has failed.
- 6.3 The following message will appear:

Mount system platter Press Reset

- 6.4 After the LED on the floppy drive has extinguished, press the SHIFT and RESET keys simultaneously (SHIFT/RESET).
- 6.5 The following prompt will appear on the monitor screen:

Key SF?

PART NO. SHEET DATE

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

6. ACTUAL TEST (cont'd)

6.6 Press the SFO key. The following screen will appear:

**** SYSTEM SOFTWARE *****

MEMORY 1024 K Select item with SPACE & BACKSPACE. Key RUN to execute, CLEAR or PREV for previous screen TERMINAL 1

### # Multiuser BASIC-2

### . Diagnostics

- 6.7 Select "DIAGNOSTICS". Press the RUN key. The "Customer Diagnostic" screen will appear:
- 6.8 Complete five (5) passes of the test program. When complete, press the SHIFT/RESET keys.
- 6.9 The following message will appear:

Mount system platter Press Reset

6.10 Press the RESET key. The following prompt will appear on the monitor screen:

Key SF?

PART NO.			
SHEET 5	OF	14	
DATE	09/1-	4/89	-

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

6. ACTUAL TEST (cont'd)

6.11 Press the SFO key. The following screen will appear:

**** SYSTEM SOFTWARE ****

MEMORY 1024 K Select item with SPACE & BACKSPACE. Key RUN to execute, CLEAR or PREV for previous screen TERMINAL 1

# Multiuser BASIC-2

. Diagnostics

PART NO. SHEET DATE

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

6. ACTUAL TEST (cont'd)

> 6.12 Select "MULTIUSER BASIC 2". Press the RUN key. The following screen will appear:

> > ***** Multiuser BASIC-2 Partition Generation Program ***** (c) Copr. Wang Laboratories, Inc. 1986, 1987, 1989

0.K. Configuration (#Partitions) (CPU number) current (4) (01)

List of options: '00 - clear partitions

'01 - clear device table

'02 - divide memory evenly '04 - edit partitions

'05 - edit device table

'06 - edit \$MSB

'07 - select printer driver

'08 - load configuration

'09 - save configuration

'10 - delete configuration

'11 - edit CPU number

Press FN/TAB to exit

Configuration 'current' loaded. Name of configuration to load?

PART NO	).			
SHEET	7	OF	7	
DATE	09	14/	139	

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

6. ACTUAL TEST (cont'd)

6.13 Press the SF15 key. The following screen will appear:

***** Multiuser BASIC-2 Partition Generation Program ***** (c) Copr. Wang Laboratories, Inc. 1986, 1987, 1989

Available	memory:	1,024 K		List of options:
No. of te	rainals	16	CPU number 1	'00 - clear partitions
PARTITION	SIZE(K)	TERMINAL	PROGRAMMABLE PROGR	AM '01 - clear device table
i	150.00	1	Y	
2	150.00	2	Υ	'02 - divide memory evenly
3	150.00	3	Y	'04 - edit partitions
4	150.00	0	Y	'05 - edit device table
				'06 - edit \$MSB
				'07 - select printer driver
		•		'08 - load configuration
				'09 - save configuration
				'10 - delete configuration
				'11 - edit CPU number
				'15 - execute
				Press FN/TAB to exit

Check configuration. OK to execute (Y or N)?

PART NO.						
SHEET	8	OF 4				
DATE	0	19/14/89				

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

- 6. ACTUAL TEST (cont'd)
  - 6.14 Press the "Y" key. Press the RETURN key and the following screen will appear:

***** Multiuser BASIC-2 Partition Generation Program ***** (c) Copr. Wang Laboratories, Inc. 1986, 1987, 1989

Available No. of ter PARTITION	minals	16	CPU number   I PROGRAMMABLE		List of options: - clear partitions - clear device table
1	150.00	1	Y		
2	150.00	2	Υ	'02	- divide memory evenly
3	150.00	3	Y	'04	- edit partitions
4	150.00	0	Y	'05	- edit device table
				'06	- edit \$MS6
				'07	- select printer driver
				'08	- load configuration
				'09	- save configuration
				' 10	- delete configuration
				'11	- edit CPU number
					- execute
				Pres	ss FN/TAB to exit

RECONFIGURATION PASSWORD ? SYSTEM

6.15 Press the RETURN key again. The following message will appear: Ready (Basic 2) Partition 01

PART NO.						
SHEET	9	OF	14			
DATE	09	1.41	199			

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

6. ACTUAL TEST (cont'd)

> 6.16 Press the LOAD, RUN, and RETURN keys. The following screen will appear:

> > System Utilities - (c) Copr. Wang Laboratories, Inc. 1989

Select an item and press RUN/EXEC:

Partition 1, 150 K Terminal 1

- # Partition Generator
- # Partition Status
- # Format Disk Platter
- # Move File
- # Backup Platter
- # Recover from Backup
- # System Install
- # Make a Reference List of File Names
- # Initialize Date & Time
- # Vertical Format Control
- # DS Utilities
- # Game

PAI	RT NO	ο.			
зн	EET	10	OF	14	
DA	TE	0	9/14	1/89	

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

6. ACTUAL TEST (cont'd)

> 6.17 Select "DS UTILITIES". Press the RUN key and the following screen will appear:

> > DS Data Storage Cabinet Utilities (Release 2.0)

Select an item and press RUN/EXEC or press CANCEL/EDIT for previous menu: Partition 1, 150 K Terminal 1

- # DS Configuration
- # Protect/Unprotect DS Surfaces
- # RAM Disk Allocation
- # Cache Usage
- # Backup Disk Platters to Tape Cassette
- # Restore Disk Platters (rom Tape Cassette
- # Field Test Unit
- # File Repair
- # Multi-Disk Utility
- # Printer Test

6.18 Select "FIELD TEST UNIT". Press the RUN key. The following message will appear on the monitor screen:

Load all devices to be tested

PART N	0.		
SHEET	//	OF	14
DATE	0	9/14/	189

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

- 6. ACTUAL TEST (cont'd)
  - 6.19 Press the RETURN key. The following screen will appear:

2200 FTU (Field Test Unit) Rev. 873E+

	Available Addresses		Disk Model		Ending Sector	
>-	340	-< >-	2270a	-< >-	1231	-<
>-	D10	-< >-	2200DS FLPm	-< <b>&gt;-</b>	4159	-(
>-	D11	-< >-	2200DS WIN	-< >-	38911	-<
>-	012	-< >-	2200DS WIN	-( )-	38911	-<

Select the address of the device to be tested.

Press: ANY KEY to input parameters CLEAR/PREV SCRN - to exit

SF'O define err RETURN/RUN to cont.

PART NO.

DATE 09/14/89

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

- ACTUAL TEST (cont'd) 6.
  - 6.20 Enter "340" as the address. Press the RETURN key and the following screen will appear:

### TEST SELECTION MENU Rev. 873E+

SF 08 - Write Enable SF 01 - Compare Sector(s) SF 09 - Write Lock SF 02 - Compare File SF 03 - Display a Sector SF 10 - Scratch Disk WRITE LOCKED SF 11 - Format Disk SF 04 - Verify SF 12 - Write SF 05 - Read SF 13 - Read After Write SF 06 - Position Head(s) SF 14 - Instruction Test SF 07 - DPU Prom Rev.

Device 340 Start Sector 0 Track 0 End Sector 1231 Track 76 Maxieue = 1231 Printer OFF (204, 215, OFF) Loop N (N=No, T=on Test, E=on Error or test) Mode I (I = sequential step In, A = Alternate step) (O = sequential step Out, R = Random step)

Press: ANY KEY to input parameters SF' key listed above SF'O define err CLEAR/PREV SCRN - to exit

- 6.21 Press the SF8 key to "release" WRITE LOCK (WRITE ENABLE). Press the RETURN key.
- 6.22 Using the RETURN key, tab over to "LOOP" and change to "T". Press the RETURN key.
- 6.23 Using the RETURN key, tab over to "MODE" and set to "RANDOM". Press the RETURN key.
- 6.24 Set "RANDOM OPERATIONS" to "1000". Press the RETURN key.

PART N	0.			
SHEET	/3	OF	14	
DATE	6	19/14	1/89	

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

- 6. ACTUAL TEST (cont'd)
  - 6.25 Press the SF13 key. Press the RETURN key.
  - 6.26 The RANDOM READ AFTER WRITE TESTS will now run. Allow the test to complete one (1) pass. When complete, press the SHIFT/RESET keys and the following message will appear:

Ready (Basic 2) Partition 01"

6.27 Press the LOAD, RUN, and RETURN keys. The following screen will appear:

System Utilities - (c) Copr. Wang Laboratories, Inc. 1989

Select an item and press RUN/EXEC:

Partition 1, 150 K Terminal 1

- # Partition Generator # Partition Status
- # Format Disk Platter
- # Move File
- # Backup Platter
- # Recover from Backup
- # System Install
- # Make a Reference List of File Names
- # Initialize Date & Time
- # Vertical Format Control
- # DS Utilities
- # 82ep
- 6.28 Select "INITIALIZE DATE AND TIME". Press the RUN key.
- 6.29 A clock will appear. Enter the correct DATE and press the RETURN key. Enter the correct TIME and press the RETURN key.
- 6.30 Verify that the clock is running.

PART N	0.	
SHEET	14 OF	14
DATE	00/14/	100

TITLE

CS386 (212-7129A-D) PRETEST/ACCEPTANCE TEST

- ACTUAL TEST (cont'd) 6.
  - 6.31 Press the SHIFT/RESET keys and power down the test bed.
  - 6.32 Remove the 212-7129A-D assembly. If the board/assembly has passed PRETEST, fill out the appropriate paperwork and send the assembly to the RUN-IN AREA. If the board/assembly has just passed FINAL ACCEPTANCE, send the assembly to STOCK.
  - 6.33 If the board/assembly did not pass, fill out the appropriate paperwork, noting the discrepancy, and send the board/assembly to the REPAIR AREA.

PUERI Juro FRODUCTION TRANSFER

# SCHEDULE FOR IN-SYSTEMS TEST / RUN-IN / REPAIR EQUIPMENT - WILFAB SET-UP

# SCHEDULE FOR RUN-IN / TEST / REPAIR STATIONS RECEIVED TO DATE IN PB

DATE: 9/7/89

|M.T.W.T.F.S.S|M.T.W.T.F.S.S|M.T.W.T.F.S.S|M.T.W.T.F.S.S|M.T.W.T.F.S.S|M.T.W.T.F.S.S|M.T.W.T.F.S.S|

COMPLETE WILFAB BUILD :XXXXXXXX=======

SET UP 2200 386 TEST/REP STA. : =.....======

LVS: STA. 12; TEST/ REP. (9094) : =.....=====

LVS: STA. 13; TEST/ REP. (9416) : =....=====

WKSTA.: RUN-IN TRAYS; (8577) : ====

11

WKSTA.: RUN-IN TRAYS; (8167)

SET-UP WILFAB AND EQUIPMENT PRODUCTION: BUILD PLAN RESPONSIBILITY: NOTE: ENGINEERING: PERFORM STATION OPERATIONAL TESTS

	WANG			A	ASSEM	BLY PROCEDURE	1 OF 1
PART NO.212-7129-A,-B,-C,-D	212-712	9-A,-B		DESCRIPTION CS	386 CPU	BOARD ASSY (1MB, 2MB, 4MB, 8MB) MODEL	TYPE
	PREP. 9	JES.	have	2	MFG. ENG. APPROVAL	Horn Mahoney Hiller REVIEW ( Self Son Le	28/11/8
ISSUE DATE	TE ISSUE	E BOM	OPER NO.	SHT. NO	ECO/MPC NO	/ DESCRIPTION	WRITER
9/12/89	9 A	<b>y</b> C	ALL	ALL		RELEASE TO MANUFACTURING	
٠							
		·-					
٠							
						2.4	
						•	
DISTRIBUTION.	TTPW.						

_

.

-	SHT. 1 OF 1	TOOLS/FIXTURES			•								
	E ISS. REV.	SPECIAL TOOLS											
ERATION SHEET	TYPE	STD									ş		
ATION	ARD ASSY	WORK CTR.						·	•				<b>.</b>
OP	ട്ട 386 മ												
WANG	DESCRIPTION	OPERATION	OS TOGETHER				-						
	212-7129-A,-B,-C,-D		ASSEMBLE BOARDS TOGETHER	QC INSPECTION	TEST								
	PART 212-7.	OPER. No.	1.0	1.5	2.0								_

-. •′, (WANG) ASSEMBLY SHEET

380/14

SHT. CS 386 CPU BOARD ASSY (IMB, 2MB, 4MB, 8 MB) 212-7129-A, -B, -C, -D| DESCRIPTION

ISSUE REV.

EV. TYPE

NOTE: BEFORE ASSEMBLING ANY PARTS, MAKE SURE THERE IS NO OBVIOUS DAWAGE OR CORROSION TO PARTS. VERIFY THE BOARD E REV. ON THE BOARDS PER THE E REV. CHART.

ASSEMBLE BOARDS TOGETHER

OPERATION

OPER. NO. REFER TO THE CHART BELOW TO DETERMINE WHICH CPU BOARD TO USE.


# CPU BOARD CHART

CPU BOARD	210-9561-A	561-		210-9561-D
DESCRIPTION	CS/386-1MB	CS/386-2MB	CS/386-4MB	CS/386-8MB
PART NUMBER	1 212-7129-A	1 212-7129-B	1 212-7129-C	212-7129-D

- 1. 210-9561-X CPU BOARD (SEE CHART)
  2. 210-9562-A CPU DAUGHIER BOARD
- 2. Z10-9362-A CPU LAUGHTER BLAND 3. 462-0410 (2) SPACER, NYLON, .437" LONG
- . 650-2202 (2) SCREW, NYLON, #4-40 X 5/8"
  - 5. 652-2001 (2) HEX NUT, NYLON, #4-40

AND THE CPU DAUGHTER BOARD WITH THE CIRCUIT SIDES FACING UP AND INSERT THE HEADERS ON THE CPU BOARD INTO THE CONNECTORS ON THE DAUGHTER BOARD. POSITION THE SPACERS (2) BETWEEN THE BOARDS AS SHOWN, INSERT THE SCREWS DOWN THROUGH THE BOARDS AND THE SPACERS AND SECURE THEM WITH THE HEX NUTS (2).

CHECK TO MAKE SURE THAT THE HARDWARE IS TIGHT.



WANG MANU	SHEET DATE	10	7/187-354 OF 8	3-3546				
TITLE CS386-D		167/187-3543-3546		TYPE OF TEST  FINAL ACCEPTANCE TEST				
APPROVAL  TECHNICAL WRITER 9-12-89  LUZANNE IN. Gark	1	APPROVAL  OCT SUPTJENGR.  Lyeants 4/2/89	PRODU		ROVAL ST ENGR			
O.C. REVIEW   G/14/4		ENGR.	1	<u> </u>				

# REVISION HISTÓRY

REV.	DESCRIPTION	SHT.	MPC/ECO	DATE	CHANGED BY
Α	PRELIMINARY DRAFT			09/08/89	
В			- /-		
5	SMALL CHANGES	n/a	n/a	09/12/89	S. CLARK
		]			
		}			_
				' 	
1		İ			
1					
				:	
1					
BOW 6	Distr. VS			001121	W CONFIDENCE
RGW C	3252 10/88			COMPA	NY CONFIDENTIA

PART NO. 167/187-3543-46 8 SHEET DATE

TITLE

CS386-D (167/187-3543-3546) FINAL ACCEPTANCE TEST

- 1. **PURPOSE** 
  - 1.1 To allow an operator to thoroughly perform a FINAL ACCEPTANCE test on the CS386D (167/187-3543-3546).
- 2. REFERENCES
  - 2.1 None required.
- RESPONSIBILITIES 3.
  - 3.1 Refer to <u>GUIDELINES FOR WRITING TEST PROCEDURES</u> (PROC-0009), section 4., for a complete listing of responsibilities.
- EQUIPMENT REQUIREMENTS 4.

DESCRIPTION	PART NUMBER	QTY.
CS386D System to be tested System Configuration:		
Triple Controlle	r212-3012	1
Workstation w/cabling	187-3249 or equiv	1
320 Floppy	289-0846	1
Tape Streamer	289-0905	1
20 Meg Wini	289-0849 or equiv	1
Printer PM018	157-3520 or equiv	1
CS386 BASIC-2 O.S. Software	(rev. 1.0 or greater	^)
CS386 Customer Diagnostic	(rev. 1960 or greate	<u>er)l</u>

NOTE:

SOFTWARE 732-0049B IS PART OF THE 2200 DIAGNOSTIC PACKAGE.

NOTE:

DRIVES MUST BE INITIALIZED.

- 5. SETUP PROCEDURE
  - 5.1 Connect the 220-0447 cable, leading from the back of the workstation, to the TERMINAL PORT of the Triple Controller located in the CS386-D System.
  - 5.2 Set switches, located on the 212-7113 assembly, as shown in APPENDIX 9.1.

PART NO. 167/187-3543-46 SHEET DATE

TITLE

### CS386-D (167/187-3543-3546) FINAL ACCEPTANCE TEST

- SETUP PROCEDURE (cont'd) 5.
  - 5.3 Verify that the workstation and CS-D system are plugged into an appropriate 115V power source.
  - 5.4 Load the 212-7113 assembly into the CS-D system.
  - 5.5 Connect the printer to the printer port located on the 212-7113 assembly.
- 6. **ACTUAL TEST** 
  - 6.1 Turn the workstation ON. Power UP the CS-D system. Power UP the printer.
  - 6.2 The following message will appear on the workstation screen:

MOUNT SYSTEM PLATTER PRESS RESET

- 6.3 Observe the floppy LED.
  - 6.3.1 If the LED is OFF, the BIT (built in test) is complete.
  - 6.3.2 If the LED is flashing, the BIT has failed. Proceed to section 8 (POWER DOWN).
- 6.4 Press the RESET key.
- 6.5 The following message will appear on the workstation screem:

SF?

6.6 Press the SFO key. The following menu will appear:

_	MULTIUSER BASIC -2	
_	DIAGNOSTICS	

- 6.7 DIAGNOSTICS:
  - 6.7.1 Select DIAGNOSTICS. The "Customer Diagnostics" menu will appear.

## WANG) MANUFACTURING TEST PROCEDURE

PART NO. 167/187-3543-46 SHEET DATE

TITLE

CS386-D (167/187-3543-3546) FINAL ACCEPTANCE TEST

- 6. ACTUAL TEST (cont'd)
  - 6.7 DIAGNOSTICS: (cont'd)
    - 6.7.2 Run this series of tests for three (3) passes.
    - 6.7.3 Press the RESET button.
    - 6.7.4 Press the "SFO" key.
  - 6.8 Select Multiuser Basic-2. Press the RUN key.
  - 6.9 Press the SF15 key.
  - 6.10 The "Check Configuration" screen will appear. Press the "Y" key. Press the RETURN key.
  - 6.11 The following message will appear:

### RECONFIGURE PASSWORD? SYSTEM

6.12 Press the RETURN key. The following message will appear on the workstation screen:

> READY (BASIC2) PARTITION 01 PRESS LOAD, RUN, RETURN

- 6.13 Press the LOAD, RUN, and RETURN keys. The "System Utilities" screen will appear. Select "DS UTILITIES". Press the RUN key. The "DS" Utilities" screen will appear.
- 6.14 Using the keyboard SPACEBAR, select the PRINTER TEST selection. Press the RUN key.
- 6.15 The following information will be printed:

ABCDEFGHIJKLMNOPQRSTUVWXYZabcdefghijklmnopqrstuvwxyz0123456789 ABCDEFGHIJKLMNOPQRSTUVWXYZabcdefghijklmnopqrstuvwxyz0123456789 END OF THE TEST

## WANG) MANUFACTURING TEST PROCEDURE

PART NO. 167/187 -3543-46 SHEET OF DATE

TITLE

CS386-D (167/187-3543-3546) FINAL ACCEPTANCE TEST

#### 6. ACTUAL TEST (cont'd)

- 6.16 On the "DS Data Storage Cabinet Utilities" screen, select the BACKUP DISK PLATTERS TO TAPE CASSETTE selection. Press the RUN key.
- 6.17 To run a backup test, perform the following:
  - Enter "DSF" for address of tape cassette. Press the 6.17.1 RETURN key.
  - Enter "E" to erase tape. Press the RETURN key. 6.17.2
  - Enter "D10" for address of disk platter (blank if no 6.17.3 more). Press the RETURN key.
  - Enter "01/01/00" for platter name. Press the RETURN 6.17.4 key.
  - Enter "00000" for starting sector (defaults = beginning 6.17.5 of platter). Press the RETURN key.
  - Enter "1200" for ending sector (default = current end 6.17.6 of cataloged data). Press the RETURN key.
  - Enter "Y" to accept this entry. Press the RETURN key. 6.17.7
  - Press the RETURN key (address of this platter to backup 6.17.8 (blank if last).
- 6.18 Backup should now be running. At the completion of the test, press the "FN" key.
- 6.19 To return to the "System Utilities" menu, press the RESET, LOAD, RUN, and RETURN keys.

#### 7. DISK TESTS

7.1 From the "System Utilities" menu, select DISK UTILITIES. Press the RUN key.

WANG )

## MANUFACTURING TEST PROCEDURE

PART NO.

/67/187-3543-46

SHEET 6 OF 8

DATE 09/14/89

TITLE

CS386-D (167/187-3543-3546) FINAL ACCEPTANCE TEST

- 7. <u>DISK TESTS</u> (cont'd)
  - 7.2 From the "Disk Utilities" menu, select MULTIDISK TEST. Press the RUN key.
  - 7.3 The following message will appear on the workstation screen:
    - * MULTI-DISK EXERCISER REV XXXX * MOUNT ALL DEVICES TO BE TESTED
  - 7.4 Press the RETURN key. The following DISK PARAMETER CHART will appear:

TEST	FRMT	INIT	VER	ADDRESS	MODEL	SECTOR RANGE	ACCESS
NO YES NO YES	NO NO NO	NO NO NO	NO NO NO	D10 D11 D12	2200 DS F 2200 DS W 2200 DS W	IIN 0/38911	INFINITE INFINITE INFINITE INFINITE

7.5 Using the cursor keys to select test parameters, fill out the chart as shown above. Press "N" for "NO" and "Y" for "YES".

CAUTION!!! DO NOT TEST D11. TEST PROGRAMS WILL BE DESTROYED!!!

7.6 Press the CONTINUE key. Press the RETURN key. The following message will appear:

TO PROCEED, TYPE 'ENABLE WRITING'

- 7.7 Type 'ENABLE WRITING'. The following warning message will appear:
  - Warning: All resident data will be destroyed by this exercise
- 7.8 Press the CONTINUE key.
- 7.9 The test will now run. Allow the test to run for 200 accesses on each drive and then press the HALT key to stop the test. If there are "O" errors on each drive, the unit has passed. If there are errors, the unit has failed. PROCEED TO SECTION 8 (POWER DOWN).

## WANG MANUFACTURING TEST PROCEDURE

PART NO. 167/187-3543-46 SHEET DATE

TITLE

CS386-D (167/187-3543-3546) FINAL ACCEPTANCE TEST

#### 8. POWER DOWN

- 8.1 Power OFF the CS-D System.
- 8.2 If an error was detected, fill out the appropriate paperwork, noting the discrepancy, and send the unit to the REPAIR AREA.
- 8.3 If no errors were detected, fill out the appropriate paperwork, and send the unit to the FINAL ASSEMBLY AREA.

## WANG MANUFACTURING TEST PROCEDURE

PART NO. 167/187-3543-46 SHEET

DATE

TITLE

CS386-D (167/187-3543-3546) FINAL ACCEPTANCE TEST


- SWITCH SETTINGS: 9.
  - 9.1 SWITCH SETTING FOR THE 210-9558 BOARD:

SW1 - 5 ON, ALL OTHERS OFF

SW2 - 1, 3, 5 ON, ALL OTHERS OFF

SW3 - 5, 6 ON, ALL OTHERS OFF

J2 SHUNT



9.2 SWITCH SETTING FOR THE 210-9559 BOARD:

- ALL OFF SW4

SW5 - 1, 3, 4 OFF 2 ON



#### MEMORANDUM

TO:

Michael Britko

FROM:

Arthur Whelden

SUBJECT:

FCC Electromagnetic Emission Testing of a CPU Printed

Circuit Board Set (210-9561 & 210-9562) in a Micro VP

Computer Cabinet (PEP H0213C)

DATE:

September 14,1989

A CPU printed circuit board set (210-9561 & 210-9562) was installed within a Wang 2200 Micro VP Cabinet. With this change the computer model no. changes to Micro VP/386. Testing was then performed in accordance with the FCC Rules and Regulations for the measurement of electromagnetic emissions from digital devices. The measured values, obtained during testing, showed the system to be in compliance with the FCC Class "A" requirements.

During testing, the computer was running a CS O/S Basic-2/386 Software Program which provided a full screen of continuously repeating H's. Alternately, this pattern was sent to the printer.

The system under test consisted of the following devices:

1)	Wang Computer	M/N Micro VP/386 S/N PR1594
2)	Workstation	M/N 2536DW S/N 41002W
3)	25' Shielded Monitor Cable	WPN 220-0447
4)	Keyboard	M/N 720
5)	Keyboard Cable Coiled to 3'	Not Identified

6)	Disk Drive	M/N 2275-10 S/N VL4608
7)	8' Shielded Disk Drive Cable	WPN 220-0365
8)	Printer	M/N PM060 S/N 13627E
9)	12' Shielded Printer Cable	WPN 220-0364

The following printed circuit boards were installed within the computer during testing:

1)	CPU Board Set	210-9561 & 210-9562
2)	MXE Two (2) Board Set (210-7973 & 210-7874)	212-3032
3)	MUX Master	210-8824

Arthur Whelden FCC/VDE Eng.

anw316



#### **MEMORANDUM**

TO:

Michael Britko

FROM:

Arthur Whelden

SUBJECT:

FCC Electromagnetic Emission Testing of a CPU Printed Circuit Board Set (210-9561 & 210-9562) in a CS Cabinet

(PEP H0213C)

DATE:

September 14,1989

A CPU printed circuit board set (210-9561 & 210-9562) was installed within a Wang Computer Cabinet M/N CS20. With this change the computer model no. changes to CS/386. Testing was then performed in accordance with the FCC Rules and Regulations for the measurement of electromagnetic emissions from digital devices. The measured values, obtained during testing, showed the system to be NONCOMPLIANT.

To bring the system into FCC Class "A" compliance a Ferrite Sleeve (WPN 410-1037) had to be installed on each end of the disk drive cable (WPN 220-0365). Therefore, when ever the two (2) board CPU set (210-9561 & 210-9562) is installed within the above cabinet the disk drive cable must be modified as above.

During testing, the computer was running a CS O/S Basic-2/386 Software Program which provided a full screen of continuously repeating H's. Alternately, this pattern was sent to the printer.

The system under test consisted of the following devices:

1)	Wang Computer	M/N CS/386
		S/N 52740R
2)	Workstation	M/N 2536DW
		S/N 41002W
	25' Shielded Monitor Cable	WPN 220-0447
4)	Keyboard	M/N 720
5)	Keyboard Cable Coiled to 3'	Not Identified

6)	Disk Drive	M/N 2275-10 S/N VL4608
7)	8' Shielded Disk Drive Cable with a ferrite sleeve added to each end	WPN 220-0365
8)	Printer	M/N PM060 S/N 13627E
9)	12' Shielded Printer Cable	WPN 220-0364

The following printed circuit boards were installed within the computer during testing:

3)	MUX Master	210-8824
2)	MXE Two (2) Board Set (210-7973 & 210-7874)	212-3032
1)	CPU Board Set	210-9561 & 210-9562

Arthur Whelden FCC/VDE Eng.

anw315

VS OFFICE ELECTRONIC MAIL

THURSDAY 09/07/89 03:53 PM PAGE:

ITEM SUBJECT: COMPUTER CS-386 PILOT

### MEMORANDUM

TO:

MICHAEL BRITKO

FROM: ARTHUR WHELDEN:

SUBJECT: FCC/VDE CLASS "A" EVALUATION: TESTING OF A COMPUTER

M/N CS-386 FROM A PILOT RUN (PEP HO213C)

DATE: AUGUST 24,1989

A WANG COMPUTER MODEL NO. CS-386 FROM A PILOT RUN WAS TESTED IN ACCORDANCE WITH THE FCC/VDE RULES AND REGULATIONS FOR ELECTROMAGNETIC EMISSIONS. THE MEASURED VALUES OBTAINED DURING TESTING SHOWED THAT THE SYSTEM WAS IN COMPLIANCE WITH THE REGULATIONS FOR A CLASS "A" COMPUTING DEVICE.

DURING TESTING, THE COMPUTER WAS RUNNING A CS O/S BASIC: SOFTWARE PROGRAM WHICH PROVIDED A FULL SCREEN: OF CONTINUOUSLY REPEATING H'S. ALTERNATELY; THIS PATTERN WAS SENT TO THE PRINTER.

## THE SYSTEM UNDER TEST CONSISTED OF THE FOLLOWING DEVICES:

13	COMPUTER S/N: 15798W	M/N' CS-386:
2)	WORKSTATION'S/N'41002W	M/N 2536DW:
3)	25° SHIELDED WORKSTATION CABLE	WPN 220-0447
4)	KEYBOARD	WPN 725-3155-US
5)	PRINTER S/N 14062E	M/N PM060
6)	12' SHIELDED PRINTER CABLE	WPN 220-0364
7)	1º SHIELDED CABLE	WPN: 220-0257:
8)	12" SHIELDED CABLE WITH FERRITE BEADS	WPN 220-0359

### THE COMPUTER CONSISTED OF THE FOLLOWING DEVICES:

MOTHER BOARD	WPN 210-9560
CPU BOARD	WPN 210-9561-1-B
CPU DAUGHTER BOARD	WPN 210-9562-0
PCA 2280 DISK CONTROLLER	WPN 210-7715
PCA DSPC MB CSD	WPN 210-9558
PCA CSD	WPN 210-9559
PCA 2275 MUX MASTER	WPN 210-8824-0.
MUX 7874-A/7973-A MXE MLT CONTROLLER	WPN 212-3032
POWER SUPPLY: WITH: A DELTA. POWER LINE FILTER P/N 04DCHW3 (WPN: 410-2041)	WPN 270-0890-1
	CPU BOARD  CPU DAUGHTER BOARD  PCA 2280 DISK CONTROLLER  PCA DSPC MB CSD  PCA CSD  PCA 2275 MUX MASTER  MUX 7874-A/7973-A MXE MLT  CONTROLLER  POWER SUPPLY: WITH: A DELTA POWER LINE FILTER

A PRODUCTION UNIT WILL BE REQUIRED FOR THE FINAL FCC/VDE VERIFICATION: TESTING.

ARTHUR WHELDEN:

AW0301

Benchman

## FAILURE ANALYSIS BY ERROR CODE

REPORT DATE: 09-13-1989

BOARD TYPE: 9561 LOT SIZE: 15 1st PASS YIELD: 86.7%

SOLDER SHORTS 04.20	ETCH   SHORTS   04.14	ETCH OPENS 04.13	DEFECT/ COMP. XX.02 L62 Y1	WRONG PART XX.05	MISSING PART XX.01
LEAD SHORTS XX.16	ECO WRONG 07.XX	SOLDER PROB. 13.XX	REVRSD/COMP.XX.03	MOUNT WRONG XX.06	LEAD NOT THRU XX.14,15

Benchmans

## FAILURE ANALYSIS BY ERROR CODE

REPORT DATE: 08-30-1989

BOARD TYPE: 9561 LOT SIZE: 15 lst PASS YIELD: 73.3%

SOLDER SHORTS 04.20	ETCH   SHORTS   04.14	ETCH OPENS 04.13	DEFECT/ COMP. XX.02	WRONG PART XX.05	MISSING PART XX.01
         		LD1 (2)	Y1 (2)		
LEAD SHORTS XX.16	ECO WRONG O7.XX	SOLDER PROB.	REVRSD/ COMP. XX.03	MOUNT WRONG XX.06	LEAD NOT THRU XX.14,15
 		 			     <del>-</del> 
 	     	     			1       

## PCB TEST

## FIRST PASS YIELD

		TYPE	OF TEST:
NAME: CUDNG VAN TRANG			LBST
DATE: 8/30/89 -9 //3 /89			INCIRCUIT
WLI #: 210- 9561_A R1		<u></u>	PRETEST W ATE
SWO #:			PRETEST W/O ATE
	<u> </u>		ACCEPTANCE

·					
SERIAL NUMBER	PASS/ FAIL	DEFECT CODE	SERIAL NUMBER	PASS/ FAIL	DEFECT CODE
04171220	م				
04171233	دم			!	
24171221	מ				
24171228	p				
04171227	P				
04171224	P				
04171229	P				
04171219	P				
04171225	p				
04171222	P				
04171223	P	i			
04171226	P				
04171232	P	·			
·24171231	F				
04171230	F				-
					-
					•
	and the second of the second o	**************************************			

## PCB REPAIR

## FAILURE ANALYSIS

## TYPE OF TEST

NAME CUONG VAN TRANG

A = LBST

C = PRETEST

B = INCIRCUIT

 $\underline{D} = RUN-IN$ 

DATE <u>9////89</u> P/N 210- <u>956/</u> R/

E = ACCEPTANCE

SERIAL	TYPE OF	REPAIR LOCATION	REPAIR	COMMENT
NUMBER	TEST FAILED		~`	
04171231	C	L62	66.02	
04171230	٠ .	<b>Y</b> /	79.02	
		``		
			<del></del>	
	İ			
•				
	•			
		_		

## PCB REPAIR

## FAILURE ANALYSIS

## TYPE OF TEST

NAME____

A = LBST

C = PRETEST

DATE 8/30/89

B

 $\underline{\mathbf{D}} = \mathbf{RUN} - \mathbf{IN}$ 

P/N 210- 956/

E = ACCEPTANCE

·						
SERIAL NUMBER	TYPE OF TEST FAILED	REPAIR LOCATION	REPAIR CCCE	COMMENT		
222		LOI	0A.13			
226		601	04.13			
230		Y /	79.02			
233		· Y /	79.02			
•						
			·			
	·					
				_		
	1			1		

____

## FIRST PASS YIELD

TYPE OF TEST:

WE:	LEST
TE: 8/79/89	INCIRCUIT
LI #: 210-9561	
WO #:	ACCEPYANCE

SERIAL	PASS/ FAIL	DEFECT	SERIAL	PASS/ FAIL	DEFECT
NUMBER	FAIL	CODE	NUMBER `	FAIL	CODE
4171 232	م .				
220	P				
231	P			_	
22.1	P				
_ 22-3	P	·			
_ 228	P				
227	P		- <del>-</del>		
224	P				
229	ρ.				
225	P				
219					
222	5.				
226	F				
230	F				·
233	F				-
	·				
		·	•		
•					
				·	
			•		and the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of th
				•••	Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction of the Contraction o

### FAILURE ANALYSIS BY ERROR CODE

REPORT DATE: 08-16-1989

BOARD TYPE: 9562 LOT SIZE: 25 1st PASS YIELD: 84.0%

SHORTS 04.20	ETCH   SHORTS   04.14	ETCH OPENS 04.13	DEFECT/COMP.XX.02	WRCNG PART XX.05	MISSING PART XX.01
			L13 -   L35   L8		 
					    -  -  -
LEAD SHORTS XX.16	ECO   WRONG   07.XX	PROB.	REVRSD/   COMP.   XX.03	MOUNT WRONG XX.06	LEAD NOT THRU XX.14,15
	 		 		L8     
	1       	       	       		       

Benchmark

and the second

## FAILURE ANALYSIS BY ERROR CODE

REPORT DATE: 08-10-1989

ECARD TYPE: 9562 LOT SIZE: 25 1st PASS YIELD: 64.0%

 SOLDER SHORTS 04.20  L38 Y1 (2)	FTCH SHORTS 04.14	ETCH OPENS 04.13	DEFECT/ COMP. XX.02	WRONG PART XX.05	MISSING PART XX.01
LEAD SHORTS XX.16	ECO WRONG 07.XX	SOLDER PROB.	REVRSD/ COMP. XX.03	MOUNT WRONG XX.06	LEAD NOT THRU XX.14,15
C16 C27 C37 C4 Y1	none	der	L35		

## PCB REPAIR

## FAILURE ANALYSIS

## TYPE OF TEST

NAME ( UDNG-V-RANG

 $\underline{\mathbf{A}} = \mathbf{LBST}$ 

C)= PRETEST

DATE 8/11/89 -> 8/15/89

B = INCIRCUIT

 $\underline{D} = RUN - IN$ 

P/N 210- 9562

E = ACCEPTANCE

SERIAL NUMBER	TYPE OF TEST FAILED	REPAIR LOCATION	REPAIR CODE	COMMENT
96883	۲	413	-66.02	
96884	<b>C</b>	<i>235</i>	66.02	
96888		68p13→16	66.06	
96878	C		66.02	
_				
· ;				
· •				
•				
			-	
				1

## PCB TEST

## FIRST PASS YIELD

	T	YPE	OF TEST:
NAME: <u>CUONG-V- TRAN</u> ET	-		lest
DATE: 8/11/39 8/15/89	-		INCIRCUIT
WIII #: 210- 9562	-	<u> </u>	PRETEST W ATE
SWO #:	· 		PRETEST W/O ATE
	; ·		ACCEPTANCE

SERIAL NUMBER	PASS/ FAIL	DEFECT CODE	SERIAL NUMBER	PASS/ FAIL	DEFECT CODE
0.3896872	p	·	03896884	<i>=</i>	
03896870	م		23896888	F	
03896889	ور		03896878	F	i
03896891	p.				
23896883	F	<u> </u>			<u> </u>
03896879	P				
03896882	p				
03896890	وز				
03896869	P				<u> </u>
03896880	בק				
0389 6893	p	ì			<u> </u>
03896886	P				
03896874	P	•			
03896885	ρ				
03896871	P				
03896875	p				
03896873	ρ				
23896887	ρ				
03896876	P				
03896881	P				
03896892	ρ				
03896877	P			į	

Benchmark

## PCB REPAIR

## FAILURE ANALYSIS

TYPE OF TEST

NAME____

 $\underline{\mathbf{A}} = \mathbf{LBST}$ 

THE PETENT

DATE 8-110 189

B = INCIRCUIT

D = RUN-IN

P/N 210- 9562

E = ACCEPTANCE

SERIAL NUMBER	TYPE OF TEST FAILED	REPAIR LOCATION	REPAIR CODE	COMENI
889	TEST PATIEN		04,20	
		235	66-02	
891		64	69,16	
882		: 432	04.13	
890		71	04.20	
884		C16	69,16	
887		435	64.03	
880		L38	04,20	
893		€27	69:16	
		C.37	69.16	
886	<u> </u>	71	71,16	
•				
			·	
•				

<del>-----</del>

Benchmark

WE:____

## FIRST PASS YIELD

THE OF TEST:

TE: <u>\$ //0 / 89</u>

INCIRCUIT

WO #: _____ ACCEPTANCE

SERTAL NUMBER	PASS/ FAIL	DEFECT		SERIAL	PASS/ FAIL	CODE
03896 877	P			891	7	
892	P			889	F.	
	P			870	P	
881	ρ					
872	P	•				
888	P					
885	P		<u>.</u>	·		
874	P					
876	ρ.					
:878	19					,
879	P					
869	1	,				
8-73	P			4		
875	P					
871	P					
886	F	<b>e</b> .				
893	F					
880	F			•		
. 887	F					
× 884	-18				·	
890	F			•		
880 887 ^ 889 890 882	1F			·	••	

## PACKAGING DATA ANNOUNCEMENT

#### DISTRIBUTION:

J. Schultz	014-A3A	PP&M Product Manager
M. Negron	015-17B	R & D
R. Bator	018-211	MFG - Secured Systems Engineering Mgr
P. Biancavilla	015-420	R & D Package Design Eng Mgr
M. Cronin	027-210	CSO - Packaging/Customer Engineering
L. Gaskell	015-350	R & D Methods Engineering
J. Wagner	015–130	Pilot Planning Manager
J. Sheehan	013-A80	R & D Hardware Product Configuration
D. Scamporino	018-G1F	Purchasing - Packaging Materials Buyer
K. Shaughnessy	015-420	R & D Package Design Proj Coordinator
D. Wilson	018-21F	MFG - Product Support Engineering Mgr
J. Lynch	015-11B	MFG - Pilot Engineering Mgr

FROM:

Roslyn Winston R&D Package Design Engineering Package Design Documentation for the new 386 BASED CS PRODUCTS, PEP SUBJ:

DATE: September 5, 1989

The following packaging has been designed, approved, and documented for implementation. Please note that this packaging is approved for shipping. CPU cabinets without drives.

## PACKAGING DATA:

Packaging Test #880-125 PASSED per SPI 10-521

Packaging BOM #290-0685

Packaging BOM Description: SHPG PKG BOM:CS-D-2200-CPU

## 2. PACKAGING MATERIALS PER BOM 290-0685:

		QTY PER	KNOCKED DOWN FLAT SIZE
WIL#	COMPONENT DESCRIPTION	PKG BOM	LENGTH X WIDTH X HEIGHT
685-0100	Edge Protector 2.5x2.5x3.0	4	N/A
685-0474	2" Clear PP tape	a/r	N/A
685-0664	Strapping, Polyester, 50W	a/r	N/A
685-0665	Strapping Seals	2	N/A
685-0723	Bag, Gusset 23x17x36	1	N/A
685-2410	FOLHSC 27.13 x 20.00 x 27.30	) 1	48.00 X 37.50 X .63
R.685-2411	Pallet, Cushioned	1	28.00 X 20.88 X 7.63
€ 685-2412	Cushion Assy, Top	1	27.00 X 19.75 X 4.31

#### SHIPPING DATA - PACKAGED PRODUCT [ENGLISH: IN - (METRIC: CM)] OUTSIDE DIMENSIONS

	001.	<i>-</i>	C DILICIIO	701	13					
LENG	TH	Χ	WIDTH	Χ	DEPTH	VOLUME				
2	8.00	X	20.88	X	30.38	10.27 ft ³				
(	71)	X	(53)	Χ	(77)	$(.29 m^3)$	Packaged	weight:	93.5	lbs

### PRODUCT DATA

TRODUCT DATA					
WLI#	TITLE				
16 <del>7/18</del> 7–3589	CS 386-10N	1MB	CS	CPU	W/O DPU
167/187-3540	CS/386-20N	2MB	CS	CPU	W/O DPU
167/187-3541	CS/386-40N	4MB	CS	CPU	W/O DPU
167/187-3542	CS/386-80N	8MB	CS	CPU	W/O DPU
167/187-3543	CS/386-10D	1MB	CS	CPU	W/DPU
167/187-3544	CS/386-20D	2MB	CS	CPU	W/DPU
167/187-3545	CS/386-40D	4MB	CS	CPU	W/DPU
167/187-3546	CS/386-80D	8MB	CS	CPU	W/DPU

doc 0208W

## MANUFACTURABILITY_REVIEW_SHEET

REVIEW DATE 5/2/89 F	PROJECT	r_ <u>C5</u> -	-386				BOARD	#_ <u>956/</u>
CHECK ITEM	 !_RA_	 ! RB	 _!_ <u>RC</u> _	<u> ! RD</u>	! RO		<u>:</u> ! <u>R2</u>	. ! R3
1_TOOLING HOLES			<u> </u>	_!	.!	_!	!	
2_COMPONENT_HOLES		.!	.!✓_		_!	_!	!	
3 COMPONENT SPACING	·		!NZ	_!	<u> </u>		!	
<u>4_CHANGE_RADIAL_TO_AXIAL</u>		_ <u> </u>	<u>''/</u>	_!	<u> </u>	<u> !</u>	!	_!
5 STANDARD SIPS	<u>.</u> !	_!	<u> </u>	· !	.!	!	<u>!</u>	!
6_SOLDERABILITY	!	_ <u>!</u>	!_✓_		.!	<u> </u>	!	
7_S.M.O.B.C	<u> </u>	_!	! /	_!	!		!	
B_FINE_LINE_BOARD_POOL	<u>!</u>		!	_!		<u> </u>	!	_!
<u>9_TRANSPORTABILITY</u>	_!	_!	_!	_!	!	_!	!	
10 WIRE ROUTING	!		<u>: N3</u>	_!	<u>!</u>			
11 MANUAL YS. POST	·!	_!	<u>!</u>	_!	<u>!</u>	!	!	<del>!</del>
12_SOLDER_FIXTURING	_!	_!	_!		!	!	!	
13 PANELLIZATION	_!	_!	<u> </u>	_!	<u>!</u>		· !	!
14_OTHER	!	<u>!</u>	! ✓	_!	•	_!	. !	_!
COMMENTS  NOTE 1: Only 2 tooling						ar ec	lges (·	200)
ICs too close to tool								
NOTE 3:3 wires on Circuit	side, 2	<u> </u>	Comp	side				
NOTE 4:								
NOTE 5:								

## MANUFACTURABILITY_REVIEW_SHEET

REVIEW DATE 7/2/89	PROJE	CT <u>C5</u> -	·326			<b></b>	BOARD	# <u>9562</u>
CHECK ITEM		! RB	! RC	! RD	! RO	! R1	<u> </u>	<u> </u>
1_TOOLING_HOLES	!	!	! N !	_!	!	_!		<u>:</u>
2_COMPONENT_HOLES	<u>!</u>		<u>. !                                   </u>		!	_!	<u> </u>	<u> </u>
<u>3_COMPONENT_SPACING</u>	<u>!</u>	· 	· NZ	_!	!		!	
<u>4_CHANGE_RADIAL_TD_AXIA</u>	<u> </u>	·	<u>.</u> :	<u> </u>		_!	!	<u> </u>
<u>5_STANDARD_SIPS</u>	!		_!/_		!		!	!
6_SOLDERABILITY	!		_!		!	_!	!	
7 S.M.O.B.C.	<u>!</u>	!	_!	!	!	_!	!	!
<u>B_FINE_LINE_BOARD_POOL.</u>	!	!		!	!	_!	!	!
<u>9_TRANSPORTABILITY</u>	!	!	_!	_!	!	_!		!
10_WIRE_ROUTING	!	!	<u>: N3</u>	<u>!</u>	!	_!	!	
11_MANUAL_YSPOST	!	!	<u>. ! /</u>	_!	!	_!	!	!
12_SOLDER_FIXTURING	!	!	<u> </u>	_!	!	<u>!</u>	!	
13 PANELLIZATION	!	!	<u> </u>	_!	!	_!	<u> </u>	!
14 OTHER	!	!	<u>!</u>	_!	!			!
COMMENTS  NOTE 1: lower right to  For ATE, All tooling  Insertion.  NOTE 2: L13 and L23	holes	beve	Caps C	ind !	ICs +	oo ch	ose for	4
NOTE 4:					Ponent	side :		
NOTE 5:								

TO:

Distribution -

FROM:

Bill Callahan Edmond Daigneault

Production Support Engineering

DATE:

April 11, 1989

SUBJECT: CS/386 CPU Board

Attached is the Manufacturing Engineering Plan for the CS /386 CPU board. The Product Support Engineer assigned to this new product will develop and lead the technical team in Manufacturing for the new product introduction period and will remain as the technical product focus in Manufacturing throughout the life of the product.

Please review this plan for the impact of this product on your operation. Direct questions and comments to the Product Support Engineer shown below.

PRODUCT:CS/386 CPU Board

PRODUCT SUPPORT ENGINEER:

Edmond Daigneault

78635 015-11B

#### COMPANY CONFIDENTIAL

# MANUFACTURING ENGINEERING PLAN TEST PLAN FOR

CS-386 CPU BOARD

Originator: Edmond Daigneault

Production Support Engineer

Revision: A

Date: April 10, 1989

#### INTRODUCTION

Edmond Daigneault will develop and maintain a checklist and schedule indicating the Manufacturing Engineering activities required for the new product introduction.

Edmond Daigneault will lead the technical team in Manufacturing during the new product introduction period, working in conjunction with the Manufacturing Program Manager for the product.

#### PRODUCT DESCRIPTION

The CS-386 will be an enhancement of the present CS series of systems. It will be a 80386 based CPU board set. Minimum memory size will be 1MB, and the maximum will be 8MB. The new CPU board will be capable of running all current 2200 instructions. For more information refer to PEP # H 0213C.

#### MARKETING / BUSINESS PLAN

The projected yearly volume for this product is 1980. This includes CSO spares and boards used in upgrade kits. This volume is based on projections from the PP&M business plan dated January 18, 1989.

The build site will be Wang Puerto Rico.

Pilot manufacturing is expected to begin at the Parkwood facility during June, 1989.

The 212-7129-A-C will replace the 210-8937-C-F.

#### SPECIFICATIONS AND DOCUMENTATION

No new manufacturing specifications, standards or documentation will be required beyond the normal new product documentation.

#### NEW PARTS AND TECHNOLOGY

No new parts will be used in this product; however, each variation of memory size will have a unique PAL installed with the memory SIMM's.

#### ASSEMBLY .

The following is a list of the proposed new CS CPU model numbers and the associated memory size. The CPU board numbers have not been determined at this time.

MODEL	MEMORY SIZE	SIMM TYPE	CPU BOARD NUMBER
CS/386-10	lmB	256KB (377-4516)	212-7129-A
CS/386-20	2MB	256KB (377-4516)	212-7129 <b>-</b> B
CS/386-40	4MB	1MB (377-4518)	212-7129-C
CS/386-80	8MB	1MB (377-4518)	212-7129-D

In addition to the above CPU's, it is planned to offer 10 memory upgrades of various configurations.

#### RELIABILITY

The MTBF calculation for this product is not available at this time.

#### TEST PLAN

The test plan for this product will follow very closely the process for the present 210-8937 CPU board and the present CS-D/CS-N systems. This process is outlined in the attached process flow charts.

#### In Circuit Test

The 210-9561 will be tested on a Fairchild in circuit test fixture. This test will detect process defects and most defective components.

Fixture project number .-

Cost ---\$14100.00

#### In Circuit Test

The 210-9562 will be tested on a Fairchild in circuit test fixture. This test will detect process defects and most defective components.

Fixture project number .-

Cost ---\$14100.00

#### TEST PLAN

#### Fault Analysis and Repair

All boards that fail in circuit test will be routed to the fault analysis and repair area. Repaired boards will be routed back to in circuit test.

#### PWA TEST

All boards that pass in circuit test will be tested in an PWA test area. A known good board will be mated with the board under test. Tests used in this area will be from the updated 2200 diagnostic package, with emphasis on cpu instruction and memory testing.

#### Test Equipment List

Description	Oty.	MEI/Model#	Available	Needed	Cost
CS-D System	1	187-3527			
Triple Controller	1	212-3012			
360KB Floppy Disk	1				
20MB Winchester	1	725-0242			
Workstation 2436	1	187-3249			
Cable Workstation	1	220-0447			

#### Board Run-In

Run-in will follow the same procedure as the present CS cpu board (210-8937). Run-in will be done on the final line in the new CS chassis. Provision will be made to run-in CSO spares. The run-in period will be 24 hours. Changes in this run-in period will be made as outlined in the Run-IN / Burn-IN Policy #191-0917.

#### Final Lines Test Equipment


The present final lines test capacity at WPR is 22 systems per day. Based on the PP&M projections this appears to be adequate. If additional capacity is needed, requests for additional equipment will have to be generated.

## 210-9561 / 213-9562 CS/386 BOARDS


OPERATION NUMBER	DESCRIPTION	EQUIPMENT	PROCEDURES	SOFTWARE	NOTES
10	Bareboard Test	Bareboard Tester	Standard Operating	Bareboard test Program	
20	Stock prep.	Sequencer Verifier Board Bake Oven	Sequencer Proc. Verifier Proc. Board Bake Proc. Barcode Proc. Kitting List	Verifier Prog.	
30	Auto Insertion	Dip Inserter VCD Radial Inserter Fixture	Dip Procedure VCD Procedure Radial Proc.		
40	Manual Insert	Contact System Visual Aids Standard Tools	Contact System Procedures	Contact System Program	
50	Wave Solder	Wave Solder Machine Wave Solder Fixture			
60	Post Solder Assembly	Visual Aids Standard Tools	Post Solder Procedures	N/A	
·0	ATE In Circuit Test	Fairchild Tester ATE Fixture	Standard ATE Procedure	ATE Program	
80	Fault Analysis	Standard Tools	N/A	N/A	
90	Functional Test	See Test Section ofThis Document	Functional Test Procedures	Operating System Diagnostics	
100	Fault Analysis	Standard Tools	N/A	N/A	

## 212-7129A-C CS/386 CPU BOARD ASSEMBLY

OPERATION NUMBER		_	PROCEDURES	SOFTWARE	NOTES
10		Standard Tools	Assembly Procedures		
20	Functional Test	See Test Plan Section of This Document	DSP Test Procedures	2200 Diagnostics	
30	Fault Analysis	See Test Plan Section of This Document	Section of Thi		or is it t 9562 board
40	Run In	See Test Plan Section of This Document	See Test Plan	See Test Plan s Section of This Document.	System Lev
50	Final Acceptance Test	See Test Plan Section of This Document.	; ;		



10004	TIVA RIC LASCONTONIA NG.		DATE	APPROVED BY
WANG LOWELL MARK U.S.A.		DWN		E ENGR
(447.5		CHK		M ENGR
MATERIAL	MODEL NO.			MFG ENGR
CS/386		TITLE 210-9	561 /2	10-9562
	SEE ENGRG. SPECIFICATIONS	PRIVE	•	•
	M.		55 PL	.0 00



TREAD DECT		BY	DATE	APPROVED BY
(WA)	CONTELL MAR ULA	DWN EJO	4/13/79	E ENGR
		CHK		M ENGR
MATERIAL MODEL NO.				MFG ENGR
	E5/386	TITLE		
	SEE ENGRG. SPECIFICATIONS	TECT	E/ 11/	(2/2 -7/2

#### ---COMPANY CONFIDENTIAL---

TO:

Distribution

FROM

Edmond Daigneault

Production Support/Pilot Engineering

DATE:

September 27, 1989

SUBJECT: CS386 CPU Revised Test Plan

Attached is a copy of revision B of the Manufacturing Test Plan for the CS386 CPU board.. This plan is intended to provide an overview of the proposed test, and repair processes for CS386 project. Originally issued as part of the Manufacturing Engineering Plan, the test plan is being issued as a separate document. Changes were needed as a result of the decision to build and test the boards at Pawtucket Boulevard, and the final systems at Puerto Rico. Your input to this document is requested as this plan will be modified and reissued as details become available.

Please review this plan for the impact of this product on your operation. Direct questions and comments to the Production Support Engineer shown below.

PRODUCT: CS386 CPU

PRODUCTION SUPPORT ENGINEER:

Edmond Daigneault

78435 015-11B

#### Distribution:

s.	Anthony	018-26C
K.	Azar	018-27C
J.	Lynch	015-11B
T.	Mahoney	015-11B
M.	Negron	015-17B
J.	O'Hara	018-26C
E.	Schulz	014-A3A
s.	Stevenson	015-130
R.	Sutton	018-27C
D.P	. Wilson	018-21F

#### TEST PLAN CS-386 CPU BOARD

This revised Test Plan will only be concerned with testing after A.T.E. testing has been completed. Full in circuit test fixtures have been provided for both the 210-9561, and the 210-9562 boards, as outlined in Rev A of the M.E.P., distributed on April 11, 1989.

#### PWA TEST

All boards that pass in circuit test will be tested in the PWA test area. A known good board will be mated with the board under test. Tests used in this area will include the following:

BIT 379-3513R1 or greater. 379-3514R1 or greater. CS386 O.S. Rev. 1.0 or greater. CS386 Customer Diagnostics

Note; CS386 OS and Customer Diagnostics are on the system diskette.

The following is a list of equipment needed for one functional test station, either Pre Test or Final Acceptance.

#### Test Equipment List

Description	$\mathbf{Q}\mathbf{t}\mathbf{X}$	<u>MEI/Model#</u>	<u>Available N</u>	eeded <u>Cost</u>	
Terminal	1	2436DW		597.27	7
CS-D/N Chassis	1	279-0873		680.59	7
Triple Cont.	1	212-3012		191.70	)
DS. DPU Board	1	212-7113		592.92	2
20MB Winch.	1	289-0849		204.95	5
360K Floppy	1	289-0846	To	<u>74.49</u> tal 2341.92	_

Substitution of the chassis and disk drives depending on availability would be acceptable as follows:

1	270-1018	524.27
1	187-3505	1019.14
1	187-3316	962.24
1	187-3505	1019.14
	1	1 187-3505 1 187-3316

Note: CS system would include cost of 210-8937A CPU board (543.45). CS chassis is not structured separately.

### Run-In:

If PCB level run-in of this assembly is required, the following equipment will be needed. Two methods are outlined. Either method will require one setup for each assembly to be run-in. Board level run-in will be required for CSO spares, and system upgrade kits. The board level run-in periods will be as follows.

System boards 6 Hrs. Minimum.
Spares/Upgrades 12 Hrs. Minimum (Overnight)

BIT

<u>Part Number</u>	<u>Description</u>	GFA.
Various	CS, CS-D/N, VLSI chassis	1
212-3012	Triple Controller	1
187-3249	Workstation	1
220-0447	Workstation cable	1
Customer Diag	nostics	
279-0873	CS-D chassis	1
212-3012	Triple Controller	1
187-3249	Workstation	1
220-0447	Workstation cable	1
289-0849	20MB Winchester	1

## Run-In Equipment Needs Analysis

MP&BM's proposed forecast for the CS386 CPU boards indicates that the average quarterly demand over the next year will average 273 system boards, and 191 spares and upgrades. The following analysis is based on this demand, and the run-in times previously proposed.

System 273/Qtr. 21/Week 4.2/Day (use 5) Spares/Upgrd 191/Qtr. 14.7/Week 2.9/Day (use 3)

If 5 run-in systems are made available, a maximum of 10 boards could be run-in per day. This would also provide a cushion, to the availability vs. demand problem.

The prefferred run-in mode is to use the Customer Diagnostics, which are not prom resident. This would mean an increase in the cost of any run-in stations. PSE has calculated that the average cost of a run-in station will be \$2300.40. Remanufactured equipment should be used if possible.

## Run-In Equipment List

	<u>Description</u> Terminal	Qty 1	MEI/Model# 2436DW	Available	_ <u>Needed</u>	<u>Cost</u> 597.27
(1)	CS-D/N Chassis	1	<b>279-087</b> 3			680.59
	Triple Cont.	1	212-3012			191.70
(2)	DS. DPU Board	1	212-7113			592.92
(2)	20MB Winch.	1	289-0849			204.95
(2)	360K Floppy	1	289-0846			74.49
					Total	2341.92
Alte	rnate Equipment			:		
(1)	VLSI chassis	1	270-1018	_		524.27
(1)	CS chassis	1	187-3316	~		418.79
(2)	2275-10 Disk	1	187-3505			1019.14

Note; Cost of CS chassis was calculated by subtracting cost of 210-8937X CPU board, which is not needed.

## Fault Analysis and Repair

All boards that fail pre test, functional test or run-in will be sent to the fault analysis and repair area. Completed units will be routed back to pre test.

Fault Analysis/Repair Station;

<u>Part Number</u>	<u>Description</u>	Qty.
None	Modified CS/D chassis	1
212-7113	DPU PCB	1
212-3012	Triple Controller	1
289-0846	360K Floppy	1
289-0849	20MB Winchester	1
289-0905	Tape Cassette Drive	1
187-3249	Workstation	1
220-0447	Workstation cable	1
666-1016	3.5V Lithium battery	1

## System Test


System test will follow the same procedure as the present CS-2 or CS-5D/N systems. The only difference will be the Operating System program, and the Customer Diagnostic program.

## System Run-In

System Run-In will follow the procedure as outlined in Manufacturing Test Procedure 167/187-3539-3542 (CS386-10N/20N/40N/80N), Run-In/Final Test..

### Final Test

If system to be shipped is a CS-N, the final test procedure is as outlined in the System Run-In step. If the system to be shipped is a CS-D, Test Procedure 167/197-3543-3546 (Final Acceptance Test) must also be performed.



TRIAD	101	ву	DATE	APPROVED BY	D.
<b>IWA</b>	LANGUATORING INC.	DWN EVO	945/89	E ENGR	$\prod$
(111		CHK		M ENGR	I
MATERIAL	MODEL NO.			MFG ENGR	П
l	C5386	TITLE	_		
1.0	SEE ENGRG. SPECIFICATIONS	BOARD	EST F	LOW (212-712	9X

ī	Z	
è		2
	5	
Ċ	Ś	5
E	2	5
•		

1 OF TYPE O. C. ENG. ASSEMBLY PROCEDURE MFG. ENG. AM Mahous 9/8/85 CS/386 CPU W/O DPU - FINAL ASSY DESCRIPTION hans 167/187-3539-3542 PREP. Br PART NO.

WRITER										
7	RELEASE TO MANUFACTURING								2.4	
ECO/MPC NO										
SHT. NO	ALL									
OPER NO SHT. NO ECO/MPC	ALT									
BON FOX	AB									
ISSUE	A									
ISSUE DATE ISSUE	9/12/89	٠					•			

DISTRIBUTION:

:																		
	TYPE ISS. REV. SHT. 1 OF 1	SPECIAL TOOLS/FIXTURES							T.P. 167/187-3539 THRU 3542			PER SPI 10-605						
SHEE	AL ASSY	STD																
ATION	1	WORK CTR.									·							
(WANG) OPERATION	167/187-3539-3542 DESCRIPTION CS/386 CPU W/O DPU	OPERATION	INSPECTION GUIDELINES	CS/386 CPU BOARD CHART	MOUNT/SECURE CPU BOARD	MOUNT/SECURE BLANK PANELS	SET POWER SUPPLY VOLFAGE	QC INSPECTION (INTERNAL)	RUN-IN/FINAL TEST	APPLY LABELS	MOUNT/SECURE COVERS	HY-POT	QC INSPECTION (EXTERNAL)	PACKAGING				
	PART 10.	OPER. No.	9*0	1.0	2.0	3.0	4.0	4.5	2.0	0.9	7.0	7.5	8.0	0.6				,

			(WANG)	<b>ASSEMBLY</b>	SHEET			•	•
PART NO.	167/18	167/187–3539–3542	DESCRIPTION	CS/386	CPU W/O DPU - FINAL ASSY		SHT. 1	0F 1	•
OPER.	0.5	0.5 OPERATION	INSPECTION GUIDELINES	IDELINES		ISSUE	REV. 1	TYPE	

## *** ATTENTION-IMPORTANT ***

THE FOLLOWING GUIDELINES ARE TO BE USED WHILE ASSEMBLING THIS PRODUCT.

- VERIFICATION OF PCB REVISIONS (E REV'S) BEFORE ASSEMBLY INTO UNITS.
- VERIFICATION THAT EXTERNALLY VISIBLE PARTS ARE FREE OF SCRATCHES, DISCOLURATION, IMPERFECTIONS, CORROSION OR ANY OTHER OBVIOUS COSMETIC DEFECTS.
- THIS INCLUDES KEY LOCKS, HINGES, SLIDES, LATCHES, SWITCHES, CASTERS, ETC. VERIFICATION THAT ALL HARDWARE IS FUNCTIONAL AND WORKS FREELY.
- INCLUSION OF ALL PROPER SWITCH SETTINGS.
- SPACING BETWEEN MATING PANELS, BEZELS, DOORS, OR EXTERNAL SUB ASSEMBLIES. INCLUSION OF PROPER ALIGNMENT AND BALANCE OF ALL VISIBLE GAPS OR
- INCLUSION OF PROPER TORQUE REQUIREMENTS FOR ALL HARDWARE FASTENERS
- THE INCLUSION OF QC CHECKS AS PART OF LAST OPERATION OF EACH SUB AND FINAL ASSEMBLY.

			(WANG)	ASSEMBLY	SHEET			240/76	
PART NO.	1/291	167/187-3539-3542	DESCRIPTION	CS/386 CPU W/O DPU - FINAL ASSY	- FINAL ASSY		SHT. 1	<b>0F</b> 1	
OPER.	1.0	OPER. 1.0 OPERATION	CS/386 CPU BOARD CHART	ARD CHART		ISSUE F	REV.	TYPE	

CS/386 CPU BOARD CHART

I ITEM NUMBER	MODEL NO.	I ITEM DESCRIPTION	I CPU BOARD
1 167/187-3539	I CS/386-10N	IMB CPU W/0 DPU	
167/187-3540	CS/386-20N	PU	212-7129
167/187-3541	CS/386-40N	1	212-7129
167/187-3542	CS/386-80N	8MB CPU W/0 DPU	1 212-7129-D


			<del></del>	•	-	 
	SHT. 1 OF 2	ISSUE REV. TYPE	<b>(1)</b>		<b>6</b>	FIG. 1
(WANG) ASSEMBLY SHEET	167/187-3539-3542 <b>DESCRIPTION</b> CS/386 CPU W/O DPU - FINAL ASSY	2.0 OPERATION MOUNT/SECURE CPU BOARD	1. 458-5026 COVER, PANEL, REAR (WELE 2. 449-0702 HANDLE, CHASSIS 3. 650-3200 SCR, 6-32 x 5/8 PL PN (2	USING THE HARDWARE AS SHOWN, SECURE THE CHASSIS HANDLE TO THE REAR PANEL COVER.  VERIFY TORQUE OF 6-32 HARDWARE TO 9 INCH/LBS.		
' 	PAG.	OPER. NO.	Ą	TO		•

<b>—</b>	
SHEET	
_ •	The second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second secon
EMBLY	
ASSEMBLY	
( WANG )	

PART NO.	167/187-3539-3542	DESCRIPTION CS/386 CPU W/O DPU - FINAL ASSY		SHT. 1	<b>0F</b> 1
OPER.	PER. 3.0 OPERATION	MOUNT/SECURE BLANK BRACKETS	ISSNE	REV.	TYPE

A. 1. 455-0093 BRACKET, BLANK 2. 650-4120 SCR, 8-32 x 3/8 SEMS (2) USING THE HARDWARE AS SHOWN, SECURE THE BLANK BRACKET TO THE REAR OF THE CHASSIS AT POSITION AS SHOWN.

VERIFY TORQUE OF 8-32 HARDWARE TO 18 INCH/LBS.




		(WANG)	<b>ASSEMBLY</b>	SHEET			·
167/187-3539-3542	. 1	DESCRIPTION	CS/386 CPU W/O DPU - FINAL ASSY	- FINAL ASSY		SHT. 1	<b>0F</b> 1 .
4.0 OPERATION	_	SET POWER SUPPLY VOLIPAGE	PLY VOLTRGE		ISSUE	REV. TI	YPE
	ı						

SET THE VOLTAGE SWITCH ON THE POWER SUPPLY AS FOLLOWS: Ä

FOR 167 ASSEMBLIES SET SWITCH TO 230V 50Hz. (INTERNATIONAL)

FOR 187 ASSEMBLIES SET SWITCH TO 115V 60Hz. (DOMESTIC)



		(WANG)	ASSEMBLY SHEET		:
PART NO.	167/187-3539-3542	DESCRIPTION	CS/386 CPU W/O DPU - FINAL ASSY	SHT. 1	<b>0F</b> 1
OPER. NO.	4.5 OPERATION	(INTERNAL)	ISSUE (INTERNAL)	REV. TI	rype

PERFORM INTERNAL INSPECTION

REFER TO OPERATION 0.5 "INSPECTION GUIDELINES".

F L L I	_	-
L	1	J
L	I T	
_	Ţ	-
(	S	
	<b>&gt;</b>	7
7	Ţ	ļ
١	Ţ	j
4	2	
L	ı	J
	5	
_		
•		
•		
•		֡֟֟֝֟֝֟֟֝֟֝֟֝֟֝
10:		
· · · · · · · · · · · · · · · · · · ·	SANC - SANC	Astonis inc

PART 16	167/187–3539–3542	DESCRIPTION	CS/386 CPU W/O DPU - FINAL ASSY		SHT.	1 <b>0F</b> 1
<b>OPER.</b> 5.0	.0 OPERATION	RUN-IN/FINAL TEST	EST	ISSUE	REV.	TYPE

PERFORM SYSTEM TEST USING T.P. 167/187-3539 THROUGH -3542.

:

, · <u>.</u> .

## LARGE PART (INTERNAL) **NSIDE UPPER RIGHT** REAR OF CHASSIS (RIGHT SIDE VIEW) TYPE 9 SHT. 1 REV. ISSUE PART OF THE LABEL TO THE OUTSIDE LOWER LEFT REAR OF THE CHASSIS, AS SHOWN. LABEL TO THE INSIDE UPPER RIGHT OF THE CHASSIS. APPLY THE OTHER LARGE MODEL NO. D□ N X CS/386-20 □ ☐ cs/386-80 ☐ REAR VIEW OF CHASSIS APPROXIMATE LOCATION. APPLY ONE OF THE LARGER PARTS OF THE SERIAL NO. MARK MODEL NO. ON LABEL PER CHART ON OPER. 1.0 APPLY THE MODEL NO. LABEL TO THE LOWER LEFT REAR OF THE CHASSIS. APPLY THE SMALL PART OF THE SERIAL NO. LABEL TO THE FRONT BEZEL (449-1577 REF.) BELOW THE WANG LOGO (451-3727 REF.) ON CENTER AT (WANG) ASSEMBLY SHEET CS/386 CPU W/O DPU - FINAL ASSY CS/386-40 SERIAL NO. (3 PARTS) FIG.3 LARGE PART (EXTERNAL) FRONT BEZEL (449-1577 REF.) LABEL, MODEL NO. DESCRIPTION APPLY LABELS LABEL, CORP. APPROX. WANG OPERATION CENTER 167/187-3539-3542 615-3872 615-4282 FRONT BEZEL CORNER OF UPPER LEFT 6.0 FIG. 1 SMALL PART OPER. NO. Ä

REV. TYPE	ISSUE	COVERS	MOUNT/SECURE COVERS	NO. 7.0 OPERATION	NO.
SHT. 1 OF 2		CS/386 CPU W/O DPU - FINAL ASSY	DESCRIPTION	167/187–3539–3542	NON I
		ASSEMBLY SHEET	(WANG)		


MOUNT THE L.H. AND R.H. COVERS TO THE CS-D/N FRAME BY INSERTING THE FRONT BRACKETS OF THE COVERS FIRST AND THEN PUSHING DOWN INTO POSITION.

COVER FOR SWITCH SETTING LABEL NOTE: CHECK INSIDE OF R.H.

- CS-D/N FRAME (WELD) REF. COVER, L.H. (WELD) REF. 458-3899 458-5028 a b
- 458-5029 615-4004 g Ĉ

LABEL, SWITCH SETTING REF. R.H. (WELD) REF.


COVER,




	2 <b>0F</b> 2	TYPE
	SHT. 2	REV.
		ISSOE
ASSEMBLY SHEET	TION CS/386 CPU W/O DPU - FINAL ASSY	MOUNT/SECURE COVERS
(WANG)	DESCRIPTION	MOUNT/SEC
	167/187-3539-3542	OPERATION
	167/18	ER. 7.0
	PART NO.	ADER.

MOUNT THE TOP COVER TO THE FRAME BY INSERTING THE FRONT BRACKET OF THE TOP COVER UNDER THE FRONT LIP OF THE FRAME AND SECURE WITH HARDWARE, AS SHOWN. В.

a) 453-5027 COVER, TOP (WELD) b) 656-4120 SCR, 8-32 x 3/8 PN HD PHL (2) VERIFY TORQUE OF 8-32 HARDWARE TO 18 INCH/LBS.



•	SHT. 1 OF 1	REV. TYPE		:	⊕ ° ⊕ ⊕	● ° • • • • • • • • • • • • • • • • • •	•	HYPOT GROUND PROBE
		ISSUE				⊕ ⊕ Primmum H ○		
(WANG) ASSEMBLY SHEET	DESCRIPTION CS/386 CPU W/O DPU - FINAL ASSY	HY-POT TEST	HY-POT PER SPI 10-605	ATTACH THE HY-POT GROUND PROBE TO THE BLANK (CKETS (455-0093 REF.) LOCATED ON THE REAR OF CABINET ASSEMBLY AS SHOWN ON ILLUSTRATION OW (UNPAINTED SURFACE).		BLANK BRACKETS (455-0093 REF.)	POWER CORD	FIG.1 REAR VIEW OF CHASSIS
	167/187-3539-3542	7.5 OPERATION		ATTACH THE HY-POT GROUND PROBEBRACKETS (455-0093 REF.) LOCATED THE CABINET ASSEMBLY AS SHOWN ON BELOW (UNPAINTED SURFACE).				:
	PART NO.	NOER.	A.					



PART 167/187-3539-3542         DESCRIPTION         CS/386 CPU W/O DPU - FINAL ASSY         SHT. 1. OF 1           NO. OPERATION         PACKAGING         TYPE			WANG	ASSEMBLY	SHEET			
OPERATION PACKAGING REV.	PART NO.	167/187-3539-3542	DESCRIPTION		FINAL ASSY		SHT.	i <b>0F</b> 1
	OPER. NO.	9.0 OPERATION	PACKAGING			ISSUE	REV.	TYPE

THE SHIPPING PACKAGE, 290-0685 AND **290-0685-02 THE FOLLOWING ITEMS ARE ALL PART OF

(A/R) TAPE 2" CLEAR POLY EDGE PROTECTOR (4) a)**685-0100 b) **685-0474

STRAPPING POLY .50 (A/R)

SEAL STRAPPING FOR

BAG GUSSET 23 x 17 x 36

PALLET 28.00 x 20.88 FOLHSC 27.13 x 20.00 c) **685-0664 d) **685-0665 e) 685-0723 f) 685-2410 g) 685-2411 h) 685-2412


CUSHION ASSY, TOP

PLACE CABINET ASSEMBLY ON CUSHION PALLET, AS SHOWN. PLACE GUSSET OVER CABINET AND PLACE TOP CUSHION ASSEMBLY ONTO CABINET ASSEMBLY AS SHOWN.

SET UP BOX, FOLD TOP FLAPS OVER AND SEAL WITH 2" CLEAR TAPE. PLACE BOX OVER CABINET, AS SHOWN. OVER THE TOP OF THE BOX, USE EDGE PROTECTORS ON RUN POLY STRAPPING UNDER CUSHION PALLET AND THE TOP OF THE BOX, SECURE STRAPPING USING STRAPPING SEALS, AT POSITIONS AS SHOWN,

615-2265 LABEL, DOCK MERGE

APPLY LABEL AT POSITION, AS SHOWN



INSPECTION GUIDELLINES   DESCRIPTION CS/386 CEU WITH DEU - FINAL ASSY   TYPE	WITH DPU - FINAL ASSY TYPE ISS. REV. SHT. 1 OF 1 " WORK STD. SPECIAL TOOLS/FIXTURES CTR. STD. SPECIAL TOOLS/FIXTURES
OPERATION         WORK         STD.           TON GUIDELINES         CPU BOARD         CPU BOARD           CPU BOARD CHART         CPU BOARD         CPU BOARD           ESCURE CFU BOARD         CPU BOARD         CPU BOARD           ESCURE CFU BOARD SET         CPU BOARD         CPU BOARD           ESCURE COVICKE         CPU BOARD         CPU BOARD           CCEPTION (INTERNAL)         CPU BOARD         CPU BOARD           CCEPTION (INTERNAL)         CPU BOARD         CPU BOARD           SECTION (EXTERNAL)         CPU BOARD         CPU BOARD           ING         CPU BOARD         CPU BOARD           IND         CPU BOARD	STD. SPECIAL
CON GUIDELINES COUR CARPT BECURE CEU BOARD BECTICA (INTERNAL) CCEPTANCE TEST ABELS BECTICA (EXTERNAL) CRETERNAL) CRETICA (EXTERNAL) CRETICA (EXTER	
CPU BOARD CHART SECURE DSPC BOARD SET SECURE DSPC BOARD SET SECURE DSPC BOARD SET SECURE DSPC BOARD SET SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COVERS SECURE COV	
BECURE CPU BOARD SECTION (INTERNAL) CCEPTANCE TEST ABELS BCTION (EXTERNAL) ING	
BECURE DSPC BOARD SET BER SUPPLY VOLTAGE  CCEPTANCE TEST ABELS BECURE COVERS BECURE COVERS  ING	
PECTION (INTERNAL)  ACCEPTANCE TEST  ABELS  BECURE COVERS  BECTION (EXTERNAL)  ING	
ABELS ABELS SECURE COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR COVERS FOUR	
ABETS ABETS SECURE COVERS SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS TO SECURE COVERS	
ABETS SECURE COVERS PECTION (EXTERNAL) ING	T.P. 167/187-3543 THRU 3546
SECURE COVERS  PECTION (EXTERNAL)  ING	
PECTION (EXTERNAL)	
	PER SPI 10-605
	į

<b> </b>		- }
L	1	J
_	1	-
<b>C</b>		
_		j
	ĭ	
9	5	<b>&gt;</b>
Į		j
(	ſ	)
(	ſ	
•		
	_	_
	WANC)	ABONATONISS INC

PART No.	167/18	167/187-3543-3546	DESCRIPTION	CS/386 CPU WITH DPU - FINAL ASSY	FINAL ASSY		SHT.	1 OF	1
OPER. NO.	0.5	OPERATION	INSPECTION GUIDELINES	ELINES		ISSNE	REV.	TYPE	

## *** ATTENTION-IMPORTANT ***

THE FOLLOWING GUIDELINES ARE TO BE USED WHILE ASSEMBLING THIS PRODUCT.

- VERIFICATION OF PCB REVISIONS (E REV'S) BEFORE ASSEMBLY INTO UNITS.
  - VERIFICATION THAT EXTERNALLY VISIBLE PARTS ARE FREE OF SCRATCHES, ISCOLORATION, IMPERFECTIONS, CORROSION OR ANY OTHER OBVIOUS COMETIC DEFECTS.
- HIS INCLUDES KEY LOCKS, HINGES, SLIDES, LATCHES, SWITCHES, CASTERS, ETC. VERIFICATION THAT ALL HARDWARE IS FUNCTIONAL AND WORKS FREELY.
  - 4. INCLUSION OF ALL PROPER SWITCH SETTINGS.
- PACING BETWEEN MATING PANELS, BEZELS, DOORS, OR EXTERNAL SUB ASSEMBLIES. NCLUSION OF PROPER ALIGNMENT AND BALANCE OF ALL VISIBLE GAPS OR
  - NCLUSION OF PROPER TORQUE REQUIREMENTS FOR ALL HARDWARE FASTENERS.
    - THE INCLUSION OF QC CHECKS AS PART OF LAST OPERATION OF EACH SUB AND FINAL ASSEMBLY.


# (WANG) ASSEMBLY SHEET

PART NO.	167/187-3543-3546	DESCRIPTION	CS/386 CPU WITH DPU - FINAL ASSY		SHT.	1 <b>0F</b> 1
OPER. NO.	PER. 1.0 OPERATION	CS/386 CPU BOARD CHART	RD CHART	ISSUE	REV.	TYPE

## CS/386 CPU BOARD CHART

	MODEL NO.	I TEM DESCRIPTION	I CPU BOARD
167/187-3543	CS/386-10D	IMB CPU WITH DPU	212-7129-A
167/187-3544	cs/386	2MB CPU WITH	212-7129-B
167/187-3545	CS/386-40D	MB CPU WITH DPU	212-7129-C
167/187-3546	CS/386-80	8MB CPU WITH D	212-7129-D

	1.	REV. TYPE	
		ISSUE	- TE - TE - TE - TE - TE - TE - TE - TE
WANG ASSEMBLY SHEET	DESCRIPTION CS/386 CPU WITH DPU - FINAL ASSY	MOUNT/SECURE CPU BOARD	COVER, PANEL, REAR (WELD) HANDLE, CHASSIS SCR, 6-32 x 5/8 PL PN (2) ARE AS SHOWN, SECURE THE CHASSIS HANDLE COVER. 6-32 HARDWARE TO 9 INCH/LBS.
	167/187-3543-3546	OPERATION	-5026 -0702 -3200 
		<b>OPER.</b> 2.0 <b>NO.</b>	A. 1. 458- 2. 449- 3. 650- USING THE TO THE REAR VERIFY TOROU




	SHT 1 OF 1	ISSUE REV. TYPE	FRONT FRONT FRONT FIG.2 RIGHT SIDE VIEW
ASSEMBLY SHEET	N CS/386 CPU WITH DPU - FINAL ASSY	s dspc board set	CHART.  FINGS". REFER TO "SWITCH SETTIN  OF R.H. COVER (458-5029 REF.).  SHOWN AND  OOF THE  CONNECTORS  CONNECTORS  CONNECTORS  CONNECTORS  FIG. 1  REAR VIEW  FROM THE PROPERTY  CONNECTORS  CONNECTORS  CONNECTORS  CONNECTORS  CONNECTORS  FIG. 1  REAR VIEW  FROM FROM FROM FROM FROM FROM FROM FROM
( WANG)	167/187-3543-3546 <b>DESCRIPTION</b>	.0 <b>OPERATION</b> MOUNT/SECURE DSPC BOARD	THE DSPC BOARD SET E REV. PE C BOARD SET "SWI SEF.) LOCATED ON THE DSPC BOARD OPTION FLAT CABL DSPC BOARD SET TIGHTENING THE ING HOLES, AS SH
		OPER. 3.0	VERIEY BOAL VERIEY BOAL VERIEY DSP (615-4004 B (615-4004 B C615-4004 B C615-40

PART 167/187-3543-3546 DESCRIPTION CS/386 CPU WITH DPU - FINAL ASSY  NO. OPER. 4.0 OPERATION SET POWER SUPPLY VOLTAGE  NO.			(WANG) ASSEMBLY SHEET		
4.0 OPERATION SET POWER SUPPLY VOLTRGE	PART NO.	167/187-3543-3546	CS/386		1
	OPER.	4.0	SET POWER SUPPLY VOLTRGE	ISSUE	REV. TYPE

SET THE VOLTAGE SWITCH ON THE POWER SUPPLY AS FOLLOWS: Ä.

FOR 167 ASSEMBLIES SET SWITCH TO 230V 50Hz. (INTERNATIONAL)

FOR 187 ASSEMBLIES SET SWITCH TO 115V 60HZ. (DOMESTIC)



•	<b>0F</b> 1	36	
	SHT. 1 C	REV. TYPE	
		ISSUE	
SHEEI	with dpu - final assy		
ASSEMBLY	CS/386 CPU WITH DPU	INTERNAL)	
WAING INC.	DESCRIPTION	OC INSPECTION (INTERNAL)	
	PART 167/187-3543-3546	OPER. 4.5 OPERATION NO.	
	ART 167/18	PER. 4.5	


PERFORM INTERNAL INSPECTION

REFER TO OPERATION 0.5 "INSPECTION GUIDELINES".

_		
L	L.	1
	L	
_		•
		)
•		
<i>-</i>		
C	r	
3	2	•
L	L	
C	ſ	)
	ſ	)
<	1	
	_	nafonits inc.
2	<u>2</u> `	Ę
4	A PIC	SORATORISE INC.
	\$	

ART 167	167/187-3543-3546	DESCRIPTION	၁ 98દ/သ	CS/386 CPU WITH DPU	- FINA	- FINAL ASSY		SHT.	1 <b>0F</b> 1	,
OPER. 5.0	OPERATION	FINAL ACCEPTANCE TEST	TEST				ISSUE	REV.	TYPE	

PERFORM SYSTEM TEST USING T.P. 167/187-3543 THROUGH -3546.



.,			
:	2	1	
	8	TYPE	
1	-	L	
	SHT.		
	18	REV.	. E. S.
		E	WELD) REF.
		<u></u>	SEE NOT
		ISSUE	
			R.H. SWITCH
			TING THE POSITION IL, SWITCH
	ASSY		LABER COVE
甲	M.		N S S S S S S S S S S S S S S S S S S S
is	- FINAL ASSY		I.ABEL I.ABEL S-400 S-400
	- 1		IING DOWN IG LABEL. 458-5029 615-4004
	1 11.		SETTING C) 4 d) 6
M	CPU WITH DPU		CS-D/N FRAME BY THEN PUSHING DOWN CH SETTING LABEL.  C) 458-5029 d) 615-4004
ASSEMBLY SHEET			
.: S	cs/386	SS	ST AND OR SWITCHER.
A	٥	MOUNT/SECURE COVERS	RS TO ENST
	NO	JRE (	COVERS ERS FIRS COVER FO  (WELD)  (WELD)
ANG	1	Sect	COVER (WELD (WELD)
WANG	DESCRIPTION	CINT/	FRAME L.H.
_	30	MC	ID R.H.  R.H.  I.H.  I.H.
	ب	Z	A P A P A P A P A P A P A P A P A P A P
	167/187-3543-3546	OPERATION	E L.H.  INSIDE  99 CS- 28 CO
	3543	PER	OUNT THE 1 CHECK INS 458-3899 458-5028
	187-	ō	OUNT TO CHECK 458-30 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 458-50 45
	167/	7.0	4 5 CH 4 5 4 5 4 5 4 5 4 5 4 5 4 5 4 5 4 5 4
			A. M. FROI a) b)
	PART NO.	OPER. NO.	A I


		WANG ASSEMBLY SHEET			
PAR TO	167/187-3543-3546	DESCRIPTION CS/386 CPU WITH DPU - FINAL ASSY		SHT. 2	<b>OF</b> 2
OPER. 7.0	7.0 OPERATION	MOUNT/SECURE COVERS	ISSUE	REV. TY	TYPE

ASSEMBLY SHEET


NG	THE FRONT BRACKET OF THE TOP COVER UNDER THE FRONT	SHOWN.
ERTI	THE	. AS
E BY INSERTING	NDER	<b>WARE</b>
E B	5 2	HARI
FRAM	COVE	WITH
THE	TOP	JRE 1
5	THE	SECL
OVER	OF	AND
TOP C	ACKET	RAME
THE	IT BI	HE
UNT	FRON	OF 1
Œ	THE	LIP
8		

COVER, TOP (WELD) SCR,  $8-32 \times 3/8$  PN HD PHL (2) 458-5027 650-4120 a)

VERIFY TORQUE OF 8-32 HARDWARE TO 18 INCH/LBS.




	SHT. 1 OF 1	ISSUE REV. TYPE	B B B B B B B B B B B B B B B B B B B
(WANG) ASSEMBLY SHEET	ā	ON HY-POT TEST	HY-POT PER SPI 10-605  ATTACH THE HY-POT GROUND PROBE TO THE BLANK BRACKETS (455-0093 REF.) LOCATED ON THE REAR OF THE CABINIT ASSEMBLY AS SHOWN ON ILLUSTRATION BELOW (UNPAINTED SURFACE).  BELOW (UNPAINTED SURFACE).  BLANK BRACKETS  (455-0093 REF.)  POWER CORD  FIG. 1  REAR VIEW OF CHASSIS
	167/187-3543-3546	ER. 7.5 OPERATION	ATTACH THE HY-POT GROUN BRACKETS (455-0093 REF.) L THE CABINET ASSEMBLY AS SH BELOW (UNPAINTED SURFACE).
	PART 167/3	ER.	A. BRACK THE C BELOW



## (WANG) ASSEMBLY SHEET

SHT. REV. ISSUE CS/386 CPU WITH DPU - FINAL ASSY DESCRIPTION PACKAGING **OPERATION** 167/187-3543-3546 OPER. No.

THE SHIPPING PACKAGE, 290-0685 AND **290-0685-02 THE FOLLOWING ITEMS ARE ALL PART OF



.50(2)

STRAPPING POLY .50 (A/R)

TAPE 2" CLEAR POLY

EDGE PROTECTOR (4)

Ä.

BAG GUSSET 23 x 17 x 36

b) **685-0474 c) **685-0664 d) **685-0665 e) 685-0723 f) 685-2410 g) 685-2411 h) 685-2412

SEAL STRAPPING FOR

FOLHSC 27.13 x 20.00 PALLET 28.00 x 20.88


CUSHION ASSY, TOP

PLACE CABINET ASSEMBLY ON CUSHION PALLET, AS SHOWN. PLACE GUSSET OVER CABINET AND PLACE TOP CUSHION ASSEMBLY ONTO CABINET ASSEMBLY, AS SHOWN.

SET UP BOX, FOLD TOP FLAPS OVER AND SEAL WITH 2" CLEAR TAPE. PLACE BOX OVER CABINET, AS SHOWN. RUN POLY STRAPPING UNDER CUSHION PALLET AND OVER THE TOP OF THE BOX, USE EDGE PROTECTORS ON THE TOP OF THE BOX. SECURE STRAPPING USING STRAPPING SEALS, AT POSITIONS AS SHOWN.

## 1. 615-2265 LABEL, DOCK MERGE

APPLY LABEL AT POSITION, AS SHOWN



; _	•								·
	WANG MANUFACTURING  O666S TEST PROCEDURE						PART NO. 167/187-3539-3542		
-						FL	SHEET 1 OF 6		
							<b>DATE</b> 09/14/89		
	CS386	TITLE  CS386-10N/20N  40N/80N		PART NUMBER 167/187-3539-3542			TYPE OF TEST  RUN-IN/FINAL TEST		
ł	APPROVAL			APPROVAL			APPROVAL		
		MICAL WRITER 9-12-89 Manne M. Clark	PRODUCT SUPT. ENGR.						
	Bildonofue 9/14/89			FILOT ENGR.					
	REVISION HISTORY								
4	REV.	DESCRIPTIO	DESCRIPTION			MPC/ECO		DATE	CHANGED BY
								09/08/89 09/12/89	S.CLARK
					,				
		,							
		·							
									<del> </del>

Distr. VS

WANG:)

## MANUFACTURING TEST PROCEDURE

PART NO.

167/187-3539-42

SHEET 2 OF 6

DATE 22/1/15

TITLE

CS386-N (167/187-3539 THRU 3542) RUN-IN/FINAL TEST

## 1. PURPOSE

- 1.1 To allow an operator to thoroughly test the CS386-10N thru CS386-80N (167/187-3539-3542).
- 1.2 To standardize the testing of the CS386-N.

## 2. SCOPE

2.1 This procedure applies to the testing of the 167/187-3539 thru 167/187-3542 only.

## 3. REFERENCES

- 3.1 Guidelines for Writing Test Procedures (PROC-0009)
- 3.2 Hypot Test Documentation (SP1-10-605).
- 3.3 Appendix A (Safety Instructions).

## 4. <u>RESPONSIBILITIES</u>

4.1 Refer to GUIDELINES FOR WRITING TEST PROCEDURE (PROC-0009) section 4., for a detailed listing of responsibilities.

## 5. HARDWARE REQUIREMENTS

- 5.1 (1) 2236DE Workstation or equivalent
- 5.2 (1) 2275 Disk Drive
- 5.3 (1) 210-6541 Disk Controller
- 5.4 (1) 212-3012 Triple Controller
- 5.5 (1) 8022A Multimeter (voltage meter)

## 6. <u>SOFTWARE REQUIREMENTS</u>

- 6.1 (1) CS386 BASIC-2 O.S. (rev 1.0 or greater)
- 6.2 (1) CS386 Customer Diagnostics (rev 1960 or greater)

## 7. <u>DOCUMENTATION REQUIREMENTS</u>

7.1 167/187-3539 thru 167/187-3542 Assembly Process Sheet.

## WANG MANUFACTURING TEST PROCEDURE

PART NO. 167/187-3539-42 SHEET DATE

TITLE

CS386-N (167/187-3539 THRU 3542) RUN-IN/FINAL TEST

#### **DESCRIPTION** 8.

Run-In will be 24 error free hours or six hours if the CPU 8.1 PCB was previously Run-In for 24 hours in a specified Run-In chassis. If an error occurs and the solution is to replace the CPU board, the system must be run-in for an additional 24 hours. If the error correction is anything other than a board (i.e. power supply or chassis), the system will also be run-in for an additional time period.

NOTE: BEFORE INSTALLING THE CPU PCB, VERIFY THAT J5 IS CORRECT.

212-7129-A, B 212-7129-C, D MODEL MEI

167/187-3539 CS386-10N 167/187-3540 CS386-20N 167/187-3541 CS386-40N CS386-80N 167/187-3542

CPU PCB

212-7129-A 212-7129-B 212-7129-C 212-7129-D

### PRELIMINARY ASSEMBLY 9.

Insert the PCB's as shown below: 9.1

-		_	_	_	_	_	_	_	_	2	丁
!	2	2	S	S	S	2	2	2	2	2	•
!	1	1	P	P	Р	Ρ	Ρ	Р	Ρ	1	!
!	0	2	Α	Α	Α	Α	Α	Α	Α	2	!
!			R	R	R	R	R	R	R	_	!
!	6	3	Ε	Ε	Ε	Ε	Ε	Ε	Ε	7	:
!	7	0								1	!
İ	8	1	Ι	I	I	I	Ι	Ι	Ι	2	!
-	_	-	7	_	_	_	_			9	!
!			-	-			0				<u>!</u>

NOTE: DO NOT APPLY POWER TO THE SYSTEM UNTIL ALL BOARDS HAVE BEEN INSERTED!

# WANG MANUFACTURING TEST PROCEDURE

PART NO. 167/187-3539-42 SHEET DATE

TITLE

CS386-N (167/187-3539 THRU 3542) RUN-IN/FINAL TEST

#### 10. **VOLTAGE MEASUREMENT**

- Plug the CPU into the correct receptacle (i.e. 50HZ into a 50 HZ).
- 10.2 Add an 7129-X CPU/MEM PCB and a 212-3012 Triple Controller PCB as a minimum load into any of the available I/O slots while leaving test points TPI - TP5 accessible.
- 10.3 Power up the system and read the voltages as follows (this is the beginning of Run-In):
  - Voltage readings are taken from the test points 10.3.1 labeled TP1 - TP5 on the 9560 motherboard. If voltage readings cannot be adjusted within the stated specification, reject the unit.
  - The power supply must be partially removed from 10.3.2 the chassis to access voltage adjustments.
  - Attach the negative lead (black) of the 10.3.3 voltmeter to the test point labeled TP1.
  - Attach the positive lead (red) of the voltmeter 10.3.4 to TP3. This is the +5V measuring point. The required voltage is +5.00 to +5.25VDC; +5.00 VDC optimum. If the voltage is outside these limits, adjust using a non-metallic screwdriver by turning the pot on the lower left hand side of the switching power supply facing the CPU board. If it cannot be adjusted within the stated specifications, reject the system.
  - Attach the positive lead (red) of the voltmeter 10.3.5 to TP4. This is the +12V measuring point. The required reading is +12.00 to 12.20 VDC; +12.00VDC optimum. If the voltage is outside these limits, adjust using a non-metallic screwdriver by turning the pot on the lower right hand side of the switching power supply facing the CPU board. If it cannot be adjusted within the stated specifications, reject the system.

## WANG) MANUFACTURING TEST PROCEDURE

PART NO. 167/187-3539-42 SHEET DATE

TITLE

CS386-N (167/187-3539 THRU 3542) RUN-IN/FINAL TEST

#### 10. **VOLTAGE MEASUREMENT**

- Attach the positive lead (red) of the 10.3.6 voltmeter to TP2. This is the -5V measuring point. The required voltage reading is -4.80 to -5.20 VDC; -5.00 VDC optimum. This voltage is not adjustable. If the reading does not meet the specification, reject the system.
- Attach the positive lead (red) of the 10.3.7 voltmeter to TP5. This is the -12V measuring point. The required voltage reading is -11.50 to -12.50 VDC; -12.00 VDC optimum. This voltage is not adjustable. If the reading does not meet the specification, reject the system.

### 11. INITIAL RUN IN

- 11.1 After ensuring that the voltages are correct, power down the unit. Connect the disk cable to the disk output of the triple controller.
- 11.2 Power <u>UP</u> the unit. The following message will appear on the workstation screen:

## MOUNT SYSTEM PLATTER PRESS RESET

11.3 Press the RESET button. The following prompt will appear on the screen:

SF ?

- 11.4 Press the SFO key. The "User Menu" will appear on the workstation screen.
- 11.5 Select "Diagnostics". Press the RUN key.
- 11.6 Run this diagnostic for 6 hours.

# WANG MANUFACTURING TEST PROCEDURE

PART NO. 167/187 - 3539 - 42 SHEET DATE 09/14/89

TITLE

CS386-N (167/187-3539 THRU 3542) RUN-IN/FINAL TEST

### INITIAL RUN IN (cont'd) 11.

- 11.7 Place six (6) 478-0863 faceplate PC blanks onto the first six I/O slots.
- 11.8 Once the unit has been run-in for the required time period, Q.C. must verify run-in data.
- 11.9 Power down the unit.
- 11.10 If the unit has passed with "O" errors, fill out the appropriate paperwork and complete assembly per 167/187-3539-3542 Assembly Process Sheet.
  - If the unit did not pass with "0" 11.10.1 errors, fill out the appropriate paperwork, noting the discrepancy, and send the unit to the REPAIR AREA.
- 11.11 Run a standard Hypot test (reference Documentation SP1-10-605).

WANG:

## MANUFACTURING TEST PROCEDURE

PART NO.		
SHEET	OF	
DATE		

TITLE

## APPENDIX A

## SAFETY INSTRUCTIONS

- 1. No unauthorized person shall use or be permitted to use the testing equipment.
- 2. Testing will be performed on a wooden bench whenever possible.
- 73. There shall always be two knowledgeable persons in the immediate area whenever the dielectric voltage-withstand test is being performed.
  - 4. No AC outlet shall be used that is not properly grounded.
  - 5. No adapters of any kind shall be used on the power cord for Hypot tester.
  - 6. Personnel performing the test shall be alert, cognizant, and maintain a constant awareness that lethal high voltages are present.
  - There shall be periodic checking of all wires, clips, and all insulation relating to the test equipment.
  - 8. The test area should be clear of debris.
  - Do not touch the UUT while testing is being performed.

B	WANG			A	ASSEM	BLY PROCEDURE	-	1 OF 1
PART NO.	167/18	167/187-3543-3546		DESCRIPTION		CS/386 CPU WITH DPU - FINAL ASSY	MODEL	TYPE
ā.	PREP. /	Both	bare	3	MFG. ENG. APPROVAL	An Mahay 18/89 REVIEW (36)	de Sonoghi	Josephus 911/185
ISSUE DATE	E ISSUE	BOM REV.	OPER NO.	SHT. NO	ECO/MPC NO	/ DESCRIPTION	0	WRITER
9/12/89	A	AB	ALL	ALL		RELEASE TO MANUFACTURING		
		,		•				
			·					
•						-		
DISTRIBUTION:	: RO1	δ <u>Ω</u>						
		}						



. .

# WANG

TO:	JUAN PENA
COMPANY:	WANG LABS PR
LOCATION:	PUFRTO RICO
FAX #:	(809) 734-8775
FROM:	STEVEN ANTHONY
DATE:	12/13/89
# ~4 B 4 G E 6	Tachding Cause

TO:

JUAN PENA

FROM:

STEVEN J. ANTHONY

SUBJECT:

2200/386 RUN-IN OF 212-7129A-D PCB SET

DATE:

12 DEC 89

In October of 1989, the Pawtucket Boulevard Manufacturing facility began production of the the 2200/386 pcb card set, 212-7129A-D (PCB 210-9561A-D and PCB 210-9562). Due to the reschedule of site sourcing at this time, PCB Run-In test equipment was not available and therefore Functional Run-In of these PCB's was not available in Pawtucket Boulevard. In lieu of the complete run-in capabilities, the PB maufacturing site has been performing a limited Built In Test for 24 hours as a prerequisit to final shipment.

Due to the lack of Run-In equipment, which is currently on order, and until this Run-In equipment becomes operational in Pawtucket Boulevard, it is recommended by the PB PCB Test Engineering group that at least a 12 HR Run-In Test be performed in Wang Labs Puerto Rico per the attached Run-In test Procedure titled "CS386 Run-In Test". If there are any questions, please contact me at Tel. (508) 656-4478.

Steven J. (Anthony

<u> </u>					
(WANG) MANU	FACT	JRIN		PART N	<b>O.</b> 212-7129A-
0664S TEST			RF	SHEET	1 OF
TITLE CS386	210- 210-	<b>T NUMB</b> -9561A-D -9562	ER	TYPE O	09/14/89 F TEST -IN TEST
APPROVAL		-7129A-D PROVAL			APPROVA
TECHNICAL WRITER 9-12-09 LUJANNE M. Clark	PRODUCT S	A	IGR. 9/12/89		

PILOT ENGR.

9/14/20

## REVISION HISTORY

REV.	DESCRIPTION	SHT.	MPC/ECO	DATE	CHANGED BY
	PRELIMINARY DRAFT CHANGES PER ENGINEERING SMALL CHANGES	n/a	n/a		S. CLARK S. CLARK
				_	
	Distr. VS Board Area				

## WANG MANUFACTURING TEST PROCEDURE

PART NO. 212-7129 A-D SHEET OF DATE 09-14-89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

#### 1. **PURPOSE**

1.1 To detail the steps necessary when performing a RUN-IN test on the CS386 CPU assembly (212-7129A-D).

NOTE:

THERE ARE TWO METHODS THAT CAN BE USED TO RUN-IN THE CPU ASSEMBLY. THIS PROCEDURE COVERS RUNNING THE ASSEMBLY WITHIN THE CS386 SYSTEM. SEE APPENDIX 7.1 FOR A PROCEDURE ON HOW TO RUN THE ASSEMBLY USING THE BUILT IN TEST (BIT).

- 2. REFERENCES
  - 2.1 None required.
- **RESPONSIBILITIES** 3.
  - Refer to GUIDELINES FOR WRITING TEST PROCEDURES (PROC-0009), section 4., for a detailed listing of responsibilities.
- EQUIPMENT REQUIREMENTS 4.

DESCRIPTION	PART NUMBER	QTY
2436 Workstation	187-3249 or equi	v1
Test fixture which includes:	289-0846	1
20MR Winchester		
- DPU PCB	212-/113	
- IT THE CONCLOTTER STATE		

#### SETUP PROCEDURE 5.

5.1 Verify that the jumper (J5), located on the 210-9561X board, is positioned as shown below:





- 5.2 Connect the battery (from the test fixture) to location J2 of the 210-9562 board.
- 5.4 Insert the assembly under test (212-7129A-D) into the CPU position of the test bed motherboard.

# WANG) MANUFACTURING TEST PROCEDURE

PART NO. 212-7129A-D SHEET OF DATE 09-14-89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

- 6. ACTUAL TEST
  - 6.1 Power UP the test bed. The following screen will appear:

COPYRIGHT, WANG LABORATORIES, INC., 1989 REV 5930

SRAM 256KB DRAM XXXXKB LOOP COUNT: XX

- 6.2 Verify that the amount of "D RAM" tested is equal to that expected for the assembly under test (see above). If the amount is less than expected, the assembly has failed.
- 6.3 The following message will appear:

Mount system platter Press Reset

- 6.4 After the LED on the floppy drive has extinguished, press the SHIFT and RESET keys simultaneously (SHIFT/RESET).
- 6.5 The following prompt will appear on the monitor screen:

Key SF?

# WANG) MANUFACTURING TEST PROCEDURE

PART NO. 212-7129A-D SHEET DATE 9-14-89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

- 6. ACTUAL TEST (cont'd)
  - 6.6 Press the SFO key. The following screen will appear:

**** SYSTEM SOFTWARE ****

Select item with SPACE & BACKSPACE. MEMORY 1024 K Key RUN to execute, CLEAR or PREV for previous screen TERMINAL 1

# Multiuser BASIC-2

. Diagnostics

- 6.7 Select "DIAGNOSTICS". Press the RUN key. The "Customer Diagnostic" screen will appear.
- 6.8 Allow the test to run for a specified period.
- 6.9 When complete, press the SHIFT and RESET keys at the same time (SHIFT/RESET). Disconnect the battery and remove the assembly from the test fixture.
- 6.10 If the assembly has run error free, fill out the appropriate paperwork and submit the assembly for FINAL ACCEPTANCE TESTING.
- 6.11 If a failure was detected, fill out the appropriate paperwork, noting the discrepancy, and send the assembly to the REPAIR AREA.

# WANG MANUFACTURING TEST PROCEDURE

PART NO. 212-7129A-D SHEET DATE

TITLE

CS386 (212-7129A-D) RUN-IN TEST

- 7. APPENDIX - ALTERNATE TEST
  - 7.1 RUN-IN TEST (BIT):

## 7.1.1 EQUIPMENT REQUIREMENTS

- One 2436 Workstation (187-3249 or equivalent)
- One Cabinet Assembly CS-D/N (279-0873)
- One Triple Controller (212-3012)

## 7.1.2 SETUP PROCEDURE

Verify that the jumper (J5), located on the 7.1.2.1 210-9561X board, is positioned as shown



- Connect the battery (from the test fixture) 7.1.2.2 to location J2 of the 210-9562 board.
- Attach jumper to location J7 of the 210-9561 7.1.2.3 board.
- Insert the 212-3012 Triple Controller into 7.1.2.4 any available slot.
- Attach a workstation cable to the terminal 7.1.2.5 position of the 212-3012 Triple Controller.
- Insert the assembly under test (212-7129A-D) 7.1.2.6 into the CPU position of the motherboard.

# WANG) MANUFACTURING TEST PROCEDURE

PART NO. 212-7129A-D 6 SHEET OF DATE 09/14/89

TITLE

CS386 (212-7129A-D) RUN-IN TEST

- APPENDIX ALTERNATE TEST (cont'd) 7.
  - 7.1 RUN-IN TEST (BIT): (cont'd)

## 7.1.3 ACTUAL TEST

SRAM 256KB

Power  $\underline{\text{ON}}$  the test bed. The following screen 7.1.3.1 will appear:

LOOP COUNT: XX

COPYRIGHT, WANG LABORATORIES, INC., 1989 REV 5930

DRAM	XXXXKB	
	7.1.3.2	Verify that the amount of "D RAM" tested is equal to that expected for the assembly under test (see above). If the amount is less than expected, the assembly has failed.
•	7.1.3.3	The assembly under test will continue to cycle for a specified run-in period (or until an error is detected).
	7.1.3.4	Run the diagnostic for a specified period.
	7.1.3.5	When complete, press the SHIFT and RESET keys at the same time (SHIFT/RESET). Power down the test bed. Disconnect the battery and remove the assembly from the test fixture.
	7.1.3.6	If the assembly has run error free, fill out the appropriate paperwork and submit the assembly for FINAL ACCEPTANCE TESTING.
	7.1.3.7	If a failure was detected, fill out the appropriate paperwork, noting the discrepancy, and send the assembly to the REPAIR AREA.

# 12.2 Magnetic Devices

SAME AS V5516

## **ILLUSTRATED PARTS**

210 - 3162 FOR NS W 5178 . 1.

	278 TESTER  278 Part No	į	
	Wang Part No.	Vendor Part No.	
5 1/4" HH 360KB Floppy	278-4033	JU455	725.0142
5 1/4" HH 1.2MB Floppy	278-4055	JU475	725-0232
5 1/4" HH Cassette Tape	725-1481	MT-2ST	— 725- 0258 e.,
10 MB HH Removeable Disk	278-4049	RH5130/360	725-0195
20 MB HH Winchester	278-4062	ST225/D5126	725-0242
32 MB FH Winchester	278-4034	Q540 QUANTUM	
32 MB FH Winchester	278-4069	1323 MICROPOLIS	725-0254
64 MB FH Winchester	278-4054	1325W	725-023
112 MB FH Winchester	725.4221	Maxtor 7 x 16	 }725-0211
140 MB FH Winchester	1250211	Maxtor 14 x 10	
32 MB HH Wire (42 med)	725-3493	CDC MAG PERIPH 9420	5·53
I/O CABLE.	220-0364		E. Co
WINC A CABLE	220-3629		,
Wine B CABLE	220-3630		
FLOPPY CABLE	220-3629		
CASSETTE CABLE	220-3628		
TEAC TAPE CLEANING KIT	725-7374	TEAC # TZ 380	
CDC Imprimus MAG PERIPH MN94205-5	3 HH 42 Ma 725-3493	MN94205-53	
150 MEG TAPE DEVE	725.4893	TEAC MT-25T NSS-	2ე.∪
STANDOFFS FOR I/O CROLE	462-0611		




FIGURE 8-15 WL NO. 210-7696-A MICROCOMPUTER/MEMORY (DPU)

## 2200 386 TURBO

The 386 Turbo is the latest edition to the 2200 family. It consists of 4 major components, a new CPU motherboard, one version compatible to the CS-D and CS-N, a 2nd version compatible to the CS and MicroVP, a new 386 based CPU board, a new 16 port MXF terminal controller board, and a new printer/disk controller. Together this new hardware provides dramatic improvement in performance over existing 2200 hardware. Most hardware and software compatible to the 386 is 100% compatible to the 'Turbo'. Some of the disk drives such as the 2270A are still being evaluated to determine if they can be made to work with the Turbo. As for the software, changes may be necessary for those programs which reference a status byte in the O/S or the CPU ID number. There could also be problems with non-standard GIO commands. See TSB HWT 9640 due out in November 1991 or the updated CS Maintenance Manual, 741-1769A, which includes the Turbo for details under 'Compatibility'. Additionally, for maximum performance, programs must be in 'NEW' or '386' format. In conjunction with the new Operating System required by the 'Turbo' the following major enhancements have been made:

- supports up to 64 user partitions.
- supports up to 64 terminals. 32 is the recommended max currently.
- supports from 4 Meg to 32 Meg of memory.
- extended RAM Disk capabilities, all non-partitioned memory, address 340.
- <u>CPU processing speed</u> twice as fast as the 386, 4 to 6 times faster than the VLSI and MVP/LVPs.
- supports 3 byte addressing which will allow disk surfaces greater than the current 16 Meg restriction. Will only be supported on the DS with the next prom revision, R4, due out the end of the year and with the Turbo SCSI Controller due out the beginning of 92.
- new <u>\$MOVE!</u> command simplifies conversion of programs from 'OLD' to 'NEW' format.
- Disk I/O performance is up to 25% faster with existing drives. The percentage of improvement will vary according to the number of users on the system and amount of disk access. In the past, disk access was strictly a serial function. If the disk access time for a particular function was '5' seconds, then every user running that function would require '5' seconds. The new disk controller (22Cll-2) is an intelligent controller and can handle disk I/O on it's own while the CPU does other tasks. This allows an improvement in performance that increases as the number of users increases. On a system of 1 to 3 users an improvement in disk performance may not be seen as basically the disk drives themselves are the slowest factor and not the interface. Some changes may be necessary with some software for maximum disk performance. Changing programs on disk to 386 or 'NEW' format is highly recommended.
- new SCSI Controller built for the Turbo provides 7-10 times the throughput of the DS. Due out beginning of '92.

## '386' TURBO CARD SET

MOTHERBOARD: 210-9578 (mandatory) compatible to the CS-D/N only.

210-9583 (mandatory) compatible to the CS and MicroVP only

Switch settings - none

Jumpers - none

Test points - (for 9578) located underneath the 7th I/O slot (for 9583) exact location to be determined

TP1 - -12V +/-.50 (not adjustable)

TP2 - +12V +/-.05 (pot located inside PS on left side front)

TP3 - +5V +/-.05 (pot located inside PS on left side rear)

TP4 - -5V +/-.05 (not adjustable)

TP5 - +/-0V

## Connectors

J34 - 4 pin connector to front panel LEDs (top left from rear) unnecessary on the 9583.

J31 - 5 pin connector to PS (bottom right from rear)

J32 - 3 pin connector to PS (bottom right from rear)

J33 - 2 pin connector to PS (bottom right from rear)

CPU BOARD: 210-9576A (mandatory) consists of 210-9576 Mbrd & 210-9577 Dbrd (comes with all SIMM Memory Modules rewmoved)

The board can be loaded for 4 different memory sizes:

SIMM Part #	Memory Size	SIMM Modules	SW1 on 9576
377-4533	4 Meg	4 1 Meg SIMMs in L3,L10,L18,L29	4 closed only
377-4533	8 Meg	8 1 Meg SIMMs	4 closed only
377-4535	16 Meg	4 4 Meg SIMMs in L3,L10,L18,L29	all open
377-4535	32 Meg	8 4 Meg SIMMs	all open

## Jumpers - 210-9576 Motherboard

J4 - OUT (2 pin jumper in top rt corner - for Brd Repair)

J5 - 1-2 for 27C256 E Proms at L50/L64 (ctr of brd above J6)

2-3 for 27C512 E Proms at L50/L64

J6 - IN (2 pin jumper above L59 - for Brd Repair)

J7 - IN (2 pin jumper under rt corner of clk Y1 - for Brd Rpr)

J8 - OUT (2 pin jpr next to SWl - for Brd Repair)

<u>LED1 - 210-9576 Motherboard</u> Diagnostic Indicator - comes on during power up & goes out if passes diagnostics (lower right corner of SIMMs)

## Jumpers - 210-9577 Daughterboard


J3 - IN (2 pin jumper above L18 - for Board Repair)

J4 - OUT (2 pin jumper above L25 - for Brd Repair)

## Connectors - 210-9577 Daughterboard

J2 - obsolete. 2 pin conn which was to be used for for Battery (666-1016) Backup for clk. New real-time clock chip L5 with built-in battery eliminates need for connector J2.


<u>LED1</u> - Diagnostic Indicator - comes on during power up & goes out if passes diagnostics (beside L28)



## **386 TURBO**

## **Controls and Indicators**

## Motherboard 210-9578



- MXF 16 PORT TERMINAL CONTROLLER: 212-9717 (desirable for maximum performance)
  - consists of 210-9579A Hi Speed I/O Proc Brd & 210-9580 Term Cont Brd.
  - supports all workstations currently supported by the MXE and MXD.
  - number of terminal controller boards cannot exceed 64 terminals. Total number of terminal controller boards cannot exceed 4. With 3 MXF boards, you can use only 1 MXE/MXD, with 2 MXFs up to 2 MXE/MXDs, and so forth. In setting up terminal numbers always start with the MXFs first. In numbering the MXE/MXD board as set by it's 4/5 bank switch, count the MXFs as you would MXEs. That is if 1 MXF exists the 1st MXE or MXD would be set as board 2, with 2 MXFs it would be board 3, and with 3 MXFs it would be board 4. The switch settings for the MXE/MXD boards are set the same as they have always been.

## External Connectors

J5 - top connector, RS232 type, for term 1 (same as MXE/MXD)

J4 - 2nd connector, RS232 type, for term 2 (same as MXE/MXD)

J3 - 3rd connector, 36 pin Amphenol, for terminals 3 thru 9 (must use special Octopus Adapter Cable, 421-0181, with 36 pin male connector on 1 end and 7 female RS232 conn on other)

J2 - 4th connector, 36 pin Amphenol, for terminals 10 thru 16 (must use special Octopus Adapter Cable, 421-0181, with 36 pin male connector on 1 end and 7 female RS232 conn on other)

LED1 - Self-Test Indicator - on during power up & goes out if passes

Switch Settings - 210-9579 High Speed I/O Processor Board

SWl sets the MXF Board Number from 1st board to 4th board.

1st MXF (term 1-16) - 1,2,4 ON only: 2nd MXF (term 17-32) - 2,4 ON only

3rd MXF (term 33-48) - 1,4 ON only: 4th MXF (term 49-64) - 4 ON only

## Switch Settings - 210-9580 Terminal Controller Board

SW1 thru SW8 control the baud rates for up to 16 terminals.

*** SW1 thru SW8, all sw's OFF - DIAGNOSTIC RUN-IN MODE.

RUN-IN Mode can be run on any MXF board with a terminal attached to port 1. The CPU is inoperable during this test. To run on the 1st MXF, the CPU board must be removed. A loopback connector is required for a channel to pass the test. The test will continually loop however without loopback connectors. The test is used to test the port and gives either a 'Pass or Fail' response. Some PCs or modems could hang the test because of the presence of a signal on a line normally unused by the standard Wang 2200 terminals. A signal on pin 8 would commonly do this.

Loopback Conn: J5/J4 2,3; J3/J2 2,20; 4,22; 7,25; 9,27; 12,30; 14;32; 17,35

PORT Assignments Terminal # 3 5 6 789 2 10 11 12 13 14 15 16 1 switches 1-4 SWl SW3 SW4 SW5 SW6 SW7 SW8 switches 5-8 SW2 SW3 SW4 SWl SW5 SW6 SW7 SW8

BAUD Rate Settings

38400 = 2,3,4 or 5,6,7 ON only : 19200 = 1,3,4 or 5,7,8 ON only 9600 = 3,4 or 7,8 ON only : 7200 = 1,2,4 or 5,6,8 ON only 4800 = 2,4 or 6,8 ON only : 2400 = 4 or 8 ON only


1800 = 1.2.3 or 5.6.7 ON only : 1200 = 2.3 or 6.7 ON only 600 = 1.3 or 5.7 ON only : 300 = 3 or 7 ON only 200 = 1.2 or 5.6 ON only : 150 = 2 or 6 ON only


134.5 = 1 or 5 ON only : 110 = or ON only *** Note: All unlisted Baud rates will default to 19200 except all OFF.

## Jumpers

Pl - IN (2 pin jumper on 9579 board next to clock Yl for MFG)
JPl - IN (2 pin jumper on 9580 board next to clock Yl for MFG)

# MXF 16-Port Terminal Controller (212-9717) 210-9579





## **386 TURBO**

7411700-4C-2.2-2

### SettIngs MXF 16-Port Terminal Controller (212-9717) 210-9580 2400 600 38400 9600 **SW1** SW2 -]@ Port 1 Port 3 ]ဖ യ **[** <u>]</u>[ 19200 4800 1200 300 4 4 <u>]</u>ෆ ]က Port 2 Port 4 10 ]N OFF OFF P1 1 Crystal Enable OZO **SW3** LED1 Port 5 J5 ]10 J4 · Port 6 **J3** · **SW4** Port 7 **J2** -**J O ]**[ <u>]</u>ෆ Port 8 SW7 SW8 SW6 **SW5** Port 13 Port 15 Port 11 Port 9 ၂တ <u>]</u> ( 10 Jω 2 **[** <u>က</u>[ 45 4 4 က ]က ]က Port 16 **Port** Port 14 <u>]</u>ෆ Port 12 ]( 7 10

- 22C11-2 PRINTER/DISK (DUAL) CONTROLLER: 212-9718 (desirable for maximum performance. In some situations, some software changes may be required to take advantage of full performance capabilities. Contact the 2200 BASIC-2 Platform Group for further information.)
  - consists of 210-9579 Hi Speed I/O Proc Brd & 210-9581 Periph Cont Brd.
  - disk port supports all disk drives except SCSI.
  - printer port supports all existing 2200 printers.
  - mux port can be used as a 22C80 (210-7715) if the disk port is not used.

## External Connectors

J4 - Printer port (top connector, cabled directly to printer)

J3 - Disk Mux port (middle connector, allows the controller to be used in place of a 22C80 (7715) which would cable to a CPU port on a 2275 MUX Master, MUX Extender, or similar brd.)

J2 - Disk Port (bottom connector, cabled directly to disk)

NOTE: Only J3 or J2 can be used at 1 time as determined by SW1.

<u>LED1</u> - Diagnostic Indicator - comes on during power up & goes out if passes diagnostics

## Switch Settings - 210-9579 High Speed I/O Processor Board

SW1 sets the disk address for all access through this controller.

SW1 - 1 2 3 4

OFF ON ON ON = address 310 selected ON OFF ON ON = address 320 selected OFF OFF ON ON = address 330 selected

## <u>Switch Settings - 210-9581 Peripheral Controller Board</u>

SWl activates the Disk MUX port. If the MUX port is activated, the disk port is inactive. The MUX port is equivalent to a 22C80 (210-7715) controller. It therefore most often will connect to a 210-8824 2275 MUX Master CPU port to share access to the drive attached to the Disk port of the 2275 MUX Master.

SW1 - 1 2 OFF OFF = Disk Port J2 Active (MUX Inactive)

OFF ON = MUX Port J3 Active (Disk port inactive)


SW2 sets the printer address.

SW2 - 1,3,5 ON only = address 215 2,3,5 ON only = address 216 1,2,3,5 ON only = address 217

### Jumpers


Pl - IN (2 pin jumper on 9579 board next to clock Yl for MFG)

# Printer/Disk Dual Controller (212-9718) 210-9579




## **386 TURBO**


## SettIngs




## 22011- SCSI CONTROLLER 212-9727 SCSI/PRINTER CONTROLLER 210-9582



## 22C11-SCSI CONTROLLER 212.9727 HIGH SPEED 1/0 PROCESSOR 210.9579





```
Partition generation:
 Part 1 make 6K.
 Part 2 make 20 K.
 Parts 3 .. n make 120 K.
ISS.000A
 330 move last stmt segment to new line 430. Add following code to end of 330.
 330 . : . : . : . : . : . : <u>: IF S3=5 THEN PRINT "C</u>S/386"
ISS.OOOM
420 A$= $PSTAT: S3=4: IF STR(A$,9,1)="V"THEN S3=3: IF STR(A$,9,1)="W"THEN S3=5
 ... leave IF S3 = tests on line 420.
 ... place 6 stmts beginning $GIO on 430.
430 $GIO/005( ...
ISS.205S line 8875 disk addresses see below
ISS.229S
           $PSTAT
7167 R9$(2)=$PSTAT(1) : IF STR(R9$(2),9,1)="W" THEN RETURN : IF STR ...
SORT.402A
line 4590 change from
4590 MI=INT(M*1024)-698
to 4590 M1=INT(MIN(M,64)*1024)-698
Enhancement to ISS utilities to check for all legal disk addresses
In "ISS.205S" Replace DEFFN '205 logic, coded on lines 8875-8915 with
8875 DEFFN'205(R,W3$,R1)
    : Q$=" "
    : IF R1<>O AND R1<>1 OR R<O OR R>15 THEN Q$="X"
    : IF W3$="340" THEN 8895
    : $TRAN(W3$,"AaBbCcDdEeFf")R
    : IF POS("DB3"=W3$)>O AND POS("123567"=STR(W3$,2))>O
                          AND VER STR(W3$,3),"H")>O THEN 8885
    : O$="I"
    : GOTO 8905
8885 IF POS("3B"=W3$)=O OR POS("123"=STR(W3$,2))=O OR STR(W3$,3)<>"O" THEN 8895
    : IF STR(W3$,,1)="3" THEN STR(W3$,3)="1"
    : STR(W3$,,1)="D"
8895 O$=" "
8905 IF R1=0 OR Q$<>" " THEN RETURN
    : SELECT #R < W3$>
    : RETURN
"KFAM107U" reported by Tom Carpenter 9/12/90. (he went back to earlier KFAM).
490 GOSUB'50(15):$UNPACK(F=HEX(A008 A003 ....6001 5003 6003 A001 A009))) ...
should be
```

490 GOSUB'50(15):\$UNPACK(F=HEX(A008 A003 ....6001 5003 <u>50</u>03 A001 A009))) ...

11.7: Lina man aina V7E immalia 4

IDEAS changes for CS/386 operation.

Problem programs in NEW format are not recognized:

IDEAS306
line 9060 AND STR(K\$(1),2,1),CO) was 80
: IF STR(K\$(1),2,1)=HEX(40) THEN 9070

PUT AN 'FP' KND OF FILE MARKEL.

VLSI CAO HANDLE THIS BUT 386 WHILL GIVE ADD ERROR.

## GBS notes: from diskette rcvd from David Thompson.

Make Configuration: TBO.1

Partition 1 5 K Term 2 Loads "GBSM"

Partition 2 21 K Term 4 Loads "STARTGBS"

Partition 3 27 K Term 2 Loads "STARTGBS"

Partition 4 8 K Term 2 Loads "@GBSM"

Partition 5 56 K Term 1 Loads "STARTGBS"

Problems in "@GENPART"

1. Device table remove /204.

On load with above configuration: Terminal 1 and 4 showed "Waiting for universal global"

- . halt/step showed waiting for "uGBS"
- . Partition status program showed error AO2 in Partition 1.

Solution: Problems in "@GENPART" Rework Configuration.

- . Assign partitions for "@GBSM" to terminal O.
- . Double memory for other partitions.

```
Partition 1 10 K Term 1 Loads "GBSM"

Partition 2 21 K Term 4 Loads "STARTGBS"

Partition 3 27 K Term 2 Loads "STARTGBS"

Partition 4 16 K Term 0 Loads "GBSM"

Partition 5 56 K Term 1 Loads "STARTGBS"
```

On load with above configuration: Terminal 1 shows Partition 5 4150 IF @Q1 GT O then 4200 ERROR P55: Undefined variable

Line 4060 is looking at @PSTAT(1) byte 9 for "M", 386 will show "W"
.looking in bytes 10 and 11 for memory less than 5K.
.... also IF Q7\$="u"THEN S\$="uGBS"
change end of line 4060 to
4060 . : .: . : S0\$,S\$=" ": IF STR(Q6\$,9,1) <> "V"THEN S0\$,S\$="GBS"
: IF Q7\$="u"THEN S\$="uGBS"

\$ DPEN TO PRINTER SEEMS TO INTERMITTENTLY DODR - UILL SEND SIN

January 26, 1993

## Bug Listing

The following is a list of Turbo bugs grouped by area of concern listed in order of importance within that group of problems. The most critical problems are noted as such on the last line of the problem to the far right. Other problems may exist. Please report any additional errors if not listed

to Mike Bahia, 2200 Product Support. · RICH KUBHNLE MIDDLESEX BACKGROUND TASKS: 45 17018 (1) A line with a DEFFN' statement may not execute any command following STEVE SHOESMITH it on the same line if in a background task. A program tape was sent to R&D - WOLFGANG BORKE to duplicate this on 8/5. 3 PARTITIONS, 2 TBLES, LOOK ER CRITICAL 011-49-231-923100 PRET 5 I SELECT GPART "KFAM" PART ' 10 DEFFN: 130: PRINT LINE LO W8 5717 SABDEY 2 5709: 60508'130 3. PRINT" LINE 30" : GOTO 50 40 PALNT" LINE 40" MOORE 22C11-HS HIGH SPEED PRINTER PORT: SO PRINT'LINE SO": STOP P2 17591 (2) The High Speed printer buffer has a 1 character overflow. If the data LARS WALKENSTROM string sent to the printer exceeds the remaining space in the buffer a hang occurs. To duplicate run the following using the HS or SCSI printer port: EQUITY, VA 10 **\$CLEAR215** MARL DEGAGNE 20 \$IFOFF/215,100: SELECT PRINT 215 MIDWEST WHOLESALE 30 PRINT "A"; (this works) or 30 PRINT "ABCDE"; (this hangs) Fools, FLAT, M. 40 B=B+1: SELECT PRINT 005 40 B=B+5: SELECT PRINT 005 RICH KUEHNLE 50 PRINT AT (2,40); "CHARACTERS SENT TO BUFFER "; B 313.744.7215/2200 DAN COLLINS 60 GOTO 20 100 SELECT PRINT 005: PRINT "PRINTER NOT READY": GOTO 20 Request R&D set buffer overflow to the printer default, 80 chars, but have it change if the line length is changed. SCSI has same problem, #30. (3) (2a) The following program checks for printer Ready and works on the SAME AS 2

old bus but not on the High Speed port.

1 DIM C9\$(16)

5 C9\$="215"

10 IF ON/215,20:ERROR GOTO 100

20 \$OPEN 100,/215:\$IF OFF/215,100: \$GIOREADPRINTERSTATUS/215,(0100 0201 1212 4000 4000 4000 4000, C9\$(2)): IF STR(C9\$(2),8,1)=HEX(10)THEN E=1: ELSE E=0: PRINT "READY": GOTO 200

100 E=-2: PRINT"NOT READY": GOTO 10

200 GOTO 10

This program works perfectly with the old bus indicating READY or NOT READY if you deselect the printer. On either the 22C11-HS or -SCSI READY is usually indicated even with no printer connected. If the program is allowed to run while the printer is deselected on either the -HS or -SCSI, within approximately 5-10 minutes the system is hung until the printer is selected. However, when the -HS hangs, NOT READY has printed one time. Never see NOT READY with the -SCSI. CRITICAL

(4) (32) A GIO sequence which works with the 386 and on the old bus to determine if the printer is READY or NOT READY if used with the 22C11-HS can cause the disk port on that board to hang or severely slow down. My configuration had a DS at 310 and a PMO10 at 215 of the same 22Cl1-HS.

P2117689 EQUITY, VA SAME AS# 2

On the disk port run the following:

10 DIM A\$(16)

20 X=INT(65023*RND(1))

TREESE 30 PRINTX

40 DATALOADBAT/D11,(X,L)A\$()

50 GOTO 20

On 2nd partition run the following: 10 Q\$=HEX(15): \$GIO(7310 0201 0300 1222

4000 4000 4000,Q\$)

20 HEXPRINT STR(Q\$,8,1)

30 IF STR(Q\$,8,1) = HEX(00)THEN 100

40 PRINT"PRINTER NOT READY"

50 GOTO 10

100 PRINT "PRINTER READY"

110 GOTO 10

If the printer is NOT READY, NOT READY is printed on the screen but disk performance slows way down. If the printer is READY and the program left running, within a few minutes the printout goes NOT READY and disk access on that board is hung. To clear the hang without powering off: a. RESET any workstation accessing that disk. b. \$CLEAR215 c. Power printer off and on. d. Send something to the print buffer. Disk should be ok. With the -SCSI printer port you always get READY, but disk performance is not affected.

5. (19) The 22C11-HS printer port will not pass the following data: HEX(0000 FFFF 0000 FFFF). Do not know the particulars of this problem. Could not duplicate on 1.18. Related to VFU code. Reported by K&R Custom S/W. K&R to retest on 1.18 and provide details if still failing.

EQUITY

6. (20) After a warm boot, \$INIT"SYSTEM", if using a printer with a  $\mathcal J$  buffer (PM017) on the 22C11-HS, will get a few garbage characters when first try to print. Appears the printer's buffer does not get cleared when using the 22Cl1-HS.

P2/17454 LARS

### MUXing DISKS:

7. (3) Intermittent I90 errors occur if using the 22C11-HS Mux port. The more terminals controllers in the Turbo the more likely the problem. Install 2 MXFs & 2 MXEs in a Turbo & use the 22Cll-HS Mux port to talk to a DS through a 2275MUX in a 2nd CPU. If try to boot through the HS Mux port will likely get I90 or hang. If system boots run the following program:

P2/17594 HONG KONG

10 DIM A\$(16)

20 X=INT(RND(1)*65000)

30DATALOADBAT/Dxx,(X,L)A\$()

40 Y=INT (RND(1)*65000)

50 DATASAVEBAT/Dxx,(Y,L)A\$():GOTO 20

8. (5) If 2 Turbos are mux'd to 2 disk drives with at least  $\bar{x}$  terminals on 61460 each system constantly accessing both drives, intermittent hangs will occur. SELECT H is OFF. This problem was duplicated with the following hardware: CS/D Turbo w/ 1 MXF, 1 2275MUX cabled to CS-D DPU Brd (310), 22Cl1-HS Mux (320): MicroVP Turbo w/1 MXF and 2 22C80s (210-7715) (addr 310 & 320) Run the following program from terminal 1 of both CPUs:

HONG KONG TOM HENDRIKS

P2/17629

DIMA\$(16)

" HOGTEST"

FIXED WITH 1.180

20 I=INT(65023*RND(1))

30 J=J+1: PRINT J

40 \$OPEN/D11: \$OPEN/D21

- 50 DATALOADBAT/D11,(I,L)A\$()
- 60 DATALOADBAT/D21,(I,L)A\$()
- 70 \$CLOSE/D11:\$CLOSE/D21

80 GOTO 20

## CRITICAL

- 9. (21) If using the 22C11-HS Mux port during a boot, the 2275MUX becomes HoN6 KoN6 locked out from all other CPU's until the booting Turbo gets @GENPART loaded. All other CPU's will hang if try to access disk connected to 2275MUX. P2
- 11. (23) If power off Turbo with 2275MUX installed, 2275MUX does not get Palinusa Howekowe properly cleared with power on. Other CPUs will hang until a RESET is keyed C9 6920 from that CPU or until the Turbo housing the 2275MUX accesses the disk connected to it.
- 10. (22) If run customer level diagnostics from screen where O/S or diagnostics is selected during boot using a 22C80 (210-7715) to a 2275MUX, other users on other CPU's using the same 2275MUX are locked out.

P2/17527 HONG KONG

### THREE BYTE ADDRESSING:

- 12. (4) For Index type 2 (3 byte), sector 0 should only have header ANDRE information in it. Index information (filenames) should start at sector 1.
- CRITICAL M2/20153 This 1 13. (6) RENAME command may corrupt disk index on a 3 byte surface. ANDRE is probably related to problem 12. CRITICAL
- 14. (37) The LOADDAT command does not work with an address beyond 16M. ANDRE With the DS an error D89 (sector address beyond end of file), with SCSI P34 P34 IF SELECT 3 OFF. SCSI (illegal value). To duplicate: Create a surface with 100000 sectors. D89 18 SEERCH 3 04.

SELECT 3 ON: SCRATCHDISK&T/Dxx,LS=255,END=99999

SELECT#1Dxx: DATASAVEDCOPENT#1,70000"3BYTEFIL"

SAVE any program in NEW format and call it "JUNK" on the same 3 byte address.

SELECT#1Dxx:LIMITST#1,"JUNK",A,B,C: PRINT A,B,C

LOADDAT(A)

- 15. (8) VERIFY does not work properly with SELECT 3 ON. Run following ~ ANDRE FELLY O CHARL LINE DA LAREN DE BEIR DISK JANG 04 YLSI & 386. program: VERIFYT/Dxx, (65534,65536) AO: PRINT AO (A0 should = 65536, it does not) P2
- 16. (13) If booting from a 3 byte surface & O/S is beyond first 16 meg, cannot boot.

## DISK RELATED:

- 44. When a program is renamed and a new program requiring more disk space  $\cdot$   $p_{g|_{20511}}$ using the old name is saved within a program, the program executes, but an error A01 (not enough memory) occurs if you try to load the program. To duplicate SAVE the following program (lines 10-40 only) as TEST, then run it.
- 10 R\$="TEST": S\$="SCRA0000"
- 20 SCRATCH T R\$: SAVE DCT () R\$: ERROR GOTO 40 · ITHTEST"
- 30 STOP "RESAVED"
- 40 SCRATCH T R\$: SAVE DCT(R\$)S\$,1: SAVE DCT (1)R\$

Comes back with STOP RESAVED. No problem yet. Now add lines:

- Run program again and system returns ':_. TEST is now resaved with 4 sectors

instead of 3 but get error A01 if try to LOAD. SCRA0000 also now exists but with just lines 10-40. On VLSI, this program properly resaves TEST the 2nd time with the additional 4 REM statements. The SCRA0000 program exists but contains no data. The 386 gives the same results as the Turbo.

- (19) (38) If a COPY is done from disk A to disk B and the last sector on B is reached, an error 198 occurs which is normal. However, address B is now hung to all other users until you key RESET from the partition that did the where the last sector such a 200 PART ACLESTED COPY. To duplicate: COPYT/D1 $\phi$ , (0,100)TOT/D1 $\chi$ , (65000) on D11 is 65024. Use any disk controller. No problem on 386 or VLSI. P2
- 17. (7) VERIFY does not work properly with the 2275. Run the following VERIFYT/Dxx, (0,0) TO 1275 DOES WHOLE DISK + 1. SEE CTO. CREF LINESS. program: VERIFYT/Dxx,(0,0)A0: PRINT A0 CARDO FIX 6)10 43 AO should = 0. It does not. P2
- (18) (17) The MOVE command causes the Catalog END to become the Current END on the output disk. The MOVE command should not change the Catalog END on the output disk and did not in the past. Move command overview The DISK INDEX P3 THE INDEX
- (42) (39) If a DS with an R4 prom is scratched with END to 65535, the END CATALOG AREA shown with LIST is 94967295. Same prob w/ SCSI. To duplicate: SCRATCHDISKT/Dxx, END=65535 LISTDCT/Dxx
- 45. The SAVE DCT (R\$)S\$,1 on line 40 in program for problem #44 should delete all lines after line 1 as it does on VLSI. On Turbo and 386 lines 10 to 40 exist in program SCRA0000.

DAN COLLINS Palinnso

P2

19A. IF YOU GET A DISK THE DISK BEFORE YOU KEY RESET THE DISIG IS HUNG & THE LED NEVER P2 17596 6000 ON

> PART TRYIN LP DCCC2. P2 17601

KEY RESET SAW PROB TOHN KNEEN IN DECEMENT ON FLAPFY

BEING READ FROM CHANGING Type IF DIFFERENT

VS OFFICE Thursday 08/06/92 08:42 am

To: Michael Riley W0000600 6FLT3

From: Michael Riley Security: Limited Subject: Turbo problems Rev.1.18 Date Received: 08/05/92

-----

### Duncan

1 6

1 4

These are the bugs I have loged in on Rev. 1.18 SCSI

- 1. When you do a list on the floppy, take out the floppy, do the list again, you still get the floppy index... (Floppy door open dose not clear cache)
- ✓ 2. SCSI controller gives wrong error code... Do a rewind of the tape drive with out tape in it will give A04 ... Should be I91...
  - 3. Can you tell the difference between door open (I98 error) and no formate on a SCSI floppy(I93 error)???? Now both is coming up with the same error...
  - 4. SELECT H needs to work like a DS... (The new cache disk drives are look good for multi CPUs SCSI...)
- $\checkmark$  5. Booting from a 512 byte/sector 1.2M floppy will hang on microcode load... It works OK on a 256 byte/sector 1.2M floppy Also it takes 4 min. to boot from a SCSI floppy and less than a min. from a
- DS floppy drive... Are you checking format each time you read from the floppy ??? If the door is never open, then the floppy is the same format!!

## O.S. are as following:

- A line with a DEFFN, statement will not exacute any other statement after the DEFFN on that line if it is in a background task...(I gave you the programs today)
- $\sqrt{4}$  2. For disk type 2, sector 0 can only have header info in it... Index info will start at sector 1 ...
  - 3. MXF printer problem... (I gave you the programs that will couse the terminal printer to add LF & CR if you SELECT PRINT 204(0).. The MXF needs to work like a MXE for 004,204,404,704 and any character with...
- $\checkmark$  4. MOVE T/Dxx TO T/Dyy... The book state that if the END is NOT stated in the MOVE statement then the END is the same as the source disk...Pg 12-58 LRM
- √ q 5. VERIFY T/Dxx (0,0)A0:print A0 ... If Dxx is a 2275 Floppy, the VERIFY failes... and dose not give a 0 for A0...
- √ ← 6. VERIFY T/Dxx (65534,65536)A0:PRINT A0... If SELECT 3 ON, you will not get
  65536 for A0...
- 7. We need the TC functions working as soon as posible !!!!Terminal to be setup in any of 3 ways: Terminal in TC or normal mode, 10 or 11 bit protocall, 2200 or XON/XOFF flow control...
- 8. PRINT AT for the MXF will not print on the correct line... Program:
  10 PRINT AT (21,0); HEX(0A 0A 0E); "TEST"
  10 PRINT AT (21,0); HEX(0A 0A); "TEST"
  Run this program on a on a MXF and a MXE on the Turbo...
- √ 7 9. Printing from a 22C11 HS... you are printing HEX(0000 FFFF 0000 FFFF) to
  the HS printer, The controller will not pass this data...
- J 10.REM % ... If you have a character of Hex(7D or 7E) after a REM% then it jumps to the next line...
  - 11.SELECT H ON... If you have a Part. doing a 10 \$OPEN T/D21:DATA LOAD BA ...: \$CLOSE T/D21: GOTO 10 and on another terminal you do a LISTDCT/D21... The LIST will hang the The DATA LOAD program... The Part doing the DATA LOAD has

SELECT H ON...The Part with the LIST has it OFF... I would think the DATA LOAD Prigram would take priority...

- 12.LISTS & LISTSD dose not line feed when it is sent to a printer using a Printer driver ....LIST a program using LISTSD... You only get one page and can not get any more...
- 13.On power up of a HS controller.. If a printer is connected to the HS on power up the HS will pass garbage to the printer that dose not get cleared out...
- 14. RENAME and 3 byte addressing.... On a Type 2 platter... RENAME a program or a DATA FILE (like @MVP or 22C11HS) that is grater than 2 bytes... It over write other index files...

### **PROMs**

- The SCSI burn in test is setup for a 2275, It needs to be setup for a PC printer.. Like a Epson 80 printer...The 22C11HS works OK ... Also change the PROM micro code Rev. number... It is the same as 22C11HS...
- 2. SCSI PROMs Floppy... If you are doing a inquire to see what is on the SCSI bus ... You do not need to check the different types of formats...This couses the configuration program to take a long time to get status and power up to get to GENPART...

This is all that I can think if today... I know that I am missing some.. Michael Riley

10 INPUT CURSOR

A\$: A=A+1: PRINT

AT(10,12); A: GOTO

40

```
SPECIFIC COMMAND RELATED:
          (20) (9) If a REM% command is followed by a HEX 7D or 7E, other commands
                                                                                            P2/17460
      on the same line following it will be ignored. This is fixed on rel 1.18Q. Pl
                                                                                             LAD BUZ GAPAL
           21. (15) The INPUT CURSOR command intermittently hangs. Run following
      program from a 2536DW terminal. This command is not valid on older terminals.
                                                                                             P2 17455
      10 DIMA$3
                                        "INPCURSE"
                                                                                            SWEPEN
      20 PRINTHEX(0306):A=0
      30 PRINT AT (5,1); HEX(02 05 OF)
      40 INPUT CURSOR A$: A=A+1: PRINT AT (10,12); A:GOTO30
      Program will intermittently hang within 5 minutes.
                                                                              P2
          (23) (27) SELECT NEW defaults to OLD after CLEAR or LOAD RUN.
                                                                                           P2 17599
                                                                            Should only
      change by re-entering the SELECT command.
           22. (25) LISTS & LISTSD do not work correctly to a system or terminal
                                                                                          P2 17453 LAR
      printer. If printer requires a printer driver it will not linefeed. If
      printout should take more than 1 screen, 2nd screen does not occur.
      duplicate LOAD @GENPART and do a SELECT PRINT 215 or 204 using a PM017 printer
      with driver installed. Do a LISTS or LISTSD. No problem on 386.
           (24) (29) If do a PRINT 1+1+1+1+1 etc when get to 87th + 1 blows O/S.
                                                                                          P2/17416
      Should give an error and not blow O/S.
      SELECT H:
                                                                                         P2117451
           25. (10) If 2 partitions are constantly accessing same DS, 1 with SELECT
OLD BUS
                                                                                             HONG KONG
SAME ADOR H ON, the partition using SELECT H ON will hang until the 2nd partition
off thishes. Must use 22Cll-HS. Run following programs:
                                                                         45/93 TESTED W 1.181, NO 22411-45
امريم ع<sup>94</sup>partition 1
                                                                           BETTER. 2 SYSTEMS MUSED.
4EU BUS 10 SELECT H ON: $OPEN/D11: DIM A$(16): X=INT(RND(1)*30000):
                                                                         SYS 1 2 TERMS W! SEL HOFF- GOTS
OFF DA DATALOADBAT/D11, (X,L)A$():PRINT X;:$CLOSE:GOTO 10
                                                                               2 TERMS W/ SEC HON- WATTING
      partition 2

SYS 2 : SEC HIER SCUENCE ACCESS

10DIMA$(16): X=INT(RND(1)*30000):DATALOADBAT/D12,(X,L)A$(): PRINT X;: GOTO 10/ GETTING EQUALTIME
1000 ¢ partition 2
                                                                                           COTTING EQUALTIME
           DS TAPE UTLITTE, HUNG WY BACKBROUND TASK RUNNING & SELECT H ON
                                                                                        TOM REESE
                                                                                          KURS/W VA
      MXF:
                                                                                          BABYFARE
                                                                                          ED MACHIOCHI
           26. (16) MXF Octopus ports will not give a DTR indication to a modem.
                                                                                          STEVE SHOES MITH
      Therefore they will not support a remote terminal. Ports 1 and 2 are OK. P1
           46. If RESET is keyed during a GIO/005 command to an MXF port,
      intermittently subsequent GIO commands will no longer execute or will hang the
                                                                                          GERMANY
      port. Must reboot to correct. Problem is more persistent with ports 2-16.
                                                                                            ALEC46
      Use the following program to duplicate:
      10 DIM Q$104, I$(24)80: PRINT HEX(03 06)
      20 Q$=ALL(09): STR(q$,1,24)=ALL(0A): STR(Q$,25,1)=HEX(00)
      30 FOR A=1 TO 24: I$(A)="This is a test
                                                   line
                                                                 , please press RESET":
      CONVERT A-1 TO STR(I$(A),27,2),(##): NEXT A
      40 FOR A=1 TO 23: STR(I$(A),79,2)=HEX(OD OA): NEXT A
      50 P$=HEX(40 01 A2 00 1A 00 A2 00)
      60 $GIO/005 (P$)Q$ 25,1 ;I$()
                                          (less than sign after Q$, grter than after 1)
      70 GOTO 60
      Run program & 1st time ok. Key RESET and run again, and repeat until fails. P1
           (27.) (18) The PRINT AT command does not position properly with the MXF in
                                                                                          P2/17600
      some cases. Run the following examples on the MXF then on the MXE to compare:
                                                                                          RADER
      Example 1: 10PRINT AT (21,0,);HEX(0A 0A);"TEST"
                                                             (fails on lines 5 & up)
                                                                                          (PRTAT) D31 SCS1
      Example 2: PRINT AT(10,0,);HEX(0A);"TEST"
                                                             (fails on line 10 only)
      In either example, if the HEX(OA) or the last comma within () is removed the
      problem will likely not occur.
           28. (24) Need MXF TC functions to work. Should have the following
                                                                                       ED MACHIOCHI
      functions: Terminal in TC or normal mode, 10 or 11 bit protocol, XON/XOFF
                                                                                       STEVE SHOESMITH
      flow control.
                                                                              P3
                                                                                       GAMTTOD MIL
                                                                                       LIM SIMPSON
      MXF-CAMMAND
```

EQUITY

SEEKS

545TEM 1 1200

### OTHER:

29. (new) CPU intensive processes can be severely impacted when upgrading from Turbo O/S 1.1 to O/S 1.18 when running at the same time as certain disk processes. This problem was duplicated as follows: Partition 16 terminals and 16 partitions on 1 MXF with 100K memory. Setup 4 terminals to run the 2200 Instruction Exerciser test, "INSTROC", and 4 running "CPUDEMO1". With just these CPU intensive tasks there is not too much difference:

CHI/BAIG BUNN COFFEE BRY CITY METALS BROYFARE?

1.1

CPU Benchmark 14-19 seconds/pass 17-20 seconds/pass Instruction Test 7 min 20 sec/pass approx 8 min 40 sec/pass

Rerun the same test w/ 1 additional W/S running the Disk Benchmark, "BMDIO1P1":

1.1

1.18

CPU Benchmark 16-19 seconds 39-66 seconds/pass
Instruction Test 8 min 27 seconds/pass 21 min 15 seconds/pass
Disk Benchmark 3 min 17 seconds/pass 24-36 seconds/pass
For disk I/O the CS/D DPU Board was used with an internal 140 Meg drive. As can be seen CPU intensive processes seem to have priority on 1.1 where disk I/O seems to have priority on 1.18. The best solution may be if this balance could be set by the customer to best meet their specific needs. Otherwise a better balance is needed.

CRITICAL

- 47. If using the Make a Reference List of File Names Utility (Moving a Selected List of Files on newer releases) and after selecting your files, option 4 is used to save the list in a program file, an error AO2 occurs on line 30, which is a COM statement. No problem on 386 or VLSI. P2
- 48. If using 2 22C11-HS Controllers, the 2nd 22C11-HS always fails the 'System Interface Card Test on the first pass only. To duplicate install 2 22C11-HS Controllers using addr's 310 and 330. On boot select diags instead of O/S. First pass only of the 'System Interface Card Test' will fail. P3
- 29a. (36) If booting from a MXE or MXD and SHIFT/RESET is keyed to bypass the boot diagnostics, you must release the SHIFT key and press it again to get RESET to work with 'Mount System Platter, Press Reset'. You do not have to release the SHIFT key with the MXF board.

  P3
  49. EXTERNAL DS BACKER SWELL WITH 22CII-NS

P8 26512

SCSI: #0920 COMMAND RETURNS ISH CONSISTENTIAN WITH THE GEST CONTROLLER. SELECT H WAS ON

30. (41) The SCSI printer port has a 1 character overflow. This can cause a hang. Same as problem 2 under 22C11-HS Printer Port. CRITICAL

31. (41a) A program to check for printer READY can hang system. Same as problem 3 under 22C11-HS Printer Port. CRITICAL

- 32. (33) A GIO sequence to determine if the printer is READY or NOT READY always comes back READY on the SCSI printer port. Use program from bug #4 under 22Cl1-HS High Speed Printer port. This sequence works properly on the old bus and with the 386.
- 33. (11) SCSI floppy fails on verify with a 1.2M diskette starting at sector 2400. Sector 2398 appears to be the last usable sector. Any attempt to go beyond 2400 with any disk command will cause an error or hang. This is why booting from SCSI floppy with a 512 byte/sector disk was failing. P1
- 34. (12) Turbo does not recognize SCSI floppy door open. If LIST a floppy, remove diskette & LIST 2nd floppy, system reads data from 1st diskette still in CACHE.
- 38. (30) SCSI burn-in test does not print out the same on printer port as 22C11-HS printer port if use printer that requires print driver. SCSI printer port is not issuing linefeed & lines overprint. Best answer would be to be able to select issue of linefeed, otherwise both should be the same. Test with same printer with both the 22C11-HS & then with SCSI printer port. Pl
- 35. (14) Booting from SCSI floppy is extremely slow, 4 minutes compared with 52 seconds with DS floppy. Getting the SCSI config program loaded is also extremely slow if a SCSI floppy door is open. It took 5 seconds to pull up the inquiry screen with the door closed, 66 seconds with the door open. P2

107 965 PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS PRILLS P

PAIT LOT LOCAL 165 MARE

> P2/17548 LOCAL 205 BLEC

- 36. (26) SCSI Controller should return T errors using the Tape drive as the DS tape does. If rewind tape with no tape installed SCSI gives A04. Should give a T10. Other Tape problems should also give correct T error, not an Axx error.
- 41. (35) Intermittently if booting with some MXE boards, the system may hang while loading @MVP. These boards work perfectly otherwise. Additional info: while loading the O/S the MXE self-test LED comes on. When the boot is successful, the LED goes out in about a second. If the LED stays on, the boot fails.
- 39. (31) No way at present time to check SCSI tape, 150M, to see if write-protected. If tape is write-protected and try to write, system should return correct error, T12.
- 37. (28) SCSI floppy returns same error if door open or disk not formatted. Door open should give I98. Disk not formatted, I93. P3
- 40. (34) Cannot boot from SCSI using an MXD board. Screen usually goes blank when key SF or will hang with message, 'Loading O/S'. RESET gets you back to Mount System Platter.
- 42. (39) If a SCSI address is scratched with END to 65535, the END CATALOG AREA shown with LIST is 94967295. To duplicate: SCRATCHDISKT/Dxx,END=65535
  LISTDCT/Dxx
- 43. (40) If do a VERIFYT/Dxx,(0,65023) to a SCSI address with the last sector equal to 65023, an error will be returned (Error in Sector 65024). P3

  BEING ACCESSED WHEN TRY TO FORMAT A DIFFERENT SEE ADDRESS, GET MISSAGE

  DRIVE ALREADY IN USE. ON 386 UTILITY HANGS.

0109D

VS OFFICE

CC:

Mike Bahia

W0000600 6FLT3

From:

Mike Bahia

Security: Date Received: 09/09/92

Limited

Subject: Are you still there?

### Duncan,

Thanks for replying. Hope you and your group remain together. Talked with Mike Riley yesterday. He indicated the Wang subsidiary you are working for may be closing and was not sure how that may affect you. They better take care of you guys. Please keep me informed.

The following is a list of Turbo bugs as I know them. It is possible Riley may have reported some I am not aware of but I do have some of his notes:

### MOST CRITICAL:

(1) A line with a DEFFN' statement will not execute any other command on that line if in a background task. Mike Riley sent you a program to duplicate this on 8/5. Let me know if I need to resend.

(2) The High Speed printer buffer has a 1 character overflow. If the data string sent to the printer exceeds the remaining space in the buffer a hang occurs. Need to monitor the printer Ready not the buffer Ready. Also should be able to set the buffer overflow to the line length. 80 characters should be the default but it should change if the line length is changed. following programchecks for printer Ready and works on the old bus but not on the High Speed port.

1 DIM C9\$ (16)

5 C9\$="215"

10 IF ON/215,20:ERROR GOTO 100

20 \$OPEN 1.00, /21.5:\$IF OFF/215,100: \$GIOREADPRINTERSTATUS/215, (0100 0201 1212 4000 4000 4000 4000, C9\$(2)): IF STR(C9\$(2),8,1)=HEX(10)THEN E=1: ELSE E=0:

PRINT "READY": GOTO 200

100 E=-2: PRINT"NOT READY": GOTO 10

200 GOTO 10

This program works perfectly with the old bus indicating READY or NOT READY if you deselect the printer. On the HIGH Speed port the printer is ignored and the High Speed buffer is checked. Again we also need to correct the buffer overflow to be equal to the selected line length, 80 being the default.

(3) Intermittent 190 errors if use the 22C11-HS Mux port. The more terminals controllers in the Turbo the more likely the problem. Install 2 MXFs & 2 MXEs in a Turbo & use the 22C11-HS Mux port to talk to a DS through a 2275MUX in a 2nd CPU. If try to boot through the HS Mux port will likely get I90 or hang. If boots run the following program:

10 DIM A\$ (16)

20 X=INT (RND (1) *65000)

30DATALOADBAT/Dxx, (X, L) A\$ ()

40 Y=INT (RND(1)*65000)

50 DATASAVEBAT/Dxx, (Y,L)A\$():GOTO 20

(4) For Index type 2 (3 byte), sector 0 should only have header info in it. Index info (filenames) should start at sector 1.

(5) If 2 Turbos are mux'd to 2 disk drives with at least 1 terminal on each system constantly accessing both drives, intermittent hangs will occur. Sent you this problem through office on 8/27 with program to duplicate. SELECT H is OFF.

54646 3 ALEL GMBH WOLFGANG BURKE 011 49 231 923100

2 17591 EQUITY

MIDWEST WHOLE ALL FOODS FULL M:

RICH KUCHALE 313.744.7215 2200

DAN CILLINS

P2117594

ANDEC BAXI

P2 17629

HONG KONG

• 6) RENAME command may corrupt disk index on a 3 byte surface. This is probably related to problem 4.

VERIFY does not work properly with the 2275. Run the following program: VERIFYT/Dxx, (0,0)A0: PRINT A0 A0 should = 0. It does not.

• (8) VERIFY does not work properly with SELECT 3 ON. Run following program: VERIFYT/Dxx, (65534,65536) A0: PRINT A0 A0 should = 65536. It does not.

9) If a REM% command is followed by a HEX 7D or 7E, other commands on the same line following it will be ignored. This is fixed on the 1.18Q sent to Hong Kong which they forwarded to me to test.

Other bugs basically in order of importance:

10. If 2 partitions are constantly accessing same DS, 1 with SELECT H ON, the partition using SELECT H ON will hang until the 2nd partition finishes. Must use 22C11-HS. Run following programs:

partition 1

10 SELECT H ON: \$OPEN/D11: DIM A\$ (16): X=INT (RND (1) *30000):

DATALOADBAT/D11, (X,L) A\$ ():PRINT X;:\$CLOSE:GOTO 10

partition 2

10DIMA\$(16): X=INT(RND(1)*30000):DATALOADBAT/D12,(X,L)A\$(): PRINT X;: GOTO 10

[II] If boot from a SCSI floppy formatted in 512 byte /sector, will hang on

12. Turbo does not recognize SCSI floppy door open. If LIST a floppy, remove diskette & LIST 2nd floppy, system readsdata from 1st diskette still in CACHE.

13) If booting from a 3 byte surface & O/S is beyond first 16 meg, cannot boot.

14 Booting from SCSI floppy is extremely slow, 4 minutes compared with 52 seconds with DS floppy. Getting the SCSI config program loaded is also extremely slow if a SCSI floppy is involved. Can we improve this?

15) The INPUT CURSOR command intermittently hangs. Run following program from a 2536DW terminal. This command is not valid on older terminals.

10 DIMA\$3

20 PRINTHEX (0306) :A=0

30 PRINT AT (5,1); HEX(02 05 0F)

40 INPUT CURSOR A\$: A=A+1: PRINT AT (10,12); A:GOTO30

Program will intermittently hang within 5 minutes.

• 16 MKF Octopus ports will not give a DTR indication to a modem. Therefore they will not support a remote terminal. Ports 1 and 2 are OK.

17) The MOVE command causes the Catalog END to become the Current END on the output disk. The MOVE command should not change the Catalog END on the output disk and did not in the past.

(18) The PRINT AT command does not position properly with the MXF in some cases. Run the following program on the MXF then on the MXE to compare: 10PRINT AT (21,0); HEX(0A 0A); "TEST"

 This was reported by Mike Riley. The 22C11-HS printer port will not pass the following data: HEX(0000 FFFF 0000 FFFF)
 Have not tested this myself.

20 After a warm boot, \$INIT"SYSTEM", if using a printer with a buffer (PM017) on the 22C11-HS, will get a few garbage characters when first try to print.

Appears the printer's buffer does not get cleared with 22C11-HS.

Other open issues:

ANDRE

P2/17596

Andre

P2/17460 1.18Q

P2/17451

P2 17595
LOCAL 205
RAEL
P2 17607
LOCAL 205
TOARK
ANDRO

P2/17598 . LOCAL 203 ALEC

P2/17455

ED MACHIOCINI

P2/17601
ANDRE
JOHN KNEEN (BAY CITY METAL)
P2/17600
RADGR

EQUITY

P2/17454

21) If using the 22C11-HS Mux port during a boot, the 2275MUX becomes locked out from all other CPU's until the booting Turbo gets @GENPART loaded. All other CPU's will hang if try to access disk connected to 2275MUX.

22) If run customer level diagnostics from screen where O/S or diagnostics is selected during boot using a 22C80 (210-7715) to a 2275MUX, other users on other CPU's are locked out.

- 23 If power off Turbo with 2275MUX installed, 2275MUX does not get properly cleared with power on. Other CPUs will hang until a RESET is keyed from that CPU or until the Turbo housing the 2275MUX accesses the disk connected to it.
- 24 Need MXF TC functions to work. According to note from Riley we need port able to setup in 3 ways: Terminal in TC or normal mode, 10 or 11 bit protocol, XON/XOFF flow control.
  - LISTS & LISTSD do not work correctly to a system or terminal printer. If printer requires a printer driver it will not linefeed. If printout should take more than 1 screen, 2nd screen does not occur. To duplicate LOAD @GENPART and do a SELECT PRINT 215 or 204 using a PM017 printer with driver installed. Do a LISTS or LISTSD. No problem on 386.
- does. If rewind tape with no tape installed SCSI gives A04. Should give a T10. Other Tape problems should also give correct T error, not an Axx error.
- SELECT NEW defaults to OLD after CLEAR or LOAD RUN. Should only change by re-entering the SELECT command.
- 28 SCSI floppy returns same error if door open or disk not formatted per Riley. Door open should give I98. Disk not formatted I93.
- 29 If do a PRINT 1+1+1+1+1 etc when get to 87th + 1 blows O/S. Should give an error and not blow O/S.

SCSI prom bug:

• 30 SCSI burn-in test does not print out the same on printer port as 22C11-HS printer port if use printer that requires print driver. SCSI printer port is not issuing linefeed & lines overprint. Best answer would be to be able to select issue of linefeed, otherwise both should be the same. Test with same printer with both the 22C11-HS & then with SCSI printer port.

Hope these are clear. If you need further detail please let me know.

Best regards,

Mike

----- Reply -----

To: Mike Bahia From: Duncan Chou Subject: Are you still there? Date Sent: 09/07/92

Mike,

Give me the bugs listing on curent Turbo O.S. and I will testing that by using my newest O.S. and then send it to you include SCSI microcode.

Regards Duncan Chou

----- Original Memo -----

To: Duncan Chou From: Mike Bahia

HONG KONG

P2/17527

P2/17452

STEVE S JIM D JIM SIMPSON EQUITY

P2 17453

P2/17599